LV7-IZVJESTAJ

5. U ovom zadatku, svakim pritiskom na taster, dolazi do povecanja duty cycle(k). Kada je k=100,

vracamo ga na 0 I pocinjemo ispocetka. #!/usr/bin/python3 import RPi.GPIO as GPIO import time GPIO.setmode(GPIO.BOARD) GPIO.setwarnings(False) GPIO.setup(3,GPIO.OUT) GPIO.setup(5,GPIO.OUT) GPIO.setup(7,GPIO.OUT) m=GPIO.PWM(3,500) GPIO.output(5,1) GPIO.output(7,1) GPIO.setup(11,GPIO.IN) k=0 m.start(0) while 1==1: if GPIO.input(11): k=k+10

if k>100:

time.sleep(1)

m.ChangeDutyCycle(k)

k=0