



			J_POW_IN		
_	5V	1	\Box		
	3V3	2	וצו		
	GND	3	⊏≍∣		
			ho		
			CONN-SIL3		

PORTA	PORTB	PORTC	PORTD
999999		999999	999999
- 0 E 4 G O	- 0 ε 4 c o	T 7 8 4 5 0	T 7 8 4 9 9
PA1 PA2 PA3 GND	PB1 PB3 GND GND	PC2 PC3 GND	PD1 PD2 PD3 GND

