## Br Element Reference



P)	Legend Not connected
	Raw +5V

Bar	ık A

R 48 45 42 39 36 33 30 27 G 49 46 43 40 37 34 31 28

9 12 15 18 21 24 8 11 14 17 20 23

Bank C

G 49 46 43 40 37 34 31 28 48 45 42 39 36 33 30 27

8 11 14 17 20 23

+V 48 45 42 39 36 33 30 27 G 49 46 43 40 37 34 31 28 3 6 9 12 15 18 21 24

2 5 8 11 14 17 20 23

Bank D

Bank B

G 49 46 43 40 37 34 31 28 48 45 42 39 36 33 30 27

5 8 11 14 17 20 23 G

6 9 12 15 18 21 24

Analog Input Analog Supply

Differential IC

Special Function

## Special Function Mapping

Au

Analog 1.8V 17

18 Analog 1.8V Analog Gnd 33

Analog Reference 34

**VBSEL\*** 20 1.8V

\*Controls dual voltage IO levels Leave floating for 3.3V IO Connect to 1.8V for 1.8V IO

Cu Au

**USB Tx** 14 **USB Tx** USB Rx 15 USB Rx

MISO 23 TDI MOSI 24 TDO

27 **TCK** SCK

SS **TMS** 28

Config Reset Program 36 37 Done Done

> Reset 39 Reset

100MHz Clock 40 100Mhz Clock