

Henry Brothers Test Project

32 Eldon Road,
Nottingham,
United Kingdom NG9 6DZ

1 - Hotworks Permit

Details	
Project	Henry Brothers Test Project
Organization	Henry Brothers
Location	Henry Brothers Test Project
Status	Open
Due Date	
Created by	Nicole Millinship on Wednesday 08 January, 2025, 9:28:21 PM
Modified by	Nicole Millinship on Wednesday 08 January, 2025, 10:28:20 PM
Downloaded	Wednesday 08 January, 2025, 10:58:23 PM
Template	Hotworks Permit
Description	AMENDED NM RM
Progress	89%

Question	Response
TEXT BOX ADDED COVERING RULES OF ISSUE.	
1 Company * Hold Point	Company A
2 Supervisor in charge of the works * Hold Point	Anthony Apple
3 Work Description * Hold Point	Lorem ipsum dolor sit amet, consectetur adipiscing elit, sed do eiusmod tempor incididunt ut labore et dolore magna aliqua.
4 Work location * Hold Point	Building A Ground Floor

1 - Hotworks Permit

5		HBT-RAMS-0002
RAMS Reference as per Aconex document register * Hold Point		
6	Date * Hold Point	Wednesday 08 January, 2025
7	Time Permit opened * Hold Point	12pm
8	Time permit closed by * Hold Point	5pm
KEY REMINDERS WHEN PLANNING HOT WORK ACTIVITIES. (PLEASE SIGN TO CONFIRM EACH OF THE KEY REMINDERS BELOW HAVE BEEN CONSIDERED)		
9	Is hot work equipment suitable for use and in good order (Check CP7 Certification)? * Hold Point	Yes
10	(1) Activities covered by this Permit are those where there is the application of heat involving a naked flame open heat source or hot air paint strippers, grinding wheels, angle grinders, disc cutters or gas space heaters etc*. * Hold Point	Acknowledged by supervisor named in item 2
11	(2) The area of work must be cleared of combustible materials for a safe distance from or beneath the place where such work is being carried out. This distance shall not be less than 15 metres when welding or cutting operations are carried out. * Hold Point	Acknowledged by supervisor named in item 2

1 - Hotworks Permit

12	Acknowledged by supervisor named in item 2
(3) Where such precautions (as above) are impractical such material will be covered with non-combustible blankets or screens. Combustible parts of premises will be similarly protected. *	
Hold Point	
13	Acknowledged by supervisor named in item 2
(4) At least two fire extinguishers (self supplied) of a type and capacity suitable for the combustible material and the premises should be kept immediately adjacent to the area of work in full working order and available for immediate use. *	
Hold Point	
14	Acknowledged by supervisor named in item 2
(5) Notwithstanding the requirements placed on HG by client's safety rules and procedures a thorough examination for any signs of combustion should be made within or below the area in which work has been undertaken IMMEDIATELY AFTER WORKS HAVE CEASED *	
Hold Point	
15	Acknowledged by supervisor named in item 2
(6) Notwithstanding the requirements placed on Henry Group by client's safety rules and procedures a thorough examination for any signs of combustion should be made within or below the area in which work has been undertaken AFTER 30 MINUTES *	
Hold Point	
16	Acknowledged by supervisor named in item 2
(7) Notwithstanding the requirements placed on HG by Client's safety rules and procedures a thorough examination for any signs of combustion should be made within or below the area in which work has been undertaken AT THE 1 HOUR POINT (TOTAL 1 HOUR) *	
Hold Point	

1 - Hotworks Permit

17 (8) A thorough examination for any signs of combustion should be made within or below the area in which work has been undertaken FOLLOWING THE TERMINATION OF EACH PERIOD OF WORK * Hold Point	Acknowledged by supervisor named in item 2
18 (9) Equipment will be lit as short a time as possible before use and extinguished immediately after use. Any equipment which is lit or switched on must not be left unattended. * Hold Point	Acknowledged by supervisor named in item 2
19 (10) Permits should be issued for each hot work activity, for the maximum of one working day and MUST be fully closed out. * Hold Point	Acknowledged by supervisor named in item 2
20 (11) Has the likely impact on any existing client fire protection or detection systems e.g. smoke alarms been checked? * Hold Point	Acknowledged by supervisor named in item 2
FIRE WATCH OBSERVERS:-	
21 Based on an assessment of the fire risk, does the named Supervisor in Charge of the Works as noted above, believe that an Observer is required to provide oversight of the hot works being undertaken by consent of this Permit? Do you acknowledge that the observer is to watch for signs of smoke or smouldering flames during the hot works?	No

1 - Hotworks Permit

22

Fire Watcher Signature. As the Fire Watcher, I acknowledge my responsibilities to watch for signs of smoke or smouldering flames during the duration of the hot works and two hours after the works are completed

ACCEPTANCE (SIGNED BY THE SUPERVISOR IN CHARGE OF THE HOT WORKS):-

23

Supervisor of Works: I hereby declare that I accept responsibility for carrying out the work detailed and that no attempt will be made by me, nor by any person under my control, to carry out work which does not follow the procedures set out above. *

Hold Point

A. Apple

Anthony Apple
Wednesday 08 January, 2025

24 Fire watch start signature (if applicable)

CLEARANCE (SIGNED BY THE SUPERVISOR IN CHARGE OF THE HOT WORKS):-

25

I hereby declare that the hot works have been successfully completed and that I have checked the area for the risk of fire immediately after the works have ceased. We will now commence our 1 hour fire watch *

Hold Point

A. Apple

Anthony Apple
Wednesday 08 January, 2025

26

I hereby declare that I have completed the 1 hour fire watch (if applicable)

1 - Hotworks Permit

27

A Apple

Anthony Apple
Wednesday 08 January, 2025

I hereby declare that any fire detection and protection systems have been reactivated where required. *

Hold Point

VERIFICATION | PERMIT CLOSE OUT (SIGNED BY HENRY GROUP MANAGEMENT) :-

28

NM

Nicole Millinship
Wednesday 08 January, 2025

I hereby declare that the hot works have been successfully completed and that I have checked the area for the risk of fire, 1 HOUR AFTER THE COMPLETION OF THE HOT WORKS I hereby declare that any fire detection and protection systems have been reactivated where required. *

Hold Point

Name

Signature

Date