FIRMWARE UPDATE

**1** TURN **OFF** THE CLOCK

2 CONNECT USB CABLE

3 UPLOAD NEW CODE

4 DISCONNECT USB CABLE

5 TURN **ON** THE CLOCK