# Minibadge Holder Build Instructions

Bottom

This sets the address for the board. If this is the first board set as **ZERO**

SPI only works on the top row of minibadges on the first board in the chain

Circles at top Left Corner

If not using chips, solder together each jumper under U2

Only I2C and power are passed down the chain

Top

16 Header and make sure they are straight

Notches DOWN