




- 2. component
- 3. solder
- 4. outline
- 5. componentmask
- 6. soldermask
- 7. plated-drill
- 8. unplated-drill
- 9. topsilk
- 10. bottomsilk
- 11. bottompaste
- 12. toppaste
- 13. topassembly
- 14. bottomassembly
- 15. fab






























There are 14 different drill sizes used in this layout, 705 holes total

```
Symbol Diam.(Inch) Count Plated?
        0.013
                   152
                           YES
        0.014
                   50
                           YES
                   10
                           YES
        0.016
        0.019
                   31
                           YES
267
                           YES
        0.020
φ
        0.030
                   4
                           YES
#
        0.038
                   18
                           YES
Ø
        0.039
                   8
                           YES
0
        0.041
                   2
                           YES
0.042
                           YES
                   150
$
        0.062
                           YES
                                         Title: (unknown) - Fabrication Drawing
曲
        0.066
                           YES
                                         Author: Mark A. Haun
0.094
                           YES
                                         Date: Mon 12 Dec 2011 01:00:47 AM GMT UTC
0
        0.130
                            NO
```



Board outline is the centerline of this path