

Tel: 020 8810 9393 Fax: 020 8810 9333

Estimate Print

Printed on 31 October 2019 by GENERAL

Job Number 18231 Source System AUDAX **Pool Number** 0 Claims Ref. **TBA**

Estimate ID AUK08360

Contact Details

VIRTUO

Registration LL19ZND

Engineer

Estimator PT 2

Make MERCEDES-BENZ

Model GLA 200

Trim

Chassis No. **Engine No.**

Vin No. WDC1569432J622344

Radio Code

Mileage 12,930

Creation Date 31 October 2019

Vehicle Colour BLACK

Work Provider UNITED REPAIR SOLUTIONS LIMITED

Strip & Refit	Qtv	Unit	Ext	MET	Panel	Paint	Allow	Total
·		Price	Price					
R + R LEFT MIRROR	1	-	-	0.30	-	-	-	0.30
R + R REAR BUMPER	1	-	-	0.90	-	-	-	0.90
R + R LEFT REAR DOOR	1	-	-	0.60	-	-	-	0.60
R + R L/R DOOR MODULE	1	-	-	0.90	-	-	-	0.90
R + R L/WAIST MOULDING	1	-	-	0.30	-	-	-	0.30
R + R L/OUTER REAR LAMP	1	-	-	0.20	-	-	-	0.20
R + R BATTERY EARTH CABLE	1	-	-	0.20	-	-	-	0.20
R + R L/R SIDE PANEL TRIM	1	-	-	0.30	-	-	-	0.30
R + R L/REAR CRANK WINDOW	1	-	-	0.30	-	-	-	0.30
R + R LEFT REAR DOOR TRIM	1	-	-	0.30	-	-	-	0.30
R + R LEFT FRONT DOOR TRIM	1	-	-	0.40	-	-	-	0.40
REMOVE&REFIT 2 MAN ALLOWANCE	1	-	-	0.40	-	-	-	0.40
R + R REAR LOWER BUMPER COVER	1	-	-	0.30	-	-	-	0.30
R + R REAR PARKTRONIC SENSOR/S	1	-	-	0.30	-	-	-	0.30
R + R LEFT REAR WHEELHOUSE SHELL	1	-	-	0.30	-	-	-	0.30
R + R LEFT FRONT OUTER DOOR HANDLE	1	-	-	0.20	-	-	-	0.20
REMOVE AND REFIT REAR LOWER BUMPER	1	-	-	0.30	-	-	-	0.30
R + R L/R DOOR MOULDING (WINDOW LINE)	1	-	-	0.20	-	-	-	0.20
Repair	Qty	Unit	Ext	MET	Panel	Paint	Allow	Total
Repair	Qtv	Unit Price	Ext Price			Paint		
REPAIR L/R DOOR	Qtv	~		MET	6.00	Paint -	Allow	6.00
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER	1	~		- -	6.00	Paint -	- -	6.00
REPAIR L/R DOOR	Qtv 1 1 1	~			6.00	Paint - -		6.00
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS	1	~		- -	6.00	Paint -	- -	6.00
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint	1 1 1 Qtv	Price - -	Price - -	- - -	6.00 1.00 0.20 Panel	Paint	Allow	6.00 1.00 0.20
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20	- - -	- - -	6.00 1.00 0.20
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	- - - Paint	Allow	6.00 1.00 0.20 Total 0.50
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 - 0.50	Allow	6.00 1.00 0.20 Total 0.50
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	- - - Paint 0.50 - 0.50 0.30	Allow	6.00 1.00 0.20 Total 0.50 - 0.50 0.30
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 - 0.50 0.30 0.60	Allow	6.00 1.00 0.20 Total 0.50 - 0.50 0.30 0.60
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel		Allow	6.00 1.00 0.20 Total 0.50 - 0.50 0.30 0.60 1.20
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III TOW EYE COVER SURFACE PAINT	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 0.50 0.30 0.60 1.20 0.20	Allow	6.00 1.00 0.20 Total 0.50 - 0.50 0.30 0.60 1.20 0.20
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 0.50 0.30 0.60 1.20 0.20 0.10	Allow	6.00 1.00 0.20 Total 0.50 - 0.50 0.30 0.60 1.20 0.20 0.10
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III TOW EYE COVER SURFACE PAINT	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 0.50 0.50 0.30 0.60 1.20 0.20 0.10 0.10	- - - - - - - - - -	6.00 1.00 0.20 Total 0.50 0.30 0.60 1.20 0.20 0.10
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III TOW EYE COVER SURFACE PAINT L/F DOOR OUT HANDLE PAINTING L/R DOOR OUT HANDLE PAINTING L/R SIDE PANEL PAINTING STAGE III	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	0.50 0.50 0.50 0.30 0.60 1.20 0.20 0.10 1.40	- - - - - - - - - - -	6.00 1.00 0.20 Total 0.50 - 0.50 0.30 0.60 1.20 0.20 0.10
REPAIR L/R DOOR REPAIR REAR UPPER BUMPER REPAIR/APPLY FILLER ON PLAST/METAL PARTS Paint DE NIB SURFACE PAINT OF FITTED BODY PARTS MASK GLASS SURFACE PAINT PRIME PLASTIC/METAL PARTS REAR UPPER BUMPER PAINTING L/R DOOR PAINTING STAGE III TOW EYE COVER SURFACE PAINT L/F DOOR OUT HANDLE PAINTING L/R DOOR OUT HANDLE PAINTING	1 1 1 Qtv	Price - - - Unit	Price - - - Ext	- - -	6.00 1.00 0.20 Panel	Paint 0.50 0.50 0.50 0.30 0.60 1.20 0.20 0.10 0.10	- - - - - - - - - - - -	6.00 1.00 0.20 Total 0.50 0.30 0.60 1.20 0.20 0.10



Tel: 020 8810 9393 Fax: 020 8810 9333

Estimate Print

Printed on 31 October 2019 by GENERAL

Job Number	18231	Registration LL19ZND								
Paint			Qtv	Unit Price	E Pric	xt MET	Panel	Paint	Allow	Total
	BUMPER (ADD/WORK)		1	-	1110		-	0.10	-	0.10
APPLY FILLER PASTE R	, ,		1	-			-	0.30	-	0.30
	FOR TWO COAT PAINT		1 1	-			-	1.40	-	1.40
	ler on plast/met par Ielling less door shi		1	-			-	0.30	-	0.30
Replace			Qtv	Unit	E	xt MET	Panel	Paint	Allow	Total
-		David Missaala		Price	Pric	:e				
PARTS		Part Numb		250.00	0.50					
L/R SIDE TRIM		156 885 1300	1	£59.00	£59.		-	-	-	-
FILLER PER HOUR		Renew	1	£12.00	£12.		-	-	-	-
L/R PROTECTION FOIL		156 732 0111	1	£9.30 £2.01	£9. £2.		-	-	-	-
SUNDRY PARTS (@ 2.5 CORROSION PROTEC			1	£2.01 £12.00	£2.		-	-	-	-
			Qty	Unit		xt MET	Panel	Paint	Allow	Total
Specialist			Qiy	Price	Pric		i dilei	ı aıııı	Allow	ioidi
SYSTEM RESET			1	£75.00	£75.	- 00	-	-	-	-
Other			Qty	Unit		xt MET	Panel	Paint	Allow	Total
LABOUR				Price	Pric	:e				
(BUMPER REMOVED)			1	_			_	_	_	_
(DOOR TRIM REMOVE	ED)		1	_			_	_	_	_
SOCKET CONNECTIO	•		1	-			-	-	-	-
CHECK QUALITY CON	NTROL		1	-		- 0.25	0.25	-	-	0.50
IMPORT ROUNDING F			1	-			-	-	-	-
Corrosion Prote ANTI		10	1	-		- 0.30	0.30	-	-	0.60
•	ING ELECTRIC PLUG AN	ND	I	-			-	-	-	-
MATERIALS			1	0.400.70	0.400	70				
PAINT/MATERIALS OTHER			1	£490.79	£490.	/9 -	-	-	-	-
EPA			1	00.00	00	00				
CAR CARE KIT			1	£8.00 £3.50	£8. £3.		-	_	-	-
METHODS RESEARCH			1	£15.00	£15.		-	-	-	-
			Tota	l Times For J	ob	7.25	7.75	7.90	0.00	22.90
Estimate Sumr	mary	Gross	Disc	count	<u>Net</u>					
LABOUR (22.90 Hr		687.00		0.00	687.00					
MATERIALS	- <i>,</i>	490.79		0.00	490.79					
OTHER		26.50		0.00	26.50					
PARTS		94.31		0.00	94.31					
SPECIALIST		74.31 75.00		0.00	74.31 75.00					
		70.00					-			
TOTALS				0.00 £	1,373.60	Plus VAT	-			

Estimate Notes



Tel: 020 8810 9393 Fax: 020 8810 9333

Estimate Print

Printed on 31 October 2019 by GENERAL

Job Number Registration LL19ZND

All prices quoted are subject to VAT at the current rate. The above prices are valid for 3 Months. Whilst every care has been taken in the production of this estimate, any further damage found on stripping the vehicle will be estimated for separately.

Estimate.rpt(09/04/2015) 3 of 3