Return Shipping Instructions

Please follow the instructions below to assist us ensure there are no issues with UK Customs Clearance for the temporary import into the UK.

- 1. Please also include a copy of the RMA form with your shipping documentation/commercial invoice which must accompany the laser shipment.
- 2. **VERY IMPORTANT** Please provide your shipping department or freight forwarder with a copy of these instructions and the RMA form and advise them they should contact me at *yvonne.samson@m2lasers.com* for UK customs clearance instructions.
- 3. Once the shipment has been arranged, please provide me with the following information along with a scanned copy of the shipping documents: -
 - Freight Forwarder/Shipping Agent's Name and Contact Telephone & Email
 - Air Way Bill Tracking Number
 - Commercial Invoice
 - Approximate delivery date to M Squared Lasers
- 4. Shipping DocumentationThe shipment must be accompanied by a commercial invoice which must include all of the following details/statements:
 - State the RMA Number: RMA171107-1
 - List all items being shipped, including Serial Number for the Laser System
 - Value of Goods
 - Statement: "Value for Customs/Insurance Purposes Only"
 - Statement: "Temporary Return of British Manufactured Goods for Repair"
 - Statement:"ATTN: UK CUSTOMS BROKER: PLEASE CONTACT
 YVONNE.SAMSON@M2LASERS.COM UK CUSTOMS CLEARANCE INSTRUCTIONS"
 - Customs Procedure Code: 51-00-000 (Temporary Import under Full Inward Processing Relief)
 - Harmonized Commodity Code: 9013.2000.00 (Laser Equipment)
 - Shipping Terms: DDP (IncoTerms: Delivered, Duty Paid)