

From: Oregon DEQ Air Quality Reporting <no-reply@deq.oregon.gov>
To: d.okafor@cascadespecialty.example
Date: Thursday, February 12, 2026 9:41 AM
Subject: Received — Annual Report, Permit 26-2841-ST-01, reporting year 2025

Your annual report has been received.

Facility: Cascade Specialty Chemicals, LLC — Portland
Permit: 26-2841-ST-01 (Standard Air Contaminant Discharge Permit)
Reporting year: 2025
Submission ID: ACDP-AR-2025-262841
Received: February 12, 2026 09:41 PST
Submitted by: Daniel Okafor, Plant Manager

This message confirms receipt only. It is not a determination that the report is complete or that the facility is in compliance with its permit. Keep this confirmation with your permit records. Records required by the permit must be kept for five years and made available to the Department on request.

Oregon Department of Environmental Quality · Air Quality Program · 700 NE Multnomah Street, Suite 600,
Portland, OR 97232

ANNUAL REPORT — REPORTING YEAR 2025
Cascade Specialty Chemicals, LLC — Portland Facility, 4410 NW Front Avenue,
Portland, Oregon 97210
Standard Air Contaminant Discharge Permit 26-2841-ST-01 · Submitted under
Condition 4.1 · Period: January 1 to December 31, 2025

1. Throughput by line

Line	Product repackaged	2025 throughput (pounds)	Operating days
Acid repackaging line (S-1)	hydrochloric, sulfuric and nitric acid solutions	1,842,000	238
Caustic repackaging line (S-2)	sodium and potassium hydroxide solutions	1,210,000	231
Solvent storage T-3 to T-6 (C-1)	acetone, isopropanol, toluene, xylene	3,960,000 gallons received	—

2. Scrubber log summary (Condition 3.1)

Scrubber	Days logged	Average pressure drop (in. w.c.)	Lowest	Highest	Days outside 2.0 to 6.0
S-1	238	3.8	3.1	4.6	0
S-2	231	4.1	3.4	5.2	0

Quarterly inspections under Condition 3.2 were carried out on March 27, June 26, September 25 and December 18, 2025, and are recorded in the scrubber maintenance file.

3. Carbon adsorption unit C-1 (Condition 3.3)

The carbon in C-1 was replaced on March 14, 2025 (Calgon Filtrasorb 400, 1,800 pounds, by Northwest Carbon Services). Weekly detector-tube checks at the C-1 outlet were carried out every week in 2025 with no breakthrough detected. The next scheduled replacement is on or before March 14, 2026.

4. Deviations and excess emissions (Conditions 5.1 and 5.2)

One deviation. On August 22, 2025 the S-2 recirculation pump failed at 14:10; the caustic repackaging line was stopped within four minutes and remained down until the pump was replaced on August 24. No product was repackaged on the caustic line while the scrubber was out of service. The Department was notified by email on August 23, 2025 and a written report was submitted on September 2, 2025 (DEQ reference DEV-2025-0913).

Opacity: no visible emissions above 20 percent were observed at any permitted source in 2025.

I certify that the information in this report is true, accurate and complete to the best of my knowledge.

Daniel Okafor, Plant Manager · Signed: February 10, 2026