		Department	Factory Control		DATE: 16.11.2019		
RULE		Area		Warehouse		Issue: 01 Revision:	
STEP		PROCESS	RES	P	FREQUENCY	Page:-	
1	MAP-ID VEHICLE REPORTING ON MATERIAL GATE.  [Security have entered vehicle reporting time in register)		Security su	Security supervisor		Continuously	
2	SYSTEM IN-WARDING & MANUAL IN- WARDING. (During system in-warding security will ensure  O Gate check list report have attached with documents & material.		Security Supervisor Continuously				
	SYSTE (Recel	EIPT INCHARGE CHECK GATE ENTRY IN EM AND ALLOW TO VEHICLE MOVE ON DOCK.  Ipt Incharge check gate entry in SAP and o security for vehicle move on unloading dock)	Receipt In	charge	Continuously		
4	a) Che packing b) Chec invoice	RIAL UNLOAD AND VERIFICATION WITH DOCUMENTS.  sock Meterials condition rust & dust as well as getandard, control sheet, orginal control s	Receiptin	charge	Continuously		
<b>9</b>	LOCATI Semi fli	nish material directly move in <u>OK</u> n after ensure <u>Q Gate check list, Lot</u>	Receiptir	charge	Continuously		
ලි		<u>GRN PREPRATION.</u> physical verification and given wledgment, GRN made by Stores data tor)	Receipt Ind	charge	Continuously		
<b>2</b>	After	TCH SPLIT TAG ATTACHED WITH LOT. storage material in OK area batch split aste with every lot control sheet which attached with material.	Receipting	charge	Continuously		
8	Q Gate	GRN APPROVED BY STORE, oproved by Stores In-charge on behalf of a Check List and one Xerox. handover to ty for record purpose If they required.	Receipting	charge	Continuously		
9	durin disput	PHYSICAL QUANTITY VERIFY. Ical quantity verify on line in every tray g production and if found any quantity te, problem highlight on mail to concern ir take action and counter-measure	Receipt Inc	harge	Continuously		
			01 0	NEWLY APP	IY	16-11-19	
	N	6,00	Issue Revision	Reason for ch		Date	