Rule	CRIT	CRITERIA EOR CT VERIEICATIONI AND INABBOVENAENT			Date- 11.02.2017
		_	15D-1V15-UC3	2	Issue -01 Rev.01
S No.	ACTIVITY		FREQUENCY	RESPONSIBILITY	CHECK POINT
-		In case of new devlopment , PE depp. Will provide the CT target of machine with new devlop model	before mass production	Section Head	
2	Target setting	CT released by PDE depp. Will be Plan or target CT for Production depp.	Change point	Section Head	Signed copy by production
к		If machine layout change ,process change, cycle time change & new model add then need to review of CT again	Change point	Section Head	
4		Cycle time of each machine (model wise) has to be verify every month	Monthly	Section Head	
5	Vata monitoring	Approved copy of CT verification sheet for each section has to be submited to OEE monitoring person	Monthly	Section Head	
Q	Analysis	If Actual CT of machine is less or more than target CT (by more than 3%) ,we have to analyz the data and find the reason of gap between target and actual CT	Every month	Section Head	CT verification sheet
7	Improvement	If Actual CT of machine is less than target CT and line capacity has also impact due to this , we have to standardize the change through PCJS process.	Monthly	Section Head	
∞		We have to fill the improvement plan for gap (pioritize on base of there impact on line capacity) after discussion with supporting depp.	Monthly	Section Head	•
Preapred By	Preapred By Will Muman	Checked By		Appro	Approved By

Preapred By Jumps