RULE

Lead & Profile Guidelines for Pre Despatch Inspection

ISD-QA-056

Date :10.01.2018,Issue No. 01,Rev.00

Objective:	Responsibility
To improve the dispatch condition with PDI reports	QA
<u>Scope</u>	
To cover all dispatch send to customer with PDI reports <u>Guideliness</u>	QA
1. Every day QA PDI person will take parts from every lot &give parts to std. room for PDI data	QA PDI
QA PDI incharge- Daliy basis	
2. After inspection of PDI parts by StD. room PDI person will collect all parts from std. room & verify L/P Graphs.	QA PDI
QA PDI incharge- Daliy basis	
3. If parts found within spec than make PDI report & inform to Dispatch.If any lot L/P graph found out of bend and in between \pm 1 μ ,Than old the lot & take decision from QA head.	QA PDI
QA PDI incharge- Daliy basis	
4. Take judgement for Parts out of bend in between \pm 1 μ , If OK than give	QA Head
go head for lots.	
5. Ensure PDI report is must for every lot by updation document (ISF -QA-98) ,handover to FC .	PDI QA

Prepared By. Mr. Bhupendra Kumar

Approved by Mr. Parveen Maan