

PRECISION

QUALITY REPAIRS. HONEST SERVICE.

9412 Commerce Blvd
Phoenix, AZ 85027
(602) 555-0884
estimates@precisionautobody.net
www.precisionautobody.net

INVOICE

INV-PAB-019447

ISSUED TO

Marcus Thompson
3851 N Camelback Vista Way
Phoenix, AZ 85016
(480) 555-0193
mthompson.az@email.com

INVOICE DATE

April 8, 2026

SERVICE PERIOD

March 30 - April 7, 2026

CLAIM REFERENCE

GEC-2026-552187

VEHICLE	VIN	MILEAGE	PLATE	COLOR
2020 Nissan Altima SV	1N4BL4BV4LC219736	67,124	AZ-CKR9248	Brilliant Silver

Driver Side Collision Damage Repair

DESCRIPTION	TYPE	QTY	RATE	AMOUNT
Driver door shell - aftermarket	PART	1	\$542.00	\$542.00
Driver side rear door skin	PART	1	\$398.00	\$398.00
Rocker panel molding (LH)	PART	1	\$124.50	\$124.50
Side mirror assembly - heated	PART	1	\$287.25	\$287.25
Door handle - exterior	PART	1	\$78.00	\$78.00
Body repair - driver door	LABOR	6	\$110.00	\$660.00
Body repair - rear door	LABOR	5.5	\$110.00	\$605.00
Rocker panel restoration	LABOR	3.5	\$110.00	\$385.00

DESCRIPTION	TYPE	QTY	RATE	AMOUNT
Door alignment and adjustment	LABOR	2	\$110.00	\$220.00
Paint - 2 doors + blend	LABOR	8	\$110.00	\$880.00
Paint and refinishing materials	MATERIALS	1	\$425.00	\$425.00
Shop supplies	MATERIALS	1	\$110.00	\$110.00

Parts subtotal	\$1,429.75
Labor subtotal	\$2,750.00
Materials & supplies	\$535.00
Subtotal	\$4,714.75
Sales tax (8.60%)	\$405.47
TOTAL	\$5,120.22

Insurance deductible of \$1,000.00 applies and is the responsibility of the customer.