



Crossroads Collision

ADVANCED VEHICLE REPAIR TECHNOLOGY

INVOICE ID

CRC-2026-MV-0224

3200 Innovation Drive, Suite 100,
Austin, TX 78758

(512) 555-
0712

claims@crossroadscollision.com

www.crossroadscollision.com

CUSTOMER

Hannah Liu

8744 Lavender Bend
Austin, TX 78759
(737) 555-0429
hannah.liu@email.com

DATES

Invoice: May 11, 2026

Service:

April 14 - May 8, 2026

Terms: Net 30

CLAIM DETAILS

Reference:

LMTY-MVA-26-559871

Carrier: Liberty Mutual

Status: Completed

VEHICLE PROFILE

YEAR/MAKE/MODEL

2023 Tesla Model 3
Long Range

VIN

5YJ3E1EBXPF512684

MILEAGE

14,892

PLATE

TX-TES330

COLOR

Pearl White Multi-
Coat

REPAIR SCOPE Multi-Vehicle Accident - Front End & Side Damage

DESCRIPTION	CATEGORY	QTY	RATE	AMOUNT
Front bumper cover assembly (Tesla OEM)	Part	1	\$1,185.00	\$1,185.00
Front fascia camera assembly	Part	1	\$685.00	\$685.00
Radar sensor module - front	Part	1	\$925.00	\$925.00
Driver side front fender	Part	1	\$612.00	\$612.00
Driver door outer skin	Part	1	\$745.50	\$745.50
Headlight assembly (driver)	Part	1	\$1,248.00	\$1,248.00
Side mirror assembly w/cameras	Part	1	\$595.00	\$595.00
Front lower control arm (LH)	Part	1	\$312.00	\$312.00
R&I front bumper assembly	Labor	3.5	\$175.00	\$612.50
Front fender replacement and align	Labor	5	\$175.00	\$875.00
Door replacement and alignment	Labor	6.5	\$175.00	\$1,137.50
Suspension R&R and alignment	Labor	3	\$175.00	\$525.00

DESCRIPTION	CATEGORY	QTY	RATE	AMOUNT
Paint refinish - fender, door, bumper	Labor	11	\$175.00	\$1,925.00
ADAS recalibration (full)	Labor	3	\$225.00	\$675.00
Tesla diagnostic and software	Labor	2	\$225.00	\$450.00
Paint materials - tri-coat	Materials	1	\$685.00	\$685.00
Shop supplies	Materials	1	\$165.00	\$165.00

Parts subtotal	\$6,307.50
Labor subtotal	\$6,200.00
Materials & supplies	\$850.00
Subtotal	\$13,357.50
Sales tax (8.25%)	\$1,101.99

TOTAL →	\$14,459.49
----------------	--------------------

Insurance deductible (customer): ~~\$1,000.00~~