

LOLER: Load Test Examination Report

Lifting Operations and Equipment Regulations 1998 Schedule 1

Client name & Address:

OpeMed Ltd Birtley House Group Ltd Birtley House Bramley Guildford GU5 0LB

Tel:

Location of Examination: Room 16

Make: Opemed Model: OT200 Serial No: 17090724 SWL: 200Kgs

Local Number: Start-up Date: 2012 MA Number: Item 1 OH

Commissioning Examination: No Safe to Operate: Yes

Advisory: Hoist will require lift tape on next visit

Schedule: Six Months

Safe to Operate: Yes

Defective Parts (Immediate Attention)

Part No Description Defect Action Taken

Defects requiring rectification at a later date:

Part No Description Defect Action Taken

Conducted according to BS EN ISO 10535

Carried out on: Jan 2019 Next due: July 2019

Name of Examiner: A.Howes : Service Engineer: 08

MoreAble LTD - Registered in England No. 7043024VAT Registration No. 978 907 840
On behalf of MoreAble Ltd 6 Benson Close, Bicester, Oxfordshire OX26 4FQ



LOLER: Load Test Examination Report

Lifting Operations and Equipment Regulations 1998 Schedule 1

Client name & Address:

OpeMed Ltd Birtley House Group Ltd Birtley House Bramley Guildford GU5 0LB

Tel:

Location of Examination: Room 32

Make: Opemed Model: OT200 Serial No: 17090718 SWL: 200Kgs

Local Number: Start-up Date: 2012 MA Number: Item 2 OH

Commissioning Examination: No Safe to Operate: Yes

Advisory: Hoist will require lift tape on next visit

Schedule: Six Months

Safe to Operate: Yes

Defective Parts (Immediate Attention)

Part No Description Defect Action Taken

Defects requiring rectification at a later date:

Part No Description Defect Action Taken

Conducted according to BS EN ISO 10535

Carried out on: Jan 2019 Next due: July 2019

Name of Examiner: A.Howes : Service Engineer: 08

MoreAble LTD - Registered in England No. 7043024VAT Registration No. 978 907 840
On behalf of MoreAble Ltd 6 Benson Close, Bicester, Oxfordshire OX26 4FQ



LOLER: Load Test Examination Report

Lifting Operations and Equipment Regulations 1998 Schedule 1

Client name & Address:

OpeMed Ltd Birtley House Group Ltd Birtley House Bramley Guildford GU5 0LB

Tel:

Location of Examination: Room 29

Make: Opemed Model: OT200 Serial No: 17090721 SWL: 200Kgs

Local Number: Start-up Date: 2012 MA Number: Item 3 OH

Commissioning Examination: No Safe to Operate: Yes

Advisory:

Schedule: Six Months

Safe to Operate: Yes

Defective Parts (Immediate Attention)

Part No Description Defect Action Taken

Defects requiring rectification at a later date:

Part No Description Defect Action Taken

Conducted according to BS EN ISO 10535

Carried out on: Jan 2019 Next due: July 2019

Name of Examiner: A.Howes : Service Engineer: 08

MoreAble LTD - Registered in England No. 7043024VAT Registration No. 978 907 840
On behalf of MoreAble Ltd 6 Benson Close, Bicester, Oxfordshire OX26 4FQ



LOLER: Load Test Examination Report

Lifting Operations and Equipment Regulations 1998 Schedule 1

Client name & Address:

OpeMed Ltd Birtley House Group Ltd Birtley House Bramley Guildford GU5 0LB

Tel:

Location of Examination: Room 33

Make: Opemed Model: OT200 Serial No: 17090719 SWL: 200Kgs

Local Number: Start-up Date: 2012 MA Number: Item 4 OH

Commissioning Examination: No Safe to Operate: Yes

Advisory:

Schedule: Six Months

Safe to Operate: Yes

Defective Parts (Immediate Attention)

Part No Description Defect Action Taken

Defects requiring rectification at a later date:

Part No Description Defect Action Taken

Conducted according to BS EN ISO 10535

Carried out on: Jan 2019 Next due: July 2019

Name of Examiner: A.Howes : Service Engineer: 08



LOLER: Load Test Examination Report

Lifting Operations and Equipment Regulations 1998 Schedule 1

Client name & Address:

OpeMed Ltd Birtley House Group Ltd Birtley House Bramley Guildford GU5 0LB

Tel:

Location of Examination: Room 38

Make: Arjo Model: V4 Serial No: V4-4208-461717 SWL: 200Kgs

Local Number: Start-up Date: 2008 MA Number: Item 5 OH

Commissioning Examination: No Safe to Operate: Yes

Advisory: Replaced 12v 5ah Batteries

Schedule: Six Months

Safe to Operate: Yes

Defective Parts (Immediate Attention)

Part No Description Defect Action Taken

Defects requiring rectification at a later date:

Part No Description Defect Action Taken

Conducted according to BS EN ISO 10535

Carried out on: Jan 2019 Next due: July 2019

Name of Examiner: A.Howes : Service Engineer: 08

MoreAble LTD - Registered in England No. 7043024VAT Registration No. 978 907 840
On behalf of MoreAble Ltd 6 Benson Close, Bicester, Oxfordshire OX26 4FQ