

UNIT 17 NORTHBROOK BUSINESS PARK WORTHING W.SUSSEX BN14 8PQ

Registered to ISO 9001:2008 with Certificate International

SALES: 01903 213983 H.O: 08458 739973 ACCOUNTS: 01903 830664 FAX: 01903 244008



20781

CUSTOMER NA	ME EYHURST COURT	LTD				
BIRTLEY HOUSE		BIRTL	BIRTLEY HOUSE			
BRAMLEY		BRAM	BRAMLEY			
GUILDFORD		GUILD	GUILDFORD			
SURREY		SURREY				
POST CODE	GU5 0LB	POST CODE	GU5 0LB			
CONTACT	TIM WHALLEY	CONTACT	TIM WHALLEY KEN			
TEL	01483 892 055	TEL	01483 892 055			

We hereby certify that apart from non-conforming ext as recorded, the Fire Extinguishing appliances as set out below have been inspected and serviced in accordance with BS FN 5306: 3

www.eflfire.co.ul	k Maintenance and serviced in ac	cordance with BS EN	5306: 3.					
Service Date Engineer's No.			Engineer					
10-	6 - 16 1386		David (	Gladwin				
Equipment Inspected			Equipment Condemned					
QTY	DESCRIPTION CONF. QTY		QTY	DESCRIPTION				
5	ABC Dry Powder Extinguishers	5	1	DOT OF SERVICE DATE				
4	AFFF Foam Extinguishers	4						
19	CO2 Extinguishers	20	3	OUT OF SEQ. LICE DOTE				
0	Fire Blankets							
19	Other Equipment Water / Spray Extinguishers	. 0						
0	Water Extinguishers	19		DUT OF SERVICE DAT				
	Water Extinguishers							
	Total Extinguishers	1.0	5.			· Martine · Martine · London · Martine · Marti		
		48			72-40			
Service T	ype: Select	Plus (30)	Service P	rice: #3	64.80 £3	2.00 / £7.60		
Materials and Parts Supplied			New Equipment Supplied					
QTY	PART NO. DESCRIPTION	UNIT PRICE	QTY	PART NO.	DESCRIPTION	N UNIT PRICE		
43	SLICHH SEALING TE	FOL	184	EXIOIL	200002	88.55		
17	SC1075 62 HOODO WA	shees fo	4	Groon	BITZ WATE			
26	Seions Gouge Lot	FOL						
26	SELOGIL HOSE O WASHE	25 FOL						
1	SOUTH WATER OFFICE	FO C						
	Shork Form poor KIT	FOC.						
		-	00000 1 001 1			473-5		
			COST £ 801	VAT	1162.36	TOTALE 978-54		
		Special In	structions	5				
need to ser	vice 2 x w13/2 x c2g in great barn offic	ces, birthley co	ourtyard, serv	ice exts in nev	v offices in 2014.			
		***************************************		***************************************				
Correctiv	e Action / Recommendation	าร						
Equipment listed a	bove as condemned 1 x Rowses 1		> 0.01-	1	1 1x 2.64 C			
should be replaced	or remedied	(Ciper	)	LOO SIN	A TX ELECT (	6 (		
			/.					
CUSTOMER NOTIF	IED AT COMPLETION OF SERVICE:							
	Guidance To Clients			MINED / UPDATE	)	Y		
Ref BS 5306: Pa	ara 5: Inspection by user.		CUSTOMERS SIGNATU	RE /	1 11			
It is recommended that regular inspection of all extingushers, spare gas cartridges and replacement charges should be carried out by a responsible								
person at interva	WELL							
	osition and have not been discharged or lost pressi shers fitted with a pressure indicator) or suffered of		POSITION	Acy will	MANAGER	DATE 10 - 6-16		