

Inspection Report: Order number: 43652952

Job Number: 30

Sold To: EYHURST COURT LTD

SITE INFORMATION

Customer Name: BIRTLEY HOUSE Material: MALIBU 17, LEFT, HI/LO, LIFT

Street: **BRAMLEY** Serial number:

City: **GUILDFORD Asset Tag:**

Post Code: GU5 0LB **Product Classification:**

Latest Location: GND FLR ANNEX

1309000986

PRODUCT INFORMATION

CONTACT INFORMATION

WORK ORDER INFORMATION

Order activity type: **Site Contact: BIRTLEY HOUSE** M Maintenance

Work Order Description: SERVICE VISIT

Site Contact Email: **Customer Order Number:** TW180376

PROBLEM DESCRIPTION AND CORRECTIVE ACTION

Damage	Problem Description	Engineers Comments
Activity	Specification	Engineers Comments
Create Quotation	Qty 1 of 8559714, no labour charge	

GENERAL INFORMATION

	External notes
Γ	Annual service completed. Found handset seat return button failing, quotation raised. Outstanding replacement seat lift PCB, awaiting part.

EQUIPMENT CHECKS

Task	Specification	Engineers Comments
Risk Assessment Performed		
Product Located		
Safe to operate		

PARTS USED

Product Code	Product Description	Qty	Accounting Indicator
6902105	O-RINGKIT, FMM 1/2" MIXER 632-	3 EA	Bronze Contract

LABOUR DETAILS

Activity Type	Start Date And Time	End Date And Time	Accounting Indicator
WORK	31.01.2019 10:15:00	31.01.2019 11:15:00	Bronze Contract



Inspection Report:

Order number: 43652952

Job Number: 30 Sold To: EYHURST COURT LTD

THOROUGH EXAMINATION LIFT

SITE INFORMATION

Account Name: EYHURST COURT LTD
Customer Name: BIRTLEY HOUSE
Street: BRAMLEY
Post Code: GU5 0LB

Product and job information

Material: MALIBU 17, LEFT, HI/LO, LIFT

Serial number: 1309000986

Asset Tag:

Product Classification:

Date of Manufacture (if 2013/05

known):

Latest Location: GND FLR ANNEX Order number: 43652952

Inspection Plan: 00028487/01/00000001

Date of Test: 20190131 Customer Order Number: 20180322

Examination Details

EXAMINATION DETAILS				
Safe working Load(s) (kg)	130	Accepted		
	(No remarks)	•		
	Test Equipment	n/a		
Date of Last Thorough Examination	25.01.2018	Accepted		
	(No remarks)	(No remarks)		
	Test Equipment	n/a		
Date of Thorough Examination	31.01.2019	Accepted		
	(No remarks)			
	Test Equipment	n/a		
Date of Next Thorough Examination	31.01.2020	Accepted		
	(No remarks)			
	Test Equipment	n/a		
Is this the first examination?	No			
	(No remarks)			
If yes,assembled&installed correctly?	Yes			
	(No remarks)			
Examination interval?	Within 6 months			
	(No remarks)			
Any defects identified?	No	No		
	(No remarks)	(No remarks)		



Inspection Report:

Order number: 43652952

Job Number: 30 Sold To: EYHURST COURT LTD

Is the defect of immediate danger?	No		
	(No remarks)		
Date when defect could become a danger?		n/a	
	(No remarks)	(No remarks)	
	Test Equipment	n/a	
Details of remedy required ?	ly required ?		
	(No remarks)		
Details of tests carried out?	Yes		
	(No remarks)		
Is the equipment safe to operate?	Yes		
	(No remarks)		

THERMOSTATIC MIXING VALVES

SITE INFORMATION

Account Name: EYHURST COURT LTD **Customer Name: BIRTLEY HOUSE** Street: **BRAMLEY** Post Code: GU5 0LB

Product and job information

Material: MALIBU 17, LEFT, HI/LO, LIFT

Serial number: 1309000986

Asset Tag:

Product Classification:

Date of Manufacture (if 2013/05 known):

Latest Location: GND FLR ANNEX 43652952

Order number: Inspection Plan: 00028490/01/00000001

Date of Test: 20190131 **Customer Order Number:** 20180322

Examination Details

In Service Testing			
Temperature Recording Device?	Device? Yes		
	Digitron Thermometer		
Temperature Recording Device Serial No?	Yes		
	(No remarks)		
Last Calibration Date ?	18.10.2018	Accepted	
	(No remarks)		
	Test Equipment	n/a	
In-Line Strainers Cleaned ?	Yes		
	(No remarks)	(No remarks)	



Inspection Report: Order number: 43652952

Job Number: 30 Sold To: EYHURST COURT LTD

Check Valves in Good Order?	Yes		
	(No remarks)		
Cold Supply Inlet Temperature °C	9	Accepted	
	(No remarks)	•	
	Test Equipment	n/a	
Hot Supply Inlet Temperature °C	60	Accepted	
	(No remarks)		
	Test Equipment	n/a	
Bath Spout Set Temp Reading °C	42.7	Accepted	
	(No remarks)		
	Test Equipment	n/a	
Shower Head Set Temp Reading °C	39.9	Accepted	
	(No remarks)		
	Test Equipment	n/a	
Bath Spout Temp Reading - cold Isolated	0	Accepted	
	(No remarks)		
	Test Equipment	n/a	
Shower Head Temp Reading - cold Isolated	0	Accepted	
	(No remarks)		
	Test Equipment	n/a	
Bath TMV correctly set & safe to use?	Yes		
	(No remarks)		
Shower TMV correctly set & safe to use?	Yes		
	(No remarks)		
If No, is the valve isolated a warning I	No		
	(No remarks)		
Commissioning Checks Follwing Install.			
Supply Pressure Cold		n/a	
	(No remarks)	•	
	Test Equipment	n/a	
Supply Pressure Hot		n/a	
	(No remarks)		
	Test Equipment	n/a	
Bath Spout Set Temp Reading - R/Flow		n/a	
	(No remarks)		
	Test Equipment	n/a	



Inspection Report: Order number: 43652952

Job Number: 30 Sold To: EYHURST COURT LTD

Shower Head Set Temp Reading - R/Flow		n/a	
	(No remarks)	(No remarks)	
	Test Equipment	n/a	
Bath Spout Temp Reading-cold Isolated (M		n/a	
	(No remarks)	(No remarks)	
	Test Equipment	n/a	
Shower Head Temp Reading-cold Isolated (n/a	
	(No remarks)		
	Test Equipment	n/a	

Technician's signature N Prosser

Date: 31.01.2019

Email:

Customer's signature See summary report

Date: 31.01.2019

Email:

Tim@birtleyhouse.co.uk