

Company: Location: Risk Assessment:

Kitchen Cooker extraction hood Kitchens Reference No.

29/10/2014 Date of Assessment:

Tim Whalley



### Birtley House

Signature/s..

29/10/2015

Review Date

# Eyhurst Court Ltd - GU5 0LB

### Cooker extraction hood Completed By:

### Identified hazard:

Le Date 18/3/15

Le 19/8/16

Le 29/12/17

Le 07/01/19

Build up of grease in ventilation ducting and hood may lead to fire. Use of step ladder.









### Who is at risk?

All staff & visitors

## How is the risk controlled?

Monthly, in-house cleaning.

Deep clean of ducting and hood carried out by external contractor every year...













The calculated risk factor for this task/operation is 6 (Probability: 2 x Severity: 3)

This is classed as a LOW risk

### Additional Measures:

None Required

Cooker extraction hood - 29-10-2014

Version: 13/03/2015

Page 2 of 2

Cooker extraction hood - 29-10-2014

Version: 13/03/2015