

Our Ref.: H8L200921/1/CW2/GM4/ISP Date: 8th January 2018

BIRTLEY HOUSE GROUP LTD Birtley House Birtley Road Bramley Guildford Surrey GU5 0LB

For the attention of Tim Whalley

Inspection Details

Type : Policy

Number : H8L200921-1 Report Nos. : 001-013

Class : Lifting & Handling Plant

Surveyor : Mr C White
Date : 4th January 2018

Location : As above

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

This report contains scheduled items which were not available for examination for the particular reason noted against each item. You should be aware that the equipment concerned should not be used without a current Statutory Examination Report. In the event of the equipment being required for use, please contact our Surveyor who will make the necessary arrangements to carry out the Statutory examination.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the inspection methods and procedures as documented in Section 7.1 of the Company Quality Assurance Policy (Manual).

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.









Policy: H8L200921 Previous Report: 240217-002-0002SK1

Site: 00001 Report Number: 080118-001-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched Plant
No. Code Item

SWL Particulars of any defect


L0148 L42Al1 Runway Track
S.No.:CS221983
Locn.:Mews Lift Shaft General:
No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination:04 Jan 2018Date of Last Examination:14 Feb 2017Inspecting Engineer:Mr C WhiteDate of Next Examination:04 Jan 2019

Signature:

Qualification: Engineer Surveyor



New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-006-0004SB2

Site: 00001 Report Number: 080118-002-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the specified time period


Sched		_		
No.	Code	Item	SWL	Particulars of any defect
BATH H	OISTS			
L0004	L73AHH	Bath Hoist	130 kg	a) None
		S.No.:8662345/1309000986		b) None
		Locn.:Lower Floor Bathroom		General:
				No apparent defects.
L0005	L73AHH	Bath Hoist	130 kg	a) None
		S.No.:VEPL00003264		b) None
		Locn.: Upper Floor Bathroom		General:
				No apparent defects.
L0006	L73AHH	Bath Hoist	130 kg	a) None
		S.No.:1205000361		b) None
		Locn.:Main House Top		General:
		Floor Bathroom		No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Date of Last Examination: 18 May 2017 Inspecting Engineer: Mr C White Date of Next Examination: 04 Jul 2018

C White Signature:

Qualification: Engineer Surveyor



New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 **Previous Report:** 130617-007-0004SB2

Site: 00001 Report Number: 080118-003-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.		Item	SWL	Particulars of any defect
	INEL HOI L73AHH	STS Personnel Hoist C/w Scales S.No.:0907001386 P.No.:12 Arjo	170 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0008	L73AHH	Personnel Hoist S.No.:LD451289471 P.No.:13 Locn.:Room 39	272 kg	a) None b) None General: No apparent defects.
L0009	L73AHH	Personnel Hoist S.No.:7090089 P.No.:10	175 kg	a) None b) None General: No apparent defects.
L0011	L73AHH	Personnel Hoist S.No.:17090721 P.No.:6 Locn.:Room 29	200 kg	a) None b) None General: No apparent defects.
L0012	L73AHH	Personnel Hoist S.No.:STLA0712G653 P.No.:1	200 kg	a) None b) None General: No apparent defects.
L0013	L73AHH	Personnel Hoist S.No.:091105865994 P.No.:11	170 kg	a) None b) None General: No apparent defects.
L0014	L73АНН	Personnel Hoist S.No.:VOYA-11319 Sunrise Locn.:Room 21	200 kg	 a) None b) None General: Lifting tape creased and one retaining bracket damaged - monitor otherwise serviceable. No other apparent defects.
L0015	L73AHH	Personnel Hoist S.No.:LD451289461 P.No.:14 Locn.:Room 22	272 kg	a) None b) None General: No apparent defects.
L0016	L73AHH	Personnel Hoist S.No.:LD451289470 P.No.:2 Locn.:Room 19	272 kg	a) None b) None General: No apparent defects.
L0017	L73AHH	Personnel Hoist S.No.:SEE0648344 P.No.:4	220 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination:04 Jan 2018Date of Last Examination:18 May 2017Inspecting Engineer:Mr C WhiteDate of Next Examination:04 Jul 2018

Signature:

C White

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP

Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-008-0004SB2

Site: 00001 Report Number: 080118-004-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the

Sched No.	Plant Code	Item	SWL	Particulars of any defect		
PERSON	PERSONNEL HOISTS					
L0018	L73AHH	Personnel Hoist S.No.:11GSZ100037 P.No.:5	159 kg	a) None b) None General: No apparent defects.		
L0019	L73AHH	Personnel Hoist S.No.:300015775 Locn.:Hawthorn App	272 kg	a) None b) None General: No apparent defects.		
L0020	L73AHH	Personnel Hoist S.No.:STLA0804G272 P.No.:3	200 kg	a) None b) None General: No apparent defects.		
L0021	L73AHH	Personnel Hoist S.No.:17090718 P.No.:7 Locn.:Room 32	200 kg	a) Noneb) NoneGeneral:Lifting tape slightly creased.No other apparent defects.		
L0149	L73AHH	Personnel Hoist S.No.:17090719 P.No.:8 Locn.:Room 33	200 kg	a) None b) None General: No apparent defects.		

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Inspecting Engineer: Mr C White

C White

Date of Last Examination: 18 May 2017 Date of Next Examination: 04 Jul 2018

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP

Registered as a branch in Ireland: 906105 Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited is accredited by the United Kingdom Accreditation Service







Signature:





Policy: H8L200921 Previous Report: 130617-009-0004SB2

Site: 00001 Report Number: 080118-005-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
PERSON L0099	INEL SLI L96AHH	NGS Personnel Sling S.No.:74031100030001 P.No.:46	272 kg	a) None b) None General: No apparent defects.
L0100	L96АНН	Personnel Sling S.No.:770907821608 P.No.:38	190 kg	a) None b) None General: No apparent defects.
L0101	L96АНН	Personnel Sling S.No.:7404110046000094 P.No.:16	272 kg	a) None b) None General: No apparent defects.
L0102	L96АНН	Personnel Sling S.No.:740411004600030 P.No.:21	272 kg	a) None b) None General: No apparent defects.
L0103	L96АНН	Personnel Sling S.No.:741210008400002 P.No.:35	272 kg	a) None b) None General: No apparent defects.
L0104	L96АНН	Personnel Sling S.No.:740411004600130 P.No.:32	272 kg	a) None b) None General: No apparent defects.
L0105	L96АНН	Personnel Sling S.No.:SL1513090213 P.No.:86	272 kg	a) None b) None General: No apparent defects.
L0106	L96АНН	Personnel Sling S.No.:SL2511070127 P.No.:04	227 kg	a) None b) None General: No apparent defects.
L0107	L96АНН	Personnel Sling S.No.:101A P.No.:42	160 kg	a) None b) None General: Worn but serviceable.
L0108	L96АНН	Personnel Sling S.No.:740311000300036 P.No.:29	272 kg	a) None b) None General: No apparent defects.
L0110	L96АНН	Personnel Sling S.No.:SL164312080325 P.No.:25	227 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Date of Last Examination: 18 May 2017 Inspecting Engineer: Mr C White Date of Next Examination: 04 Jul 2018

Signature:

C White

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-010-0004SB2

Site: 00001 Report Number: 080118-006-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the specified time period

Sched Plant	<u> </u>		
No. Code	ltem	SWL	Particulars of any defect
PERSONNEL S	SLINGS HH Personnel Sling S.No.:220314004700016 P.No.:19	190 kg	a) None b) None General: No apparent defects.
L0112 L96A)	HH Personnel Sling S.No.:MAA4031/XL P.No.:28	190 kg	a) None b) None General: No apparent defects.
L0114 L96A	HH Personnel Sling S.No.:1017 P.No.:14	190 kg	a) None b) None General: No apparent defects.
L0115 L96A	HH Personnel Sling S.No.:740910015000046 P.No.:49	272 kg	a) None b) None General: No apparent defects.
L0116 L96A	HH Personnel Sling S.No.:1030 P.No.:09	272 kg	a) None b) None General: No apparent defects.
L0117 L96A	HH Personnel Sling S.No.:LOT7402150028 P.No.:10	272 kg	a) None b) None General: No apparent defects.
L0118 L96A	HH Personnel Sling S.No.:7411140031 P.No.:83	272 kg	a) None b) None General: No apparent defects.
L0119 L96A	HH Personnel Sling S.No.:LOT2203150239 P.No.:67	200 kg	a) None b) None General: No apparent defects.
L0122 L96A)	HH Personnel Sling S.No.:LOC0080/31 P.No.:99	175 kg	a) None b) None General: Worn but serviceable.
L0126 L96A	HH Personnel Sling S.No.:20 P.No.:20	200 kg	a) None b) None General: No apparent defects.
L0127 L96A)	HH Personnel Sling S.No.:SL2731060071 P.No.:47	227 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Date of Last Examination: 18 May 2017 Inspecting Engineer: Mr C White Date of Next Examination: 04 Jul 2018

HSB Engineering Insurance Services Limited

is accredited by the United Kingdom

Accreditation Service

Signature:

HSBEI-1029-1214-3

C White

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP

Registered as a branch in Ireland: 906105 Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-012-0004SB2

Site: 00001 Report Number: 080118-007-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.		Item	SWL	Particulars of any defect
PERSON	NEL SLI	NGS		
L0128	L96АНН	Personnel Sling S.No.:SL2712100242 P.No.:26	227 kg	a) None b) None General: No apparent defects.
L0129	L96АНН	Personnel Sling S.No.:IEU00905469 P.No.:44	200 kg	a) None b) None General: Belt clip missing - refit. No other apparent defects.
L0130	L96АНН	Personnel Sling S.No.:IEU009005 P.No.:95	200 kg	a) None b) None General: No apparent defects.
L0131	L96АНН	Personnel Sling S.No.:0101 P.No.:07	175 kg	a) Noneb) NoneGeneral:Velcro stitching worn - monitor, otherwise serviceable.No other apparent defects.
L0132	L96АНН	Personnel Sling S.No.:SL1642212100178 P.No.:50	227 kg	a) None b) None General: No apparent defects.
L0133	L96АНН	Personnel Sling S.No.:SL164214080133 P.No.:88	227 kg	a) None b) None General: No apparent defects.
L0134	L96АНН	Personnel Sling S.No.:M4000-LL-1 P.No.:30	272 kg	a) None b) None General: No apparent defects.
L0135	L96АНН	Personnel Sling S.No.:8822084880373 P.No.:31	272 kg	a) None b) None General: No apparent defects.
L0136	L96АНН	Personnel Sling S.No.:24 P.No.:24	190 kg	a) None b) None General: No apparent defects.
L0138	L96АНН	Personnel Sling S.No.:TSS.503 P.No.:68	200 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination:04 Jan 2018Date of Last Examination:18 May 2017Inspecting Engineer:Mr C WhiteDate of Next Examination:04 Jul 2018

Signature:

- White

HSB Engineering Insurance Services Limited is accredited by the United Kingdom

Accreditation Service



Qualification: Engineer Surveyor





Telephone: 0845 345 5510





Policy: H8L200921 Previous Report: 130617-013-0004SB2

Site: 00001 Report Number: 080118-008-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
	NEL SLI L96AHH	NGS Personnel Sling S.No.:220412016 P.No.:37	190 kg	a) None b) None General: No apparent defects.
L0143	L96АНН	Personnel Sling S.No.:741210008400007 P.No.:70	272 kg	a) None b) None General: No apparent defects.
L0144	L96АНН	Personnel Sling S.No.:7412108400025 P.No.:34	272 kg	a) None b) None General: No apparent defects.
L0145	L96АНН	Personnel Sling S.No.:741210008400013 P.No.:33	272 kg	a) None b) None General: No apparent defects.
L0147	L96АНН	Personnel Sling S.No.:882208480378 P.No.:63	272 kg	a) None b) None General: No apparent defects.
L0150	L96АНН	Personnel Sling S.No.:931147 P.No.:92	200 kg	<pre>a) None b) None General: Clearly mark with safe working load. No other apparent defects.</pre>
L0151	L96АНН	Personnel Sling S.No.:22116078036 P.No.:22	190 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0154	L96АНН	Personnel Sling S.No.:221116099041 P.No.:77	200 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0156	L96АНН	Personnel Sling S.No.:931148 P.No.:55	200 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0158	L96АНН	Personnel Sling S.No.:0205446 Silvalea Ltd Locn.:Room 18	Not marked	a) None b) None General: Clearly mark with safe working load. No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Date of Last Examination: 18 May 2017 Inspecting Engineer: Mr C White Date of Next Examination: 04 Jul 2018

Signature:

C White

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-004-0004SB2

Site: 00001 Report Number: 080118-009-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the specified time period


Sched No.	Plant Code	Item	SWL	Particulars of any defect		
PERSO	PERSONNEL SLINGS					
L0159	L96АНН	Personnel Sling Silvalea Ltd Locn.:Room 18	Not marked	 a) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects. 		
L0160	L96АНН	Personnel Sling Chiltern Locn.:Room 18	Not marked	 a) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects. 		
L0161	L96АНН	Personnel Sling Chiltern Locn.:Room 18	Not marked	 a) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects. 		

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 04 Jan 2018 Date of Last Examination: 18 May 2017 Inspecting Engineer: Mr C White Date of Next Examination: 04 Jul 2018

C White Signature:

Qualification: Engineer Surveyor



New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 130617-014-0004SB2

Site: 00001 Report Number: 080118-010-0007GM4 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
	TRACKS L42AHH	Runway Track Locn.:Room 39	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0089	L42АНН	Runway Track Locn.:Room 29	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0090	L42AHH	Runway Track Locn.:Room 32	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0091	L42AHH	Runway Track Locn.:Room 21	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0092	L42AHH	Runway Track Locn.:Room 22	200 kg (as marked)	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0094	L42AHH	Runway Track Locn.:Room 33	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0095	L42AHH	Runway Track Locn.:Room 19	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0096	L42AHH	Runway Track Locn.:Hawthorn App	Not marked	la) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.


Date of Examination:04 Jan 2018Date of Last Examination:18 May 2017Inspecting Engineer:Mr C WhiteDate of Next Examination:04 Jul 2018

Signature:

4SBEI-1029-1214-3

- White

Qualification: Engineer Surveyor



New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510







REPORT OF DELETED ITEMS





Policy: H8L200921 Previous Report: ----

Site: 00001 Report Number: 080118-011-0007GM4 DELI1

Occupier BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Sched No.	Plant Code	Item	Remarks
L0088	L42AHH	Runway Track	Deleted from site plant schedule.
L0093	L42AHH	Runway Track	Deleted from site plant schedule.
L0010	L73AHH	Personnel Hoist S.No.:17090724 P.No.:9 SWL: 200 kg	Deleted from site plant schedule.
L0109	L96АНН	Personnel Sling S.No.:1EU00890246 P.No.:05 SWL: 200 kg	Deleted from site plant schedule.

I/we hereby advise that the above items of equipment have been deleted from the plant schedule with effect from the date(s) shown.

Date 04 Jan 2018
Inspecting Engineer: Mr C White

Signature:

Qualification: Engineer Surveyor







C While

REPORT OF NON-INSPECTED ITEMS





Policy: H8L200921 **Previous Report:** 130617-010-0004SB2

Site: 00001 Report Number: 080118-012-0007GM4 RONI1

Occupier BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Sched No.	Plant Code	Item	Remarks
PERSON	NEL SLI	NGS	
L0113	L96AHH	Personnel Sling S.No.:740311000300015	Not located at site.
		P.No.:48 SWL: 272 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0120	L96AHH	Personnel Sling S.No.:LOC0080/29	Not located at site.
		P.No.:41 SWL: 175 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0121	L96AHH	Personnel Sling	Not located at site.
		S.No.:L0C0081-1 P.No.:12 SWL: 175 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0123	L96AHH	H Personnel Sling S.No.:30 P.No.:39 SWL: 203 kg	Not located at site.
			Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0124	L96АНН	Personnel Sling S.No.:SGP001-1 P.No.:36 SWL: 200 kg	Not located at site.
			Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0125	L96AHH	Personnel Sling S.No.:SGP001-1 P.No.:03 SWL: 200 kg	Not located at site.
			Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0137	L96АНН	Personnel Sling S.No.:741214000300041	Not located at site.
		S.No.:/41214000300041 P.No.:81 SWL: 272 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0139	L96AHH	Personnel Sling	Not located at site.
		S.No.:77117081266798 P.No.:08 SWL: 200 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0140	L96AHH	Personnel Sling S.No.:7737081565748	Not located at site.
		P.No.:18 SWL: 190 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION

We hereby advise that the above items of equipment have not recently been examined or inspected, and the status of previous certification or examination/inspection reports should be determined prior to returning the items to service.

Date: 04 Jan 2018 Date of Last Examination: 18 May 2017

Inspecting Engineer: Mr C White

Signature:

HSB Engineering Insurance Services Limited is accredited by the United Kingdom Accreditation Service



Qualification: Engineer Surveyor





Telephone: 0845 345 5510

4SBEI-1029-1214-3

REPORT OF NON-INSPECTED ITEMS





Previous Report: 130617-013-0004SB2

RONI1 Site: 00001 Report Number: 080118-013-0007GM4

Occupier BIRTLEY HOUSE GROUP LTD

Policy: H8L200921

Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Sched			
No.	Code	Item	Remarks
	NEL SLI		Wet lead to the
L0142	Г 96АНН	Personnel Sling S.No.:40600	Not located at site.
		P.No.:15 SWL: 190 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0146	L96AHH	Personnel Sling S.No.:102071891438	Not located at site.
		P.No.:40 SWL: 228 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0152	L96AHH	Personnel Sling S.No.:027	Not located at site.
		P.No.:03 SWL: 203 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0153	L96АНН	Personnel Sling S.No.:140359	Not located at site.
		P.No.:06 SWL: 220 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0155	L96AHH	Personnel Sling S.No.:0234302002	Not located at site.
		P.No.:99 SWL: 200 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION
L0157	L96АНН	Personnel Sling S.No.:8015/MS0345	Not located at site.
		S.No.:8015/MS0345 P.No.:11 SWL: 190 kg	Please advise when available for statutory examination, contact our Engineer Surveyor, C White on 07515 922043. THIS IS NOT A STATUTORY REPORT OF THOROUGH EXAMINATION

We hereby advise that the above items of equipment have not recently been examined or inspected, and the status of previous certification or examination/inspection reports should be determined prior to returning the items to service.

Date: Date of Last Examination: 18 May 2017 04 Jan 2018

Inspecting Engineer: Mr C White

Signature: - White Qualification: Engineer Surveyor







Telephone: 0845 345 5510

4SBEI-1029-1214-3