

## Fire Extinguisher

## **Certificate of Inspection**

Client and Jo	b Details									
Contract Client	0809 BIRTLEY HOUSE GROUP LTD				Job Number 12343 Call Type Routine Maintenance					
	BIRTLEY HOUSE				Appointment Date/Time 13/07/18 09:50				ı	
	BRAMLEY				Reported R					
	GUILDFORD					DA)TO BO	OK EMAIL I	helpdesk@	hunterfm.co.uk	(FAO
	SURREY				SHANNON					
	GU5 0LB				CSD = 30	EDVICE 2	Y W/13/ 2 Y	COG INI G	REAT BARN (	DEFICES
Contact	TIM WHALLEY				BIRTHLEY			( 020 IIV C	INCAT DANN	JI I IOLO
Telephone 	Car @Linta da coma a contr				=					
email System Detai	tim@birtleyhouse.co.uk									
System Type	Fire Extinguisher									
Service Chec	-	⋉ False/I	No F	□ N/A						
		_	-	_	Danfanna	dia ah anna	11			
	xtinguisher against weight and top cap for corrosion o			☑ ☑	Perform a discharge test					
1	e gauge for correct operatin	•		<b>☑</b>	Examine body internally especially welds  Check the extinguisher body is in date					<b>⊻</b>
	g mechanism and squeeze	• .		<u>.</u> ☑	Remove cartridge and check if in date/condition					
	pin and fit new seal	J. 1		<b>☑</b>	Check liquid levels and top up if necessary					
Replace washe	•			<u></u> ✓	Unwind and inspect hose apparatus for damage					
Grease and ma	ke free all working parts				Check reel i.e. mounting brackets					
	rms have sufficient friction				Check nozzle for correct operation					
	t holes are clear from obstru			V	Remove blanket from holder and visually inspect  ☑					
	extinguisher according to ri	sk		Ø	Changed Safety Pin and OK Indicator					
	her down with clean cloth			<b></b> ✓	Complete on-site log book  ☑					
Record type of service, weight, date and initials on label				☑ ☑						
Elisure extiligu	Ensure extinguisher is wall mounted or in stand  ☑									
We hereby certify that apart from non-conforming ext as recorded, the Fire Extinguishing appliances as set out below have been inspected and serviced in accordance with BS EN 5306:3										
Equipment Ins	pected	Qty	Qty	Svs	Svs	Svs	Svs	Svs	Comments	
Description		Expected	Found	Action1	Action2	Action3	Action4	Action5		
DRY POWDER EX		5	5	SVS	CON					
AFFF FOAM EXTIN		4	4	SVS	2011					
CO2 EXTINGUISH	ERS	19	21	SVS	CON					
FIRE BLANKETS	N/TIMO HOUSE DO	1	1	CON	01/0	2011				
WATER / SPRAY E	:XTINGUISHERS Svs Actions - SVS - Basic S	19	18 Fire Blo	DTR	SVS	CON	Sorvino O	Overhoud	od BC Book	argod C
	on Required, CON - Condem									
Customer Re	port									
Engineers findings & actions W						Was a fire risk assessment report available to engineer at the □				
13/07/2018 09:00:00 John Davies					time of maintenance					
Job For Client BIRTLEY HOUSE GROUP LTD Note 7 x 2kg co2, 1 x 3l water plus 1 x 6kg powder due 10yr refurb replaced.					Are additional Class A (water based) extinguishers required □ to conform with current British Standard BS5306-8 8.2.1					
	2, 1 x 3l water plus 1 x 6kg po te fireblanket replaced. 4 x mi			epiacea.	to conform	with curre	ent British	Standard I	BS5306-8 8.2.1	ı

BATE BATE

Visit our website on www.eflfire.co.uk

Unit 17 Northbrook Business Park, Worthing, West Sussex, BN14 8PQ



## Fire Extinguisher

## **Certificate of Inspection**

Parts Used		
Description	Item Code	Qty
Sealing Ties	SR-1044	38
Horn Washer 2-5Kg Co2	SR-1035	14
Gauge Test	SR-1038	24
Hose O Ring	SR-1034	24
Sealing O Ring	SR-1033	1
Water with additive kit 3-6L	SR-1014	1
Powder ID	SI-1017P	1
CO2 ID	SI-1017C	1
Fire Blanket ID	SI-1017FB	1
Foam ID	SI-1017F	1
1m x 1m blanket (202600)	ANC-1000	1
2Kg Co2 (100400)	EX-1011	7
3L Water spray (100825)	EX-1001	1
6Kg Powder (101600)	EX-1009	1

Timesheets Date on Site	Arrival	Departure	Customer Name / Signature	Engineers Name / Signature
13/07/2018	09:00:00	14:55:00	Tim Whalley	John Davies

Visit our website on www.eflfire.co.uk
Unit 17 Northbrook Business Park, Worthing, West Sussex, BN14 8PQ

General Enquiries Tel: 08458739973 Accounts Tel: 01903 830664 Fax: 01903 244008 Job Number 12343