'friendly, local service...nationwide'



3/19, Ropery Business Park,

Telephone 020 8293 4176

Anchor and Hope Lane, London, SE7 7RX Web www.jacksonlifts.com

Service Attendance Form

Site Details

MNumber: M54079

Site Name: Birtley House Site Address: Bramley

Site Postcode: GU3 0LB

Customer Lift Ref: HPL Passenger Lift No 2

Property Code:

Site Contact: Mark Teverson

Engineer: 0728

225 Route No:

Supervisor: Tony Moore

Contract Type: A+

Service Work Details

Main Ropes/Chains

Wiring/Flexes

Service Type:

Visit Month: April

Worn but Serviceable Winding/Pump Unit Worn but Serviceable

Door Operator

Worn but Serviceable Controller

Date: 30/04/18 Safety/Governor Rope

Worn but Serviceable Worn but Serviceable Worn but Serviceable

The service inspection type undertaken during this visit was type Z - Items visually checked during this visit may include (but are not limited to), controller, motors/generators, main sheave, winding gear, brake unit, car entrances, door/gate operators, safety gear/guides, lift alarm, landing entrances, landing protection, and shaft equipment. For a full break down of this service

plan, please check your Jackson Lift Service Plan & Method Statement.

Other Work Completed this Visit

Due

Completed

Last Test Result

Insurance Items:

Safety Test:

30/08/19

30/08/18

Satisfactory

Autodialler

Test Results:

Installed No

Audible Alarm Functional

Line Functional

Calls JLG helpdesk

Comments

General Remarks

CAR COMMUNICATIONS REQUIRED

Sign Off

Engineer Name: Signature:

Steve Cooper

Client Name:

Signature:



