

Fire Extinguisher

Certificate of Inspection

Client and Jol	b Details				
Contract Client	0809 EYHURST COURT LTD BIRTLEY HOUSE BRAMLEY GUILDFORD SURREY GU5 0LB		Job Number Call Type Appointment Date/Time Reported Reason For Call -	-5408 Routine Maintenance 02/06/17	07:19
Contact	TIM WHALLEY		-		
Telephone email	01483 892 055				
	tim@birtleyhouse.co.uk				
System Detail	S				
System Type	Fire Extinguisher				
Service Checl	ks 🗹 True/Yes 🗵 F	alse/No 🔲 N/A			
Check/weigh extinguisher against weight record Examine body and top cap for corrosion or damage Check pressure gauge for correct operating pressure Check operating mechanism and squeeze grip handle Remove safety pin and fit new seal Replace washers and o'rings Grease and make free all working parts Check swivel arms have sufficient friction Check any vent holes are clear from obstruction Check correct extinguisher according to risk Wipe extinguisher down with clean cloth Record type of service, weight, date and initials on label Ensure extinguisher is wall mounted or in stand		Perform a discharge test Examine body internally esp Reassemble and return to op Check the extinguisher body Remove cartridge and check Check liquid levels and top of Unwind and inspect hose ap Check reel i.e. mounting bra Check nozzle for correct ope Remove blanket from holder Changed Safety Pin and OK Complete on-site log book	V V V X X X X X X V		

serviced in accordance with BS EN 5306:3

Equipment Inspected Description	Qty Expected	Qty Found	Svs Action1	Svs Action2	Svs Action3	Svs Action4	Svs Action5	Comments
DRY POWDER EXTINGUISHERS	5	4	SVS-4	CON-1				out of service date / replaced.
AFFF FOAM EXTINGUISHERS	4	4	SVS-4	CON-2				out of service date / replaced
CO2 EXTINGUISHERS	19	21	SVS-21					
FIRE BLANKETS	1	1	FBS-1					
WATER / SPRAY EXTINGUISHERS	19	18	SVS-16	DTR-2	CON-1			out of service date.

Key Codes For Svs Actions - SVS - Basic Service, FBS - Fire Blanket Service, DTR - Extended Service, O - Overhauled, RC - Recharged, C -Corrective Action Required, CON - Condemned, MI - Missing, EXC - Exchanged (like for like), REP - Replaced (Alternative Item), NE - New.

Customer Report	
Engineers findings & actions 02/06/2017 07:33:00 David Gladwin Job For Client EYHURST COURT LTD relocated 1 x 2kg co2 from inside lift motor room to 1st floor nurses office.	Further visit required+when ☐ Further Action Required by Customer
	Work To be Completed







Visit our website on www.eflfire.co.uk











Fire Extinguisher

Certificate of Inspection

Parts Used Description	Item Code	Qty
Sealing Ties	SR-1044	43
Horn Washer 2-5Kg Co2	SR-1035	21
Gauge Test	SR-1038	22
Hose O Ring	SR-1034	22
Water with additive kit 3-6L	SR-1014	2
6L Stored pressure foam (101400)	EX-1003	2
6Kg Powder (101600)	EX-1009	1
3L Water spray (100825)	EX-1001	1

Timesheets Date on Site	Arrival	Departure	Customer Name / Signature	Engineers Name / Signature
02/06/2017	07:33:00	12:17:00	Tim Whalley	David Gladwin

Job Number -5408











