

Our Ref.: H8L200921/1/RK/SB2/LSE Date: 13th June 2017

BIRTLEY HOUSE GROUP LTD Birtley House Birtley Road Bramley Guildford Surrey GU5 0LB

For the attention of Tim Whalley

Inspection Details

Type : Policy

Number : H8L200921-1 Report Nos.: 001-015

Class : Lifting & Handling Plant

Surveyor : Mr R Kidd

Date : 18th May 2017 - 19th May 2017

Location : As above

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the method statements documented in Section 13.5 of the Company Quality Procedures.

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.



Web: www.hsbeil.com

REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT





as required by the Lifting Operation and Lifting Equipment Regulations 1998; or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999; or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: H8L200921 Plant Code: L27AHH Previous Report: 240217-001-0002SK1

Schedule: T.0001 Site: 00001 Report Number: 130617-001-0004SB2 I OI 54

Sit	te: 00001 Schedule:	L0001 Report Number: 130617-001-0004SB2 LOL54
Em	nployer (or owner) of premises	BIRTLEY HOUSE GROUP LTD
Ad	Idress	Birtley House, Birtley Road Bramley, Guildford Surrey, GU5 0LB
1.	(a) Type of hoist or lift and identification number and description	Passenger/Goods Lift Hydraulic
	(b) Date of construction or reconstruction (if ascertainable)	Carlton Lifts Serial No.:- GB4508 Unknown
2.	(a) Is this the first thorough examination following installation of the equipment at the above site/location?	No
	(b) Were examinations in accordance with an examination scheme?	No
3.	Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use. (a) Enclosure of hoistway or liftway.	Yes
	(b) Landing gates and cage gate(s).	Yes - But a suitable landing barrier should be made available.
	(c) Interlocks on the landing gates and cage gate(s).	Yes
	(d) Other gate fastenings.	Yes
	(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes - But replenish oil lubrication pots.
	(f) Over-running devices.(g) Suspension ropes or chains, and their attachments.	No - The engineers upper limit switch must be returned to service to allow safe escape from the car top. $\ensuremath{\mathrm{N/a}}$
	(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes - Visual inspection, Rupture valve.
	(j) Brakes.	N/a
	(k) Worm or spur gearing.	N/a
	(I) Other electrical equipment.	No - The pit prop interlock should be returned to service. Car lighting to be returned to full service.
	(m) Other parts.	No - Refit missing lift motor room door and associated signage.
4.	What parts (if any) were inaccessible?	Enclosed electrical and mechanical parts
5.	Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None"):-	
	(a) defects found which give rise to imminent danger and require attention immediately.	None
	(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None
6.	Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	630kg/8 Persons (As marked)
7.		The auto dialler should be returned to service. Hydraulic ram seal weeping - monitor.
Th	is is to cartify that on the data of examination the he	nist or lift was thoroughly examined and unless otherwise indicated above, was safe to

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 19 May 2017


Inspecting Engineer: Mr R Kidd

Signature:

Date of Last Examination: 14 Feb 2017

Date of Next Examination: 19 Nov 2017

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510







REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT





HSB Engineering Insurance

as required by the Lifting Operation and Lifting Equipment Regulations 1998; or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999; or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: H8L200921 Plant Code: L27AHH Previous Report: 061216-012-0001LM1

Site	e: 00001 Schedule:	L0098	Report Number: 130617-002-0004SB2	LOL54
Em	nployer (or owner) of premises	BIRTLEY HOU	SE GROUP LTD	
Ad	dress	Birtley Hou Bramley, Gu Surrey, GU5		
1.	(a) Type of hoist or lift and identification number and description	Passenger/G	oods Lift Hydraulic	
	(b) Date of construction or reconstruction (if ascertainable)	Northern Li Serial No.: Unknown		
2.	(a) Is this the first thorough examination following installation of the equipment at the above site/location?	No		
	(b) Were examinations in accordance with an examination scheme?	No		
3.	Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use. (a) Enclosure of hoistway or liftway.	Yes		
	(b) Landing gates and cage gate(s).	Yes		
	(c) Interlocks on the landing gates and cage gate(s).	Yes		
	(d) Other gate fastenings.	Yes		
	(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes, but da	mage noted to the ram head guide bracket.	
	(f) Over-running devices.	Yes		
	(g) Suspension ropes or chains, and their attachments.	Yes		
	(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes - visua	linspection	
	(j) Brakes.	N/A		
	(k) Worm or spur gearing.	N/A		
	(I) Other electrical equipment.		suitable electrical isolation mat should be placed b	elow
	(m) Other parts.	the control Yes	capinet.	
4.	What parts (if any) were inaccessible?	Enclosed el	ectrical and mechanical parts	
5.	Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-			
	(a) defects found which give rise to imminent danger and require attention immediately.	None		
	(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period	None		
6.	Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	630kg / 8 F	ersons (as marked)	
7.	Other observations	The governo	r rope was splintered - advise renew.	
=				

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 19 May 2017


Inspecting Engineer: Mr R Kidd

Signature:

Date of Last Examination: 16 Nov 2016

Date of Next Examination: 19 Nov 2017

Qualification: Engineer Surveyor



Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510







REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT





as required by the Lifting Operation and Lifting Equipment Regulations 1998; or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999; or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: H8L200921 Plant Code: L27AHH Previous Report: 061216-013-0001LM1

Site: 00001 Schedule: L0002 **Report Number:** 130617-003-0004SB2 LOL54

311	s. 00001 Scriedule.	L0002	Report Number. 130617-003-00045B2	LUL34
En	ployer (or owner) of premises	BIRTLEY HOUSE GROUP LT	CD	
Ad	dress	Birtley House, Birtley Bramley, Guildford Surrey, GU5 OLB	Road	
1.	(a) Type of hoist or lift and identification number and description	Passenger/Goods Lift	Hydraulic	
		Stannah Serial No.:- 270423		
	(b) Date of construction or reconstruction (if ascertainable)	2008		
2.	(a) Is this the first thorough examination following installation of the equipment at the above site/location?	No		
	(b) Were examinations in accordance with an examination scheme?	No		
3.	Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use. (a) Enclosure of hoistway or liftway.	Yes		
	(b) Landing gates and cage gate(s).	Yes		
	(c) Interlocks on the landing gates and cage gate(s).	Yes		
	(d) Other gate fastenings.	Yes		
	(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes		
	(f) Over-running devices.	Yes		
	(g) Suspension ropes or chains, and their attachments.	Yes		
	(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes - Visual inspection	n	
	(j) Brakes.	N/A		
	(k) Worm or spur gearing.	N/A		
	(I) Other electrical equipment.	See Plant Report Conti	nuation	
	(m) Other parts.	Yes		
4.	What parts (if any) were inaccessible?	Enclosed electrical ar	d mechanical parts	
5.	Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None"):-			
	(a) defects found which give rise to imminent danger and require attention immediately.	None		
	(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None		
6.	Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	1000kg / 13 Persons (a	s marked)	
7.	Other observations	Shaft Lifting Beam S/N apparent defects.	o: 5015, safe working load: 1000kg. No)

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 19 May 2017

Inspecting Engineer: Mr R Kidd

Signature:

Date of Last Examination: 16 Nov 2016 Date of Next Examination: 19 Nov 2017

Qualification: Engineer Surveyor





Telephone: 0845 345 5510

PLANT REPORT CONTINUATION





Policy: H8L200921 Plant Code: L27AHH Previous Report: ---

Schedule: L0002 Site: 00001 Report Number: 130617-003-0004SB2

Occupier BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road Bramley, Guildford Surrey, GU5 OLB

PRC1

Section Remarks

3(1) Yes - but electrical isolation mat should be made available to place below the control cabinet. An approved lift motor room sign should be placed on the lift control cabinet door.

Date of Examination: 19 May 2017 Date of Last Examination: 16 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 19 Nov 2017

The Widd Signature:

Qualification: Engineer Surveyor











Policy: H8L200921 Previous Report: ----

Site: 00001 Report Number: 130617-004-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
L0150	L96АНН	Personnel Sling S.No.:931147 P.No.:92	200 kg	a) None b) None General: Clearly mark with safe working load
L0151	L96АНН	Personnel Sling S.No.:22116078036 P.No.:22	190 kg	a) None b) None General: Clearly mark with safe working load
L0152	L96АНН	Personnel Sling S.No.:027 P.No.:03	203 kg	a) None b) None General: Clearly mark with safe working load
L0153	L96АНН	Personnel Sling S.No.:140359 P.No.:06	220 kg	a) None b) None General: Clearly mark with safe working load
L0154	L96АНН	Personnel Sling S.No.:221116099041 P.No.:77	200 kg	a) None b) None General: Clearly mark with safe working load
L0155	L96АНН	Personnel Sling S.No.:0234302002 P.No.:99	200 kg	a) None b) None General: Clearly mark with safe working load
L0156	L96АНН	Personnel Sling S.No.:931148 P.No.:55	200 kg	a) None b) None General: Clearly mark with safe working load
L0157	L96АНН	Personnel Sling S.No.:8015/MS0345 P.No.:11	190 kg	a) None b) None General: Clearly mark with safe working load
L0158	L96АНН	Personnel Sling S.No.:0205446 Silvalea Ltd Locn.:Room 18	Not mark	ed a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0159	L96АНН	Personnel Sling Silvalea Ltd Locn.:Room 18	Not mark	ed a) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: n/a

Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

Ju Hidd Signature: Qualification: Engineer Surveyor

New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510

is accredited by the United Kingdom Accreditation Service











Policy: H8L200921 Previous Report: ----

Site: 00001 Report Number: 130617-005-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the

(b) Dele	b) Defects round which could, in time, give rise to danger and require attention within the specified time period.			
Sched No.	Plant Code	Item	SWL	Particulars of any defect
L0160	L96АНН	Personnel Sling Chiltern Locn.:Room 18	Not marked	a) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects.
L0161	L96АНН	Personnel Sling Chiltern Locn.:Room 18	Not marked	la) None b) None General: Clearly mark with serial number or plant number and safe working load No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: n/a

Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

Ju Hidd Signature: Qualification: Engineer Surveyor

New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 061216-014-0001LM1

Site: 00001 Report Number: 130617-006-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 0LB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the

Sched Plant				
No.	Code	Item	SWL	Particulars of any defect
BATH F L0004	IOISTS L73AHH	Bath Hoist S.No.:8662345/1309000986	130 kg	a) None b) None General: No apparent defects.
L0005	L73AHH	Bath Hoist S.No.:VEPL00003264	130 kg	a) None b) None General: No apparent defects.
L0006	L73AHH	Bath Hoist S.No.:1205000361	130 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Inspecting Engineer: Mr R Kidd

Ju Hidd

Date of Last Examination: 24 Nov 2016 Date of Next Examination: 18 Nov 2017

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited is accredited by the United Kingdom Accreditation Service







Signature:





Policy: H8L200921 Previous Report: 061216-015-0001LM1

Site: 00001 Report Number: 130617-007-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the specified time period

Sched Pla			01:"	
No. Co		Item	SWL	Particulars of any defect
PERSONNEL L0007 L73		Personnel Hoist S.No.:0907001386 P.No.:12 Arjo	170 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0008 L73	ЗАНН	Personnel Hoist S.No.:LD451289471 P.No.:13 Locn.:Room 39	272 kg	a) None b) None General: No apparent defects.
L0009 L73	ЗАНН	Personnel Hoist S.No.:7090089 P.No.:10	175 kg	a) None b) None General: No apparent defects.
L0010 L73	ЗАНН	Personnel Hoist S.No.:17090724 P.No.:9 Locn.:Room 30	200 kg	a) Noneb) NoneGeneral:Lifting tape creased - monitor.No other apparent defects.
L0011 L73	ЗАНН	Personnel Hoist S.No.:17090721 P.No.:6 Locn.:Room 29	200 kg	a) None b) None General: No apparent defects.
L0012 L73	ЗАНН	Personnel Hoist S.No.:STLA0712G653 P.No.:1	200 kg	a) None b) None General: No apparent defects.
L0013 L73	ЗАНН	Personnel Hoist S.No.:091105865994 P.No.:11	170 kg	a) None b) None General: No apparent defects.
L0014 L73	ЗАНН	Personnel Hoist S.No.:VOYA-11319 Sunrise Locn.:Room 21	200 kg	 a) None b) None General: Lifting tape creased and one retaining bracket damaged - monitor otherwise serviceable. No other apparent defects.
L0015 L73	ЗАНН	Personnel Hoist S.No.:LD451289461 P.No.:14 Locn.:Room 22	272 kg	a) None b) None General: No apparent defects.
L0016 L73	ЗАНН	Personnel Hoist S.No.:LD451289470 P.No.:2 Locn.:Room 19	272 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: 24 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

In Widd Signature:

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 061216-016-0001LM1

Site: 00001 Report Number: 130617-008-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.
(b) Defects found which could, in time, give rise to danger and require attention within the specified time period


Sched	Plant						
No.	Code	Item	SWL	Particulars of any defect			
PERSON	PERSONNEL HOISTS						
L0017	L73AHH	Personnel Hoist S.No.:SEE0648344 P.No.:4	220 kg	a) None b) None General: Clearly mark with safe working load. No other apparent defects.			
L0018	L73AHH	Personnel Hoist S.No.:11GSZ100037 P.No.:5	159 kg	a) None b) None General: No apparent defects.			
L0019	L73AHH	Personnel Hoist S.No.:300015775 Locn.:Hawthorn App	272 kg	a) None b) None General: No apparent defects.			
L0020	L73AHH	Personnel Hoist S.No.:STLA0804G272 P.No.:3	200 kg	a) None b) None General: No apparent defects.			

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: As above Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

In Kidd Signature:

Qualification: Engineer Surveyor



New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 290317-001-0003JCH

Site: 00001 Report Number: 130617-009-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched Plant No. Code	Item	SWL	Particulars of any defect
		SVVL	Particulars of any defect
PERSONNEL SL L0149 L73AHH	Personnel Hoist S.No.:17090719 P.No.:8 Locn.:Room 33	200 kg	a) None b) None General: Hesitant when lifting. No other apparent defects. Date of Last Examination- 14 Mar 2017
L0021 L73AHH	Personnel Hoist S.No.:17090718 Locn.:Room 32	200 kg	a) None b) None General: Lifting tape slightly creased. No other apparent defects. Date of Last Examination- 14 Mar 2017
L0127 L96АНН	Item of Safety Equipment S.No.:SL2731060071 P.No.:47	227 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016
L0099 L96АНН	Personnel Sling S.No.:74031100030001 P.No.:46	272 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016
L0100 L96АНН	Personnel Sling S.No.:770907821608 P.No.:38	190 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016
L0101 L96АНН	Personnel Sling S.No.:7404110046000094 P.No.:16	272 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016
L0102 L96АНН	Personnel Sling S.No.:740411004600030 P.No.:21	272 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016
L0103 L96АНН	Personnel Sling S.No.:741210008400002 P.No.:35	272 kg	a) None b) None General: No apparent defects. Date of Last Examination- 24 Nov 2016

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: As above Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

In Widd Signature:

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP

Registered as a branch in Ireland: 906105 Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 061216-017-0001LM1

Site: 00001 Report Number: 130617-010-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
	INEL SLI L96AHH	NGS Personnel Sling S.No.:740411004600130 P.No.:32	272 kg	a) None b) None General: No apparent defects.
L0105	L96АНН	Personnel Sling S.No.:SL1513090213 P.No.:86	272 kg	a) None b) None General: No apparent defects.
L0106	L96АНН	Personnel Sling S.No.:SL2511070127 P.No.:04	227 kg	a) None b) None General: No apparent defects.
L0107	L96АНН	Personnel Sling S.No.:101A P.No.:42	160 kg	a) None b) None General: No apparent defects.
L0108	L96АНН	Personnel Sling S.No.:740311000300036 P.No.:29	272 kg	a) None b) None General: No apparent defects.
L0109	L96АНН	Personnel Sling S.No.:1EU00890246 P.No.:05	200 kg	a) None b) None General: No apparent defects.
L0110	L96АНН	Personnel Sling S.No.:SL164312080325 P.No.:25	227 kg	a) None b) None General: No apparent defects.
L0111	L96АНН	Personnel Sling S.No.:220314004700016 P.No.:19	190 kg	a) None b) None General: No apparent defects.
L0112	L96АНН	Personnel Sling S.No.:MAA4031/XL P.No.:28	190 kg	a) None b) None General: No apparent defects.
L0113	L96АНН	Personnel Sling S.No.:740311000300015 P.No.:48	272 kg	a) None b) None General: No apparent defects.
L0114	L96АНН	Personnel Sling S.No.:1017 P.No.:14	190 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: 24 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

Signature:

HSBEI-1029-1214-3

In Widd

Qualification: Engineer Surveyor





Registered as a branch in Ireland: 906105 Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited is accredited by the United Kingdom

Accreditation Service





Previous Report: 061216-018-0001LM1

Site: 00001 Report Number: 130617-011-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Policy: H8L200921

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
PERSON L0115	NEL SLI L96AHH	NGS Personnel Sling S.No.:740910015000046 P.No.:49	272 kg	a) None b) None General: No apparent defects.
L0116	L96AHH	Personnel Sling S.No.:1030 P.No.:09	160 kg	a) None b) None General: No apparent defects.
L0117	L96AHH	Personnel Sling S.No.:LOT7402150028 P.No.:10	272 kg	a) None b) None General: No apparent defects.
L0118	L96АНН	Personnel Sling S.No.:7411140031 P.No.:83	272 kg	a) None b) None General: No apparent defects.
L0119	L96АНН	Personnel Sling S.No.:LOT2203150239 P.No.:67	200 kg	a) None b) None General: No apparent defects.
L0120	L96АНН	Personnel Sling S.No.:L0C0080/29 P.No.:41	175 kg	a) None b) None General: No apparent defects.
L0121	L96АНН	Personnel Sling S.No.:L0C0081-1 P.No.:12	175 kg	a) None b) None General: No apparent defects.
L0122	L96АНН	Personnel Sling S.No.:L0C0080/31 P.No.:2	175 kg	a) None b) None General: No apparent defects.
L0123	L96АНН	Personnel Sling S.No.:30 P.No.:39	203 kg	a) None b) None General: No apparent defects.
L0124	L96АНН	Personnel Sling S.No.:SGP001-1 P.No.:36	200 kg	a) None b) None General: No apparent defects.
L0125	L96AHH	Personnel Sling S.No.:SGP001-1 P.No.:03	200 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: 24 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

In Widd Signature:

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Previous Report: 061216-019-0001LM1

Site: 00001 Report Number: 130617-012-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Policy: H8L200921

Address Birtley House, Birtley Road Bramley, Guildford

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.		Item	SWL	Particulars of any defect
PERSON	NNEL SLI	NGS	•	
L0126	L96АНН	Personnel Sling S.No.:20 P.No.:20	200 kg	a) None b) None General: No apparent defects.
L0128	L96АНН	Personnel Sling S.No.:SL2712100242 P.No.:26	227 kg	a) None b) None General: No apparent defects.
L0129	L96АНН	Personnel Sling S.No.:IEU00905469 P.No.:44	200 kg	a) None b) None General: Belt clip missing - refit. No other apparent defects.
L0130	L96АНН	Personnel Sling S.No.:IEU009005 P.No.:95	200 kg	a) None b) None General: No apparent defects.
L0131	L96АНН	Personnel Sling S.No.:0101 P.No.:07	175 kg	 a) None b) None General: Velcro stitching worn - monitor, otherwise serviceable. No other apparent defects.
L0132	L96АНН	Personnel Sling S.No.:SL1642212100178 P.No.:50	227 kg	a) None b) None General: No apparent defects.
L0133	L96АНН	Personnel Sling S.No.:SL164214080133 P.No.:88	227 kg	a) None b) None General: No apparent defects.
L0134	L96АНН	Personnel Sling S.No.:M4000-LL-1 P.No.:30	272 kg	a) None b) None General: No apparent defects.
L0135	L96АНН	Personnel Sling S.No.:8822084880373 P.No.:31	272 kg	a) None b) None General: No apparent defects.
L0136	L96АНН	Personnel Sling S.No.:24 P.No.:24	190 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination:18 May 2017Date of Last Examination:24 Nov 2016Inspecting Engineer:Mr R KiddDate of Next Examination:18 Nov 2017

Signature: In High

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Policy: H8L200921 Previous Report: 061216-020-0001LM1

Site: 00001 Report Number: 130617-013-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
	NEL SLI L96AHH	NGS Personnel Sling S.No.:741214000300041 P.No.:81	272 kg	a) None b) None General: No apparent defects.
L0138	L96AHH	Personnel Sling S.No.:TSS.503 P.No.:68	200 kg	a) None b) None General: No apparent defects.
L0139	L96AHH	Personnel Sling S.No.:77117081266798 P.No.:08	200 kg	a) None b) None General: No apparent defects.
L0140	L96АНН	Personnel Sling S.No.:7737081565748 P.No.:18	190 kg	a) None b) None General: No apparent defects.
L0141	L96АНН	Personnel Sling S.No.:220412016 P.No.:37	190 kg	a) None b) None General: No apparent defects.
L0142	L96АНН	Personnel Sling S.No.:40600 P.No.:15	190 kg	a) None b) None General: No apparent defects.
L0143	L96АНН	Personnel Sling S.No.:741210008400007 P.No.:70	272 kg	a) None b) None General: No apparent defects.
L0144	L96АНН	Personnel Sling S.No.:7412108400025 P.No.:34	272 kg	a) Noneb) NoneGeneral:No apparent defects.
L0145	L96АНН	Personnel Sling S.No.:741210008400013 P.No.:33	272 kg	a) Noneb) NoneGeneral:No apparent defects.
L0146	L96АНН	Personnel Sling S.No.:102071891438 P.No.:40	228 kg	a) None b) None General: No apparent defects.
L0147	L96AHH	Personnel Sling S.No.:882208480378 P.No.:63	272 kg	a) None b) None General: No apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: 24 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

Signature:

HSBEI-1029-1214-3

In Widd

Qualification: Engineer Surveyor





Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510





Policy: H8L200921 Previous Report: 061216-022-0001LM1

Site: 00001 Report Number: 130617-014-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
RIINWAY	Y TRACKS			
		Runway Track Locn.:Room 39	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0088	L42AHH	Runway Track Locn.:Room 30	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0089	L42AHH	Runway Track Locn.:Room 29	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0090	L42AHH	Runway Track Locn.:Room 32	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0091	L42AHH	Runway Track Locn.:Room 21	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0092	L42AHH	Runway Track Locn.:Room 22	200 kg (as marked)	a) None b) None General: Clearly mark with safe working load. No other apparent defects.
L0093	L42AHH	Runway Track Locn.:Room 32	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0094	L42AHH	Runway Track Locn.:Room 33	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.
L0095	L42AHH	Runway Track Locn.:Room 19	Not marked	a) None b) None General: Clearly mark with identification and safe working load. No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination:18 May 2017Date of Last Examination:24 Nov 2016Inspecting Engineer:Mr R KiddDate of Next Examination:18 Nov 2017

Signature: Julied

Qualification: Engineer Surveyor



Registered in England and Wales: 03010292, New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510











Previous Report: 061216-023-0001LM1

Site: 00001 Report Number: 130617-015-0004SB2 LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).

The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).

The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer BIRTLEY HOUSE GROUP LTD

Address Birtley House, Birtley Road

Bramley, Guildford Surrey, GU5 OLB

Were examinations in accordance with an examination scheme?

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched Plant SWL Particulars of any defect No. Code Item

Policy: H8L200921

RUNWAY TRACKS L0096 L42AHH Runway Track Not marked a) None Locn.: Hawthorn App b) None

General:

Clearly mark with identification and safe working load. No other apparent defects.

This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 18 May 2017 Date of Last Examination: 24 Nov 2016 Inspecting Engineer: Mr R Kidd Date of Next Examination: 18 Nov 2017

In Widd Signature: Qualification: Engineer Surveyor

New London House, 6 London Street, London EC3R 7LP Registered as a branch in Ireland: 906105

Telephone: 0845 345 5510





