

Client and Job Details

## **Fire Alarm Certificate of Inspection**

Fire Alarm serviced in accordance with BS 5839 PT1

Client E	2007			Lab Namebon 45750		
	Contract 3007			Job Number         15756           Appointment Date/Time         23/01/19         09:00		
F	BIRTLEY HOUSE GROUP LTD BIRTLEY HOUSE			Appointment Date/Time 23/01/19 09:00 Contract Type Standard A		
	BRAMLEY			Panel Type		
C	GUILDFORD			Panel Location 1ST FLOOR Category		
SURREY						
	GU5 0LB Contact TIM WHALLEY			Further visit required+when 23-01-2019		
elephone				Quotation to be sent to client		
•	gill@birtleyhouse.co.uk		Percentage of devices tested 50%			
Battery Reading			False Alarms			
Batt = [ (Iq x ts) + (I	a x 1.25) ] Ah			Total No of automatic devices (x)	220	
				Total false alarms over last 12 months (from customers log book or ARC)	0	
Quiescent Current	(lq) (A)			Rate of false alarms per 40 devices	0.00	
Alarm Current (Ia)	(A)			Requires investigation (if more than 2 per 40 devices 2 or from same device)	No	
Battery Standby Pe	eriod required (ts) (hrs)			Maintenance Information		
Battery Required (E	Batt) (Ah)	0.00		Last maintenance undertaken	12/07/2018	
Size Fitted	(Ah)	38		Next maintenance due	01/07/2019	
Date Fitted 07			/2016	Existing BAFE CoC on system		
<b>Operational Tes</b>	sts					
Test				Test		
Site requested not to test sounders			True	Site requested not to test outputs	þ	
Confirm signals received to ARC (fire & fault)			р	Audible alarm devices checked (mains & battery)		
Open/Short circuit - indicator, buzzer & zone ok			Ф	Visual alarm devices checked (mains & battery)	þ	
Open/Short circuit - all alarm circuits ok			ρ	Consumables checked and found to be sufficient	þ	
Open/Short circuit - all other monitored circuits ok			ρ	Functional test of emergency lighting		
Mains disconnected - indicator & buzzer ok			D	Panel function zones tested	þ	
Battery disconnected - indicator & buzzer ok			þ	All other controls tested e.g. access codes, keyswitch etc.	þ	
Readily available cable & fittings inspected			þ	Any changes of use of building which may affect fire alarm		
			•	Any changes of construction of building which may affect fire a	alaı þ	
Final Checks	Check with monitoring station that "fire" signals have been received			Set systems for normal operation Record test in log book	þ	
Check with monitor	ğ ğ					
Check with monitor received	f compliance issued?			Graphic zone chart available	þ	
Check with monitor received	'			Graphic zone chart available System satisfactory	þ þ	







Variations from the recommendations of BS 5839-1 - Clause 45 - for periodic or annual inspection and test:

Visit our website on www.eflfire.co.uk









## **Fire Alarm Certificate of Inspection**

Fire Alarm serviced in accordance with BS 5839 PT1

Equipment Inspected Description	Qty Expected	Service Code
HEAT DETECTOR	10	INS
INPUT / OUTPUT MODULE	7	INS
MANUAL CALL POINT	29	INS
OTHER	2	INS
PANEL	1	INS
SMOKE DETECTOR	210	INS
REPEATER PANEL	1	INS
SOUNDER / BELL	50	INS

I / We being the competent person(s) responsible for the servicing of the system(s) described above certify that the work complies with the recommendations of Clause 45 of BS 5839-1 except for the variations identified above, if any, stated in this certificate and in accordance with BAFE Scheme SP203-1

Timesheets Date on Site	Arrival	Departure	Customer Name / Signature	Engineers Name / Signature
23/01/2019	09:20:00	11:53:00	phil	Phil Smith

Visit our website on www.eflfire.co.uk

Unit 17 Northbrook Business Park, Worthing, West Sussex, BN14 8PQ

General Enquiries Tel: 08458739973 Accounts Tel: 01903 830664 Fax: 01903 244008 BAFE registration no. 100786

AdsPDAFire.rtm

Job Number 15756

Page 2 of 2