

Recipient Address:

Mr Tim Whalley BIRTLEY HOUSE

Note:- All enquiries relating to this form should be directed to:-

Regional Address Adrian Cornell

Southern Region Engineer Surveyors

Allianz Engineering Haslemere Road

Liphook Hampshire GU30 7UN Telephone no: +44 (0) 1483 265837

Fax no: +44 (0) 870 0605300

Please quote your report number in any communication





Name of User BIRTLEY HOUSE GROUP LTD

BIRTLEY HOUSE, BIRTLEY ROAD, BRAMLEY, GUILDFORD, SURREY, GU5 0LB Location

Policy No. NZ28883721 Report No. E18513027203 Contract No.

1. a. Description and unique identifier or no. Client No:PGL11000

Description:Passenger/Goods Lift

Manufacturer: Northern Lifts

Serial Number: NL206

Manufacture Date: 1989

b. Location of Lift Main House Hallway

c. Date of last examination Unknown d. Date of current examination 03-Oct-2018 e. Latest date by which the next 03-Apr-2019

examination should be carried out

f. Examination scheme no. Not Known

2. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which they should be completed.

a. Enclosure of liftway. None b. Landing doors and car doors. None

c. Interlocks on the landing doors and None car gate(s).

d. Other door fastenings. None

e. Car or platform and fittings, car None guides, buffers, interior of the liftway.

f. Over-running devices. None

g. Suspension ropes or chains, and None their attachments.

h. Safety gear, ie arrangements for None preventing fall of platform or car.

Brakes. None

j. Worm, spur gears or jacks. None

k. Other electrical equipment. None

I. Other parts. None

Date of commencement of examination and tests

Date of Report Engineer Surveyor

Adrian Cornell

03-OCT-2018

03-OCT-2018

Competent Person Allianz Engineering

UK Tel: +44 (0) 1428 722407

ROI Tel: +00353 (0) 1 613 4081





Side 2 of 2

Report No. E18513027203

3.	Supplementary test(s) required to support the thorough examination. Particulars of any test(s), reason for the requirement and the period within which the test(s) should be completed.	None
4.	Other Defects Identification of any other parts that require rectification.	None
5.	Observations and Recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)	A suitable car mechanical restraint device should be provided to enhance the safety of persons whilst working in the lift pit and a sign advising its use be displayed in the pit. We recommend that the car top control is moved to within 1m of the landing threshold. Oil weep at lift ram seal. Oil loss should be monitored by your lift engineers and renewals made as and when necessary.
6.	Safe Working Load.	630kg, 8 persons

The above items were seen at : (If blank, refer to the Location details)

Examination carried out on behalf of:

Client Name Address

BIRTLEY HOUSE GROUP LTD BIRTLEY HOUSE BIRTLEY ROAD BRAMLEY GUILDFORD GU5 0LB

First Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as having been installed correctly, and is safe to operate. (On the basis of a visual thorough examination of the equipment).

Regular Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as being safe to operate. (On the basis of a visual thorough examination of the equipment).

This report shall not be reproduced without the approval of Allianz Engineering and the client for whom it was produced.



Name of User BIRTLEY HOUSE GROUP LTD

BIRTLEY HOUSE, BIRTLEY ROAD, BRAMLEY, GUILDFORD, SURREY, GU5 0LB Location

Policy No. NZ28883721 Report No. E18513027204 Contract No.

1. a. Description and unique identifier or no. Client No:PGL11002

Description:Passenger/Goods Lift

Manufacturer: Carlton Lifts

Serial Number: GB-4508

Manufacture Date:2000

b. Location of Lift Annex c. Date of last examination Unknown d. Date of current examination 03-Oct-2018 e. Latest date by which the next 03-Apr-2019 examination should be carried out

f. Examination scheme no. Not Known

2. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which they should be completed.

None

None

a. Enclosure of liftway. None b. Landing doors and car doors. None None

c. Interlocks on the landing doors and car gate(s).

d. Other door fastenings. None

e. Car or platform and fittings, car None guides, buffers, interior of the liftway.

f. Over-running devices. None

g. Suspension ropes or chains, and None their attachments.

h. Safety gear, ie arrangements for

preventing fall of platform or car.

Brakes. None

j. Worm, spur gears or jacks. None k. Other electrical equipment.

I. Other parts. None

Date of commencement of examination and tests

Date of Report

Engineer Surveyor

Adrian Cornell

03-OCT-2018

03-OCT-2018

Competent Person Allianz Engineering

UK Tel: +44 (0) 1428 722407

ROI Tel: +00353 (0) 1 613 4081





Lift Report

Lifting Operations & Lifting Equipment Regulation 1998 Provision & Use of Work Equipment Regulations 1998 Regular Thorough Examination

Side 2 of 2

Report No. E18513027204

3.	Supplementary test(s) required to support the thorough examination. Particulars of any test(s), reason for the requirement and the period within which the test(s) should be completed.	None
4.	Other Defects Identification of any other parts that require rectification.	The maintenance upper travel limit switch should be fitted/adjusted to ensure safe access and egrees from the car top when activated.
5.	Observations and Recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)	An approved electrical insulation mat should be provided for use when working on the control panel.
6.	Safe Working Load.	630kg, 8 persons

The above items were seen at : (If blank, refer to the Location details)

Examination carried out on behalf of:

Client Name Address BIRTLEY HOUSE GROUP LTD BIRTLEY HOUSE BIRTLEY ROAD BRAMLEY GUILDFORD GU5 0LB

First Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as having been installed correctly, and is safe to operate. (On the basis of a visual thorough examination of the equipment).

Regular Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as being safe to operate. (On the basis of a visual thorough examination of the equipment).

This report shall not be reproduced without the approval of Allianz Engineering and the client for whom it was produced.



Name of User BIRTLEY HOUSE GROUP LTD

BIRTLEY HOUSE, BIRTLEY ROAD, BRAMLEY, GUILDFORD, SURREY, GU5 0LB Location

Policy No. NZ28883721 Report No. E18513027205 Contract No.

1. a. Description and unique identifier or no. Client No:PGL11004

Description:Passenger/Goods Lift

Manufacturer:Stannah

Serial Number:270423

Manufacture Date:2008

b. Location of Lift Main House Dining Room

c. Date of last examination Unknown 03-Oct-2018 d. Date of current examination e. Latest date by which the next 03-Apr-2019

examination should be carried out

f. Examination scheme no. Not Known

2. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which they should be completed.

None

a. Enclosure of liftway. None b. Landing doors and car doors. None

c. Interlocks on the landing doors and car gate(s).

d. Other door fastenings. None e. Car or platform and fittings, car None guides, buffers, interior of the liftway.

f. Over-running devices. None

g. Suspension ropes or chains, and None their attachments.

h. Safety gear, ie arrangements for

None preventing fall of platform or car.

Brakes. None

j. Worm, spur gears or jacks. None k. Other electrical equipment. None

I. Other parts. None

Date of commencement of examination and tests

Date of Report

Engineer Surveyor

Adrian Cornell

03-OCT-2018

03-OCT-2018

Competent Person Allianz Engineering

UK Tel: +44 (0) 1428 722407

ROI Tel: +00353 (0) 1 613 4081





Lift Report

Lifting Operations & Lifting Equipment Regulation 1998 Provision & Use of Work Equipment Regulations 1998 Regular Thorough Examination

Side 2 of 2

Report No. E18513027205

3.	Supplementary test(s) required to support the thorough examination. Particulars of any test(s), reason for the requirement and the period within which the test(s) should be completed.	None
4.	Other Defects Identification of any other parts that require rectification.	None
5.	Observations and Recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)	None
6.	Safe Working Load.	1000kg, 13 persons

The above items were seen at : (If blank, refer to the Location details)

Examination carried out on behalf of:

Client Name Address BIRTLEY HOUSE GROUP LTD BIRTLEY HOUSE BIRTLEY ROAD BRAMLEY GUILDFORD GU5 0LB

First Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as having been installed correctly, and is safe to operate. (On the basis of a visual thorough examination of the equipment).

Regular Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as being safe to operate. (On the basis of a visual thorough examination of the equipment).

This report shall not be reproduced without the approval of Allianz Engineering and the client for whom it was produced.

Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998 Provision & Use of Work Equipment Regulations 1998 Regular Thorough Examination

Name of User BIRTLEY HOUSE GROUP LTD

BIRTLEY HOUSE, BIRTLEY ROAD, BRAMLEY, GUILDFORD, SURREY, GU5 0LB Location

Policy No.	NZ28883721	Report No.	E18513027206	Contract No.
------------	------------	------------	--------------	--------------

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. B. C.	Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. Identification of any other parts that require rectification. Observations and Recommendations. (issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
LBLI11003 Unknown 03-Oct-2018 03-Apr-2019	Lifting Beam (Lift Installation) 5015 Carlton Lifts Top if liftway, Main House Dining Room	1000kg	A None B None C None	
LBLI11001 Unknown 03-Oct-2018 03-Apr-2019	Lifting Beam (Lift Installation) CS221988 Top of Iftway, annex lift	500kg	A None B None C None	

The above items were seen at : (If blank, refer to the Location details)

Examination carried out on behalf of:

Client Name Address

BIRTLEY HOUSE GROUP LTD BIRTLEY HOUSE BIRTLEY ROAD BRAMLEY GUILDFORD

GU5 OLB

First Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as having been installed correctly, and is safe to operate. (On the basis of a visual thorough examination of the equipment).

Regular Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as being safe to operate. (On the basis of a visual thorough examination of the equipment).

This report shall not be reproduced without the approval of Allianz Engineering and the client for whom it was produced.

Date of commencement of examination and tests

Date of Report

Engineer Surveyor

Adrian Cornell

03-OCT-2018

Competent Person Allianz Engineering 03-OCT-2018

UK Tel: +44 (0) 1428 722407

ROI Tel: +00353 (0) 1 613 4081



