

Company: Location:

All Depts 29/10/2014 Risk Assessment: Reference No. Date of Assessment: Completed By:

Birtley House Eyhurst Court Ltd - GU5 0LB

None Required

Review Date

Tim Whalley



Gas

Identified hazard:

Fire, explosion



Who is at risk?

All staff, visitors, residents and contractors

How is the risk controlled?

The gas isolation valves in the kitchen/laundry/boiler areas are well situated and identified clearly. There is a formal procedure for dealing with (suspected) gas leaks.

Relevant employees have been instructed in the gas isolation procedure as part of the Fire Action







The calculated risk factor for this task/operation is 18 (Probability: 2 x Severity: 9)

This is classed as a MEDIUM risk

Additional Measures:

Gas - 29-10-2014

Version: 13/03/2015

Gas - 29-10-2014

Version: 13/03/2015

91/8/61 Signature/s..... 29/10/2015