


CHIMNEY SWEEPS









YOUR CHIMNEY HAS BEEN BRUSH SWEPT IN ACCORDANCE WITH THE APICS CODE OF PRACTICE AND Mr J Tanner

BSEN 15287-1:2007+A1:2010

BY:

13 Deanery rd

13 Deanery rd	Date of Issue 20 - 11 - 2018
Godalming GU7 2PG	The state of the s
07920 774004	Issued by

Your chimney is likely to require re-sweeping within 2 months, being / (month) 20 (year). Should you have any complaint concerning the work, it should, in the first instance be made to the responsible firm or sweep within seven days. If satisfactory response is not made we suggest that you should contact the Association of Professional Independent Chimney Sweeps.

The Association will do its best to resolve such a complaint.

It is recommended that in normal use, chimneys should be swept as follows:

- Chimneys with solid fuel appliances Chimneys with solid fuel appliances Chimneys with solid fuel appliances Chimneys Smokeless fuels at least once a year.

 Domestic bituminous coal at least twice a year.
- Chimneys with oil-fired appliances Once a year.

CHIMNEYS SHOULD NOT BE CLEANED BY VACUUM ALONE - BRUSHES MUST BE USED

Disclaimer: While great care is taken to prevent damage to your property, the sweep cannot be held responsible for badly maintained pots, cowls, chimney stacks or any other part of your chimney. Material information should always be disclosed, i.e. chimney fires, fuels used, dates (if known). Your sweep can only use his/her knowledge during sweeping to advise on the condition of your chimney or appliance. He/she will not be able to investigate inaccessible/concealed areas.

This requires the use of a chimney camera. Any information must not be relied upon in any way. Chimneys are affected by the way they are used, the weather and many other conditions, which may not be known to your sweep. If you have any concerns please talk to your sweep who will usually be able to offer sound, unbiased advice. This is not a certificate of guarantee or warranty that any fireplace, heating appliance, boiler, flue or chimney stack is safe. Please be aware that older chimney linings may continue to drop material no matter how often they are swept and that tarry chimneys pose a fire risk and may require chemical intervention. Please check with your liner manufacturer that they approve the use of chemicals before using them.

Some forms of soot may require a more aggressive form of cleaning, which may not be suitable for your chimney system.

Name Tim Mcelley Customer's Signature (if applicable) X Mill Hence	
Address Birthey House Braubles	
Location of chimney En france & Sitting Rooms Ref. No.	

Regular chimney sweeping is important, for whatever fuel you may use, coal, oil, wood or gas