

Inspection Report:

Order number: 43687712

Job Number: 20 Sold To: EYHURST COURT LTD

SITE INFORMATION

Customer Name: BIRTLEY HOUSE Street: **BRAMLEY**

City: **GUILDFORD** GU5 0LB

Post Code:

PRODUCT INFORMATION

Material: SOVEREIGN, RIGHT, HI/LO,

LIFT

Serial number: VEPL00003264

Asset Tag:

Product Classification:

Latest Location: FIRST FLOOR ANNEX

WORK ORDER INFORMATION

Order activity type: R Contract Repair

Work Order Description: Kim Whalley, Director, 01483

892055

Customer Order Number: Kim Whalley **CONTACT INFORMATION**

Site Contact: Site Contact Email: **BIRTLEY HOUSE**

PROBLEM DESCRIPTION AND CORRECTIVE ACTION

Damage	Problem Description	Engineers Comments
Controls not functioning		
Activity	Specification	Engineers Comments

GENERAL INFORMATION

External notes

Replaced faulty seat limit PCB under warranty as previously replaced. Replaced handset as seat return button failing (hard to press). All tested okay.

EQUIPMENT CHECKS

Task	Specification	Engineers Comments
Product Located		
Risk Assessment Performed		
Safe to operate		

PARTS USED

Product Code	Product Description	Qty	Accounting Indicator
8559714	HANDSET, 2 BUTTON	1 EA	BILLABLE
8562148	END LIMIT PCB BOARD ASSY	1 EA	SERVICE WARRANTY

LABOUR DETAILS

Activity Type	Start Date And Time	End Date And Time	Accounting Indicator
WORK	07.03.2019 13:00:00	07.03.2019 13:45:00	SERVICE GOODWILL



Inspection Report: Order number: 43687712

Job Number: 20

Technician's signature N Prosser

Date: 07.03.2019

Email:

Sold To: EYHURST COURT LTD

Customer's signature S Whalley

Date: 07.03.2019

Email:

Tim@birtleyhouse.co.uk