

Vehicle information

Benz_Sprinter Sprinter

VIN: WD2PD744X55718012

Mileage:

Diagnostic time: 2024-09-21 13:31:29

Diagnostic path: Manual selection\Sprinter\901.6; 902.6; 903.6; 904.6; 905.6(KWP 2000 - 2006)\USA,

Canada\OBDII\Auto scan\

Status report

System name	DTC counts	Status
CR-Common rail	12	Fault
EGS electronic transmission control	03	Fault
Transmission control	03	Fault
ESP-Electronic stability program	03	Fault
AB-Airbag	0	Pass
KI-Instrument cluster	01	Fault
WSP immobilizer	0	Pass
EWM-Electronic selector lever module	03	Fault
HZR-Heating control	02	Fault

1. CR-Common rail---(12)

1.1 2009-1	The fill level sensor (water separator) does not supply a signal.	Stored&Current
1.2 2208-1	CAN bus: Brake signal .Plausibility	Stored
1.3 2511	Component 'Y85 (Exhaust gas recirculation positioner)' is faulty. Unknown fault type: -1	Stored
1.4 2132-1	Preglowing failed.Short circuit to battery or open circuit	MIL ON&Stored
1.5 2132-2	Preglowing failed.Short circuit to ground	MIL ON&Stored
1.6 2218-002	Fault of the control module 'A4 (ETC [EGS] control module)' Unknown fault type: -1	Stored
1.7 2219-1	Fault of the control module 'A4 (ETC [EGS] control module)''2 - 3-shift' solenoid valve is faulty.	Stored



1.8 2210-002	No or incorrect CAN message from the control module 'A40 (ESM [EWM] control unit)' Unknown fault type: -1	Stored
1.9 2133-1	Component 'R17 (Glow plug)' is faulty. Short circuit to battery or open circuit	Stored
1.10 2135-1	Component 'R15 (Glow plug)' is faulty. Short circuit to battery or open circuit	Stored
1.11 2136-1	Component 'R14 (Glow plug)' is faulty. Short circuit to battery or open circuit	Stored
1.12 2228-1	Fault of the control module 'A4 (ETC [EGS] control module)'Impermissible transmission ratio	Stored&Current

2. EGS electronic transmission control---(03)

2.1 P2602	The supply voltage of the valves is faulty.	Stored
2.2 P2500	Impermissible transmission ratio	Stored
2.3 Event P2404	CAN fault - The signal of the stop light switch is implausible.	Stored

3. Transmission control---(03)

3.1 P2602 (2602)	Please refer to vehicle manual!	Stored
3.2 P2404 (2404)	Please refer to vehicle manual!	Stored
3.3 P2500 (2500)	Please refer to vehicle manual!	Stored

4. ESP-Electronic stability program---(03)

4.1 5501	CAN communication with the Transmission Control Module (TCM) is faulty.	Stored
4.2 5159	Stop lamp switch, Short circuit to positive/incorrect adjustment	Stored
4.3 518F	Wire Pressure sensor	Stored

5. KI-Instrument cluster---(01)

5.1 Event B1042-000	CAN communication with the control module 'Electronic Transmission Control (ETC/EGS)' is faulty.	Stored
---------------------	--	--------

6. EWM-Electronic selector lever module---(03)

6.1 Event P1926	CAN communication is faulty.	Stored&Current
6.2 Event P1925	CAN fault - The brake torque is implausible.	Stored
6.3 Event P1927	CAN fault - Signal 'Stop lamp switch' is implausible.	Stored



7. HZR-Heating control---(02)

7.1 B1005-007	Heater output has Short circuit to positive or Open circuit.	Stored&Current
7.2 B1007-007	Blower stage 1 has Short circuit to positive or Open circuit.	Stored