



CLEAN UP

Every time you leave an area. Including the floor.

- 1 Clean up every time whenever you leave an area, including sweeping the floor.
- 2 Clean and return all tools to where you got them.
- 3 Use compressed air sparingly; never aim it at another person or use it to clean hair or clothes.
- 4 Shut off and unplug machines when cleaning, repairing, or oiling.
- 5 Never use a rag near moving machinery.
- 6 Use a brush, hook, or a special tool to remove chips, shavings, etc. from the work area. Never use the hands.
- 7 Keep fingers clear of the point of operation of machines by using special tools or devices, such as push sticks, hooks, pliers, etc.
- 8 Keep the floor around machines clean, dry, and free from trip hazards. Do not allow chips to accumulate.
- 9 Mop up spills immediately and put a chair or cone over them if they are wet enough to cause someone to slip.

Use a brush or a hook for chips and shavings. Never your hands — they are sharp and they are often still hot.