



DRESS RIGHT

No safety glasses... No entry.

Eye protection is worn at all times in the Makerspace — whether you are working or not. Someone else's work can reach your eyes while you are just walking through.

- 1 Wear eye protection: safety glasses with side shields, goggles, or face shields at all times, whether working or not.
- 2 Do not wear loose-fitting clothing around moving or rotating machinery.
- 3 Remove ties, jewelry, gloves, etc. especially around moving or rotating machinery.
- 4 Tie back or cover long hair to keep it away from moving machinery.
- 5 Wear only shoes that cover the entire foot, no open-toe shoes or sandals.
- 6 Wear suitable gloves when handling hot objects, glass, or sharp-edged items.
- 7 Wear appropriate clothing for the job (i.e., do not wear short sleeve shirts or short pants when welding).