#### **GFICO**

Amarillo

For supplement requests, copy the link

Request supplement at partners.geico.com Visit us online at www.geico.com

Amarillo, TX

Phone: (806) 443-2525

Fax: (855) 794-8316

Claim #: Workfile ID:

0606007200000001-01

8b706f83

Estimate of Record

Written By: MARRCI MARSHALL, 9/10/2019 8:17:33 PM Adjuster: Cook, Myra, (254) 239-7601 Business

Insured: Brittany Huber

Owner Policy #:

4506040403

Claim #: 0606007200000001-01

Type of Loss:

Collision

Date of Loss:

09/03/2019 10:30 AM

Days to Repair:

Point of Impact:

12 Front

Deductible:

500.00

Owner (Insured): **Brittany Huber** 

Inspection Location:

T-miller Wrecker T-miller Wrecker

15330 E Evans Ave Aurora, CO 80013 (303) 960-7370 Evening

1201 S Johnson St Amarillo, TX 79101

(303) 960-7370 Cellular Field

(806) 376-5384 Day

Appraiser Information:

MyCook@GEICO.com (254) 239-7601

Repair Facility: Total Loss

**VEHICLE** 

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

VIN:

State:

KNAFX4A6XE5182135

Production Date:

Interior Color:

License:

00z490

ΤX

Odometer: Condition:

63322

Exterior Color:

bronze

TRANSMISSION

STEERING WHEEL TOUCH

**CONTROLS** 

SATELLITE RADIO

**GLASS & MIRRORS** 

AUTOMATIC TRANSMISSION

CONSOLE/STORAGE

**SAFETY** 

**DUAL MIRRORS** 

DRIVER CONVENIENCE

**INSTRUMENT PANEL** TRACTION CONTROL

DRIVERS SIDE AIR BAG

SIGNAL INTEGRATED MIRRORS

KEYLESS ENTRY MESSAGE CENTER STABILITY CONTROL

PASSENGER AIR BAG

**AUXILIARY AUDIO CONNECTION** 

TINTED GLASS

**POWER WINDOWS** POWER LOCKS

AIR CONDITIONING REAR DEFOGGER

**SEATS** FRONT SIDE IMPACT AIR BAGS

**CLOTH SEATS** 

POWER MIRRORS

HANDS FREE DEVICE

HEAD/CURTAIN AIR BAGS **BUCKET SEATS** PAINT RECLINING/LOUNGE SEATS

HEATED MIRRORS

RADIO AM RADIO CLEARCOAT PAINT METALLIC PAINT

WHEELS

POWER TRUNK/GATE RELEASE CRUISE CONTROL

FM RADIO **STEREO** 

FRONT END POWER STEERING 4-WHEEL DISC BRAKES ALUMINUM/ALLOY WHEELS

INTERMITTENT WIPERS TILT WHEEL

TELESCOPIC WHEEL

SEARCH/SEEK CD PLAYER

**POWER BRAKES** ANTI-LOCK BRAKES (4)

9/10/2019 8:17:34 PM 135812 | 1.7.04.10120 Page 1

Claim #: Workfile ID: 0606007200000001-01

8b706f83

# Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

Line		Oper	Description	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER & GRILLE						
2	**	Repl	Opt OEM Impact bar	1	245.00	0.3	
3			O/H front bumper			1.8	
4	**	Repl	A/M CAPA Absorber	1	64.00	Incl.	
5	** <>	Repl	A/M CAPA Bumper cover w/o prk sensor	1	190.00	Incl.	2.8
6			Add for Clear Coat				1.1
7	FRONT LAM	IPS					
8	**	Repl	A/M CAPA RT Headlamp assy	1	225.00	Incl.	
9			Aim headlamps			0.5	
10	**	Repl	A/M CAPA LT Headlamp assy	1	225.00	Incl.	
11	RADIATOR	SUPPORT	Г				
12	*	Repl	LKQ Radiator support +25%	1	312.50	<u>4.2</u>	
13	FENDER						
14	**	Repl	A/M CAPA RT Fender	1	155.00	1.5	1.8
15			Overlap Major Non-Adj. Panel				-0.2
16			Add for Clear Coat				0.3
17			Add for Edging				0.5
18			Add for Clear Coat				0.1
19	**	Repl	A/M CAPA LT Fender	1	155.00	1.5	1.8
20			Overlap Major Non-Adj. Panel				-0.2
21			Add for Clear Coat				0.3
22			Add for Edging				0.5
23			Add for Clear Coat				0.1
24		Repl	RT Apron assy	1	266.50 s	6.4	1.1
25		Repl	LT Apron assy	1	266.50 s	6.4	1.1
26			Overlap Major Non-Adj. Panel				-0.2
27		Repl	LT Rail assy	1	504.67 s	15.4	1.4
28			Overlap Major Non-Adj. Panel				-0.2
29			Deduct for Overlap			-1.5	
30	RESTRAINT	SYSTEM	S				
31		Repl	Driver air bag	1	641.67 m	0.3	
32			Air bag system diagnosis		m	0.5	
33		Repl	Psngr air bag	1	858.34 m	0.5	
34		Repl	Clockspring w/o heated wheel	1	104.00 m	0.9	
35		Repl	Air bag module to 10/21/2013	1	529.33 m	0.3	
36		Repl	RT Ft impact sensor	1	133.50 m	0.2	
37		Repl	LT Ft impact sensor	1	133.50 m	0.2	
38		Repl	RT Belt & retractor	1	318.33	8.0	
39		Repl	LT Belt & retractor	1	318.33	0.8	
40	#		Cover Car	1	5.00		
41	#		Flex Additive	1	5.00		

0606007200000001-01

Workfile ID:

8b706f83

# Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze							
42	#	Seam Sealer		1	12.00 T		
43	OTHER CHARGES						
44	#	E.P.C.		1	2.50		
			SUBTOTALS		5,670.67	41.0	12.1

# NOTES

Prior Damage Notes: hail damage to video

# **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				5,656.17
Body Labor	41.0 hrs	@	\$ 46.00 /hr	1,886.00
Paint Labor	12.1 hrs	@	\$ 46.00 /hr	556.60
Paint Supplies	12.1 hrs	@	\$ 32.00 /hr	387.20
Miscellaneous				12.00
Other Charges				2.50
Subtotal				8,500.47
Sales Tax	\$ 6,055.37	@	8.2500 %	499.57
Total Cost of Repairs				9,000.04
Deductible				500.00
Total Adjustments				500.00
Net Cost of Repairs	_		-	8,500.04

0606007200000001-01

Workfile ID: 8b706f83

#### Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

#### ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

\*\*\*IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

\*\*\*\*OWNER LIMITED GUARANTEE\*\*\*\* WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

IT IS UNLAWFUL TO KNOWINGLY PROVIDE FALSE, INCOMPLETE, OR MISLEADING FACTS OR INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING OR ATTEMPTING TO DEFRAUD THE COMPANY. PENALTIES MAY INCLUDE IMPRISONMENT, FINES, DENIAL OF INSURANCE, AND CIVIL DAMAGES. ANY INSURANCE COMPANY OR AGENT OF AN INSURANCE COMPANY WHO KNOWINGLY PROVIDES FALSE, INCOMPLETE, OR MISLEADING FACTS OR INFORMATION TO A POLICYHOLDER OR CLAIMANT FOR THE PURPOSE OF DEFRAUDING OR ATTEMPTING TO DEFRAUD THE POLICYHOLDER OR CLAIMANT WITH REGARD TO A SETTLEMENT OR AWARD PAYABLE FROM INSURANCE PROCEEDS SHALL BE REPORTED TO THE COLORADO DIVISION OF INSURANCE WITHIN THE DEPARTMENT OF REGULATORY AGENCIES.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

Claim #: Workfile ID: 0606007200000001-01

8b706f83

### Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARY2471, CCC Data Date 9/3/2019, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2020 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

0606007200000001-01

Workfile ID: 8b706f83

## Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

## ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
2	KEYSTONE - LUBBOCK, TX	#KI10061400E	\$ 245.00
	1411 SOUTH LOOP 289	Opt OEM Impact bar	
	LUBBOCK TX 79423	Quote: 409470051	
	(806) 745-7002	Expires: 10/24/19	
4	KEYSTONE - LUBBOCK, TX	#KI1070134C	\$ 64.00
	1411 SOUTH LOOP 289	A/M CAPA Absorber	
	LUBBOCK TX 79423	Quote: 409470051	
	(806) 745-7002	Expires: 10/24/19	
5	National Autobody Parts Whse DFW	#KI1000163C	\$ 190.00
	Reid Whitesel	A/M CAPA Bumper cover w/o prk sensor	
	2000 E Main Street		
	Grand Prairie TX 75050		
	(800) 214-7222		
8	All Star Auto Lights - Texas	#3231144RAC2	\$ 225.00
	2934 N PANAM EXPY	A/M CAPA RT Headlamp assy	
	SAN ANTONIO TX 78208	Quote: 19387136	
	(210) 996-2107	Expires: 09/19/19	
10	All Star Auto Lights - Texas	#3231144LAC2	\$ 225.00
	2934 N PANAM EXPY	A/M CAPA LT Headlamp assy	
	SAN ANTONIO TX 78208	Quote: 19387136	
	(210) 996-2107	Expires: 09/19/19	
12	B And R Auto Parts, Inc.	#160105	\$ 250.00
	Terry	LKQ Radiator support +25%	
	4401 Avenue A	RADIATOR SUPPORT-EX,2.0L,ATOD,UPPER TIE SUPPORT - KOREA BUILT ( VIN K, 1ST DIGIT ), COUP	
	Lubbock TX 79404		
	(806) 762-0319		
14	National Autobody Parts Whse DFW	#KI1241138NSF	\$ 155.00
	Reid Whitesel	A/M CAPA RT Fender	
	2000 E Main Street		
	Grand Prairie TX 75050		
	(800) 214-7222		
19	National Autobody Parts Whse DFW	#KI1240138NSF	\$ 155.00
	Reid Whitesel	A/M CAPA LT Fender	
	2000 E Main Street		
	Grand Prairie TX 75050		

0606007200000001-01

Workfile ID: 8b706f83

# Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

(800) 214-7222

0606007200000001-01

Workfile ID: 8b706f83

# Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

## ALTERNATE PARTS USAGE

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

VIN: KNAFX4A6XE5182135

TX

Production Date:

Interior Color:

License: 00z490

State:

Odometer: Condition: Exterior Color:

bronze

Alternate Part Type	# Of Available Parts	# Of Parts Selected
Aftermarket	25	6
Optional OEM	5	1
Reconditioned	7	0
Recycled	58	1

63322

Interior Color:

0606007200000001-01

Workfile ID: 8b706f83

#### Estimate of Record

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

#### RECALL INFO

2014 KIA Forte LX Automatic 4D SED 4-1.8L Gasoline MPI bronze

VIN: KNAFX4A6XE5182135 Production Date:

00z490

License:

Odometer: 63322 Exterior Color: bronze

State: TX Condition:

The National Highway Transportation and Safety Administration (NHTSA) has issued 2 safety-related recall notice(s) that may apply to the selected vehicle

NHTSA ID: 17V773000 Issued: Dec 12, 17 Number of Vehicles: 00134366

SERVICE BRAKES, HYDRAULIC Kia Motors America (Kia) is recalling certain 2012-2014 Forte and Forte Koup vehicles. The brake pedal stopper pad can deteriorate allowing the brake light switch plunger to remain extended when the brake pedal is released. This will allow the brake lights to remain illuminated continuously. It can also allow the shift lever to be moved without depressing the brake pedal, or activate the engine management brake pedal override feature. If the brake light switch plunger does not retract as it should when the brake pedal is not being pressed, the brake lights may stay illuminated preventing accurate communication to following vehicles that the vehicle is slowing or stopping. Additionally, if the brake switch plunger is not retracted, then the transmission can be shifted out of PARK without depressing the brake pedal. Either condition increases the risk of a crash. Kia will notify owners, and dealers will replace the brake pedal stopper pad, free of charge. The recall is expected to begin January 30, 2018. Owners may contact Kia customer service at 1-800-333-4542. Kia"s number for this recall is SC158.

ELECTRICAL SYSTEM Kia Motors America (Kia) is recalling certain model year 2014 Kia Forte vehicles manufactured December 5, 2012, to April 17, 2014. In the affected vehicles, the cooling fan resistor may overheat and melt. If the cooling fan resistor overheats and melts, there is an increased risk of a vehicle fire. Kia will notify owners, and for vehicles produced from December 5, 2012 to January 27, 2014, dealers will replace the cooling fan resistor and multi-fuse unit. For vehicles produced from January 28, 2014 to April 17, 2014, dealers will replace the multi-fuse unit only. Owners of vehicles with a 1.8L engine will also have the engine control unit software updated. The recall began on February 20, 2015. Owners may contact Kia customer service at 1-800-333-4542. Kia"s number for this recall is SC113.