

1. horsor Movement Rev - Rby 2. Invernenting Number -For - Rb6 3. Enter Stop - Rbo 1. Save and Exit Start - Rco

Strategy 1. Menn Screen Strosting 2. hoom Setting 3. Dhothi settings. 4. Saving hom/ phothinto EPROM 5. Dothi setting Display 6. Reset - Implementation after the Relay Phase