

# Section 32. Configuration

# **HIGHLIGHTS**

This section of the manual contains the following major topics:

32.1	Introduction	32-2
32.2	Modes of Operation	32-3
32.3	Effects of Various Resets	32-4
32.4	Related Application Notes	32-5
32.5	Revision History	32-6

Note:

This family reference manual section is meant to serve as a complement to device data sheets. Depending on the device variant, this manual section may not apply to all PIC32 devices.

Please consult the note at the beginning of the "**Special Features**" chapter in the current device data sheet to check whether this document supports the device you are using.

Device data sheets and family reference manual sections are available for download from the Microchip Worldwide Web site at: http://www.microchip.com

# 32.1 INTRODUCTION

A PIC32 family device includes several nonvolatile (programmable) Configuration Words that define device behavior.

The device configuration features may vary according to PIC32 family variants; however, the following features are common to all PIC32 devices:

- · System Clock Oscillator mode and Phase-Locked Loop (PLL)
- Secondary Oscillator (Sosc) enable/disable
- · Watchdog Timer (WDT) enable/disable and postscaler
- Boot Flash and Program Flash write-protect regions
- User ID
- · Debug mode

The PIC32 Configuration Words are located in Boot Flash memory and are programmed when the PIC32 Boot Flash region is programmed.

System clock oscillator and PLL bits provide a large selection of flexible clock source options and PLL prescalers/postscalers.

The SOSC bit enables or disables a low-power SOSC that can serve as a clock source for several peripherals, such as RTCC, Timer1 and CPU.

The WDT and postscaler bits allow the user to permanently disable or enable the WDT. When enabled, a postscaler can be selected to provide a wide range of WDT periods. A Windowed mode Watchdog feature is also available.

The Boot Flash and Program Flash write-protected bits provide write protection to all of Boot Flash memory and selected regions of Program Flash memory.

User ID bits are available for programming application-specific or product-specific identification information, such as product ID or serial numbers. Debug mode bits provide a selection of debugging modes and channels.

**Note:** For more information on the available device Configuration Words, refer to the specific device data sheet.

# 32.2 MODES OF OPERATION

# 32.2.1 PIC32MX Configuration Words

In the PIC32MX family of devices, the Configuration Words select various device configurations, and are located in the last four Words (32-bit x 4 Words) of Boot Flash memory, DEVCFG0 to DEVCFG3.

During programming, a Configuration Word can be programmed a maximum of two times before a page erase must be performed. For example, during device programming, a user can program the Configuration Word, DEVCFG1, with desired data, and then perform a verification or other integrity check. DEVCFG1 can then be programmed again, this time setting any remaining unprogrammed bits to '0'.

Note:

The Configuration Word, DEVCFG0, can only be programmed once before a page erase must be performed. Each time the Boot Flash memory region is erased, the DEVCFG0<31> bit is automatically set to '0', leaving only one additional programming operation available, DEVCFG0.

After programming the Configuration Words, the user should reset the device to ensure the Configuration data is reloaded with the new programmed values.

# 32.2.1.1 CONFIGURATION REGISTER PROTECTION

To ensure the 128-bit data integrity of each Configuration Word, a comparison is continuously made between each Configuration bit and its stored complement. If a mismatch is detected, a Configuration Mismatch Reset is generated causing a device Reset.

# 32.2.2 PIC32MZ Configuration and Alternate Configuration Words

In the PIC32MZ family of devices, the Configuration Words select various device configurations, and are located at physical addresses 0x1FC0FFC0 (DEVCFG3) through 0x1FC0FFCC (DEVCFG0).

If an unrecoverable ECC error occurs when reading the Configuration Words, the Alternate Configuration Words are used to configure the device and Boot Flash memory. This configuration can be identical to the primary Configuration Words, or different to operate in another condition. The Alternate Configuration Words are located at physical addresses 0x1FC0FF40 (ADEVCFG3) through 0x1FC0FF4C (ADEVCFG0). To flag that an ECC error has occurred, the BCFGERR (RCON<27>) bit is set.

If uncorrectable ECC errors are found in both primary and alternate words, the BCFGFAIL (RCON<26>) bit is set and the default configuration is used.

During programming, all four Configuration Words should be programmed at the same time to ensure ECC operation. The Configuration Words can only be programmed once before a quad-word erase must be performed. All unprogrammed bits should be set to '0'.

After programming the Configuration Words, the user application should reset the device to ensure the configuration data is reloaded with the new programmed values.

## 32.2.2.1 SEQUENCE NUMBER AND BOOT FLASH MEMORY

In the PIC32MZ family of devices, there are two regions of Boot Flash memory. Each can contain its own version of Configuration and Alternate Configuration Words, and its own bootloader. At boot the device reads two memory locations from each panel, which are called the sequence numbers. If the value programmed into the TSEQ<15:0> bits of the Boot Flash 1 Sequence Word 0 (BF1SEQ0) is equal to or greater than the value programmed into the TSEQ<15:0> bits of the Boot Flash 2 Sequence Word 0 (BF2SEQ0), Boot Flash 1 is aliased to the lower boot alias region. If the value of the TSEQ<15:0> bits of BF2SEQ0 is greater than the TSEQ<15:0> bits of BF1SEQ0, Boot Flash 2 is aliased to the lower boot alias region.

The CSEQ<15:0> bits must contain the complement value of the TSEQ<15:0> bits; otherwise, the value of the TSEQ<15:0> bits is considered invalid, and an alternate sequence is used.

Once Boot Flash memories are aliased, configuration space located in the lower boot alias region is used as the basis for the configuration words DEVSIGN0, DEVCP0, and DEVCFGx.

# 32.3 EFFECTS OF VARIOUS RESETS

The Configuration data is reloaded from the corresponding Boot Flash memory Configuration Words on the following types of reset:

- Power-on Reset (POR)
- Brown-out Reset (BOR)
- External Reset (MCLR)
- Configuration Mismatch Reset (CM)
- Watchdog Timer Reset (WDTR)
- Software Reset (SWR)
- NMI Time-out Reset (NMITR)

# 32.4 RELATED APPLICATION NOTES

This section lists application notes that are related to this section of the manual. These application notes may not be written specifically for the PIC32 device family, but the concepts are pertinent and could be used with modification and possible limitations. The current application notes related to Configuration are:

Title Application Note #

No related application notes at this time.

N/A

**Note:** Please visit the Microchip web site (www.microchip.com) for additional application notes and code examples for the PIC32 device families.

# 32.5 REVISION HISTORY

# Revision A (August 2007)

This is the initial released version of this document.

# **Revision B (October 2007)**

Updated document to remove Confidential status.

# Revision C (April 2008)

Revised status to Preliminary; Revised U-0 to r-x; Revised Section 32.3.2; Revised Table 32-1; Revised Configuration Word DEVID Register; Revised Configuration Word DEVCFG2 Register.

# Revision D (June 2008)

Revised Register 31-1 (DEVCFG0); Change Reserved bits from "Maintain as" to "Write".

# **Revision E (July 2009)**

This revision includes the following updates:

- Minor updates to the text and formatting have been incorporated throughout the document.
- Added a note regarding Configuration Word availability in PIC32MX devices to "Section 32. Configuration Words".
- Added the following bits to Table 32-1: Configuration Word Summary and to the related registers:
  - SIGN (see Register 32-1)
  - WINDIS (Register 32-2)
  - FVBUSIO (Register 32-4)
  - FUSBIDIO (Register 32-4)
  - FSCM1IO (Register 32-4)
  - FCANIO (Register 32-4)
  - FETHIO (Register 32-4)
  - FMIIEN (Register 32-4)
  - FSRSSEL (Register 32-4)

# **Revision F (June 2011)**

This revision includes the following updates:

- Added a note with information to customers for utilizing family reference manual sections and data sheets as a joint reference (see note above 32.1 "Introduction")
- Removed Register 32-1 through Register 32-5
- Removed 32.2 CONFIGURATION WORDS
- Updated 32.2.1 "Configuration Words"
- Removed 32.3.2 Device Code Protection
- Removed 32.3.3 Program Write Protection (PWP)
- Removed Table 32-1 through Table 32-3
- Updated all PIC32MX references to PIC32
- Updates to formatting and minor text changes were incorporated throughout the document

# **Revision G (November 2013)**

This revision includes the following updates:

- Added 32.2.2 "PIC32MZ Configuration and Alternate Configuration Words"
- · Minor updates to text and formatting were incorporated throughout the document

# Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not
  mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

# QUALITY MANAGEMENT SYSTEM CERTIFIED BY DNV = ISO/TS 16949=

#### **Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rfPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rfLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2007-2013, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

Printed on recycled paper.

ISBN: 978-1-62077-640-7

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



# Worldwide Sales and Service

## **AMERICAS**

Corporate Office

2355 West Chandler Blvd. Chandler, AZ 85224-6199

Tel: 480-792-7200 Fax: 480-792-7277 Technical Support:

http://www.microchip.com/

support

Web Address: www.microchip.com

Atlanta

Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455

**Austin, TX** Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago

Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075

Cleveland

Independence, OH Tel: 216-447-0464 Fax: 216-447-0643

**Dallas** 

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit Novi. MI

Tel: 248-848-4000

Houston, TX Tel: 281-894-5983

Indianapolis Noblesville, IN Tel: 317-773-8323

Tel: 317-773-8323 Fax: 317-773-5453

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608

New York, NY Tel: 631-435-6000

San Jose, CA Tel: 408-735-9110

Canada - Toronto Tel: 905-673-0699

Tel: 905-673-0699 Fax: 905-673-6509

#### ASIA/PACIFIC

**Asia Pacific Office** 

Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon Hong Kong

Tel: 852-2401-1200 Fax: 852-2401-3431

Australia - Sydney Tel: 61-2-9868-6733

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8569-7000 Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

China - Chongqing

Tel: 86-23-8980-9588 Fax: 86-23-8980-9500

China - Hangzhou Tel: 86-571-2819-3187

Fax: 86-571-2819-3189

China - Hong Kong SAR Tel: 852-2943-5100 Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460 Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8864-2200 Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

China - Xian

Tel: 86-29-8833-7252 Fax: 86-29-8833-7256

China - Xiamen

Tel: 86-592-2388138 Fax: 86-592-2388130

China - Zhuhai Tel: 86-756-3210040

Tel: 86-756-3210040 Fax: 86-756-3210049

#### ASIA/PACIFIC

India - Bangalore

Tel: 91-80-3090-4444 Fax: 91-80-3090-4123

India - New Delhi

Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-3019-1500

Japan - Osaka

Tel: 81-6-6152-7160 Fax: 81-6-6152-9310

Japan - Tokyo

Tel: 81-3-6880- 3770 Fax: 81-3-6880-3771

Korea - Daegu

Tel: 82-53-744-4301 Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857 Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870 Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065 Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870 Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-5778-366 Fax: 886-3-5770-955

Taiwan - Kaohsiung

Tel: 886-7-213-7830

Taiwan - Taipei

Tel: 886-2-2508-8600 Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351 Fax: 66-2-694-1350

# **EUROPE**

Austria - Wels

Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany - Dusseldorf Tel: 49-2129-3766400

Germany - Munich

Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

**Germany - Pforzheim** Tel: 49-7231-424750

Italy - Milan

Tel: 39-0331-742611 Fax: 39-0331-466781

Italy - Venice

Tel: 39-049-7625286

Netherlands - Drunen Tel: 31-416-690399

Fax: 31-416-690340

**Poland - Warsaw** Tel: 48-22-3325737

Spain - Madrid

Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

Sweden - Stockholm

Tel: 46-8-5090-4654

**UK - Wokingham** Tel: 44-118-921-5800 Fax: 44-118-921-5820

10/28/13