

Task 8: Descriptive Statistics and Technical Interpretation

Name: Unnabh Baruah

Reg no: 240961174

Subsystem: Software & ML

Objective

The objective of this task is to understand descriptive statistics as tools for reasoning about measurement data rather than as formulas to memorize. The focus is on what statistics reveal, what they hide and what conclusions remain valid once units, sample size, outliers and domain context are taken into account.

1. Descriptive Statistics and Why They Matter

Descriptive statistics are numerical summaries that describe the main features of a dataset such as its center, spread and shape. They are used before cleaning decisions, visualization, feature creation or machine learning because they give a quick sense of what the data looks like and whether it contains problems such as outliers, missing values or inconsistent scales that need to be addressed first.

However statistics summarize a dataset without explaining why a pattern exists. A dataset can be numerically summarized and still be poorly understood. For example a mechanical dataset might show a mean strain value that looks reasonable, but the underlying readings could actually come from two different materials tested under different conditions. The mean would hide this mixture completely and give a false sense of a single consistent process.

2. Center and Spread

Mean is the average of all values in a dataset. Median is the middle value when the data is arranged in order. Minimum and maximum are the smallest and largest values present, and range is the difference between them. Variance measures how far values are spread from the mean on average, using squared differences, while standard deviation is the square root of variance and is expressed in the same unit as the original data, making it easier to interpret. IQR, or interquartile range, is the range covering the middle fifty percent of the data and is calculated as the difference between the seventy fifth and twenty fifth percentiles.

Center describes where most values in a dataset are located, while spread describes how much the values vary around that center. Two datasets can share the same mean but have very different spreads, which means center alone is not enough to describe a dataset.

The mean becomes misleading when a dataset contains outliers or is heavily skewed, since even one extreme value can pull it away from where most of the data actually lies. The median is more stable in these cases because it depends only on the middle value's position and not on the magnitude of extreme readings.

A high standard deviation in an experimental measurement means the readings are inconsistent and spread widely around the mean, which could point to measurement error, an unstable process or genuine variation in the phenomenon being studied. IQR is useful when data is skewed or contains outliers because, like the median, it ignores extreme values at either end and focuses only on the central portion of the data, giving a more reliable sense of typical spread.

3. Distribution Shape and Sample Size

A distribution shows how the values of a numerical variable are spread across their possible range, revealing where values cluster and how frequently different ranges occur. Skewness indicates that a distribution leans more toward one side, with a longer tail extending in one direction. Clusters can indicate the presence of distinct subgroups within the data, while gaps may indicate missing measurement ranges or a threshold effect. Overall spread indicates how consistent or variable the underlying process is.

A statistic calculated from five readings is far weaker than one calculated from five hundred readings because small samples are much more sensitive to random variation and individual extreme values. A single unusual reading in a sample of five can shift the mean substantially, while the same reading in a sample of five hundred has almost no effect. Sample size therefore matters before trusting a mean, variance or visual pattern, since small samples may reflect chance rather than a real underlying trend.

For example if only five pressure readings are taken from a mechanical test rig and one of them happens to be unusually high due to a temporary fault, the resulting mean could suggest the system regularly operates under high pressure, when in reality this was an isolated event that a larger sample would have diluted or revealed as an outlier.

4. Outliers and Domain Context

An outlier is a value that lies far from the rest of the data in a dataset, standing apart from the general pattern that most observations follow. Not every outlier is automatically an error, since it can also represent a genuine rare event, a boundary condition or an important discovery that deserves closer attention. An outlier should be investigated rather than removed whenever there is no clear evidence that it resulted from a measurement fault, a data entry mistake or a sensor malfunction.

In Biochemistry, a pH value far outside the expected range could indicate sample contamination, use of the wrong buffer or a genuine chemical reaction that needs further study rather than simple measurement error. In Electronics, a sudden current spike could indicate an overload condition, a transient switching event or an actual short circuit, each of which requires a different response. In Mechanical measurements, an unusually high force reading could indicate a stronger than expected material, a unit mismatch during recording, sensor saturation or a rare but real structural event. In all three cases the correct approach is to investigate the cause first rather than deleting the value without explanation.

5. Plot Selection and Interpretation

Every plot must include a clear title, axis labels and units, since a plot without this information cannot be interpreted reliably even if the underlying data is correct. The choice of plot type depends on what aspect of the data needs to be shown.

Plot Type	When to use	Domain Example
Histogram	To show the distribution and frequency of a single numerical variable	Distribution of pH readings across multiple biochemistry samples

Box plot	To show center, spread and outliers of a numerical variable, especially when comparing groups	Comparing voltage readings across low load and high load electronic conditions
Bar chart	To compare values across categorical groups	Number of samples recorded for each biomolecule type in a biochemistry dataset
Scatter plot	To show the relationship between two numerical variables	Relationship between depth and rate of penetration in mechanical drilling data
Line plot	To show how a variable changes over time or in sequence	Current readings recorded over time during a circuit test

6. Correlation, Causation and Confounding

Correlation describes a statistical relationship where two variables tend to change together, either increasing together or moving in opposite directions. Causation means that a change in one variable directly produces a change in another. Two variables increasing together does not prove that one caused the other, since both could be influenced by a third factor or the relationship could simply be coincidental within the observed data.

A confounding variable is a hidden factor that influences both variables being studied, creating an apparent relationship between them that is not actually direct. For example if student attendance and exam scores both increase together, it may be tempting to conclude that attendance causes higher scores, but a confounding variable such as overall motivation or study habits could be driving both attendance and performance independently.

7. Domain Measurement Interpretation and Comparability

An overall mean calculated across pH, voltage, current, force and pressure would be meaningless because these variables measure entirely different physical and chemical quantities using different units and scales. Averaging them produces a number with no real world interpretation. Units are part of the meaning of a value, since the same number can represent completely different quantities depending on the unit attached to it. For this reason values should always be grouped by domain, measurement type, unit and experimental condition before any interpretation or comparison is attempted.

Valid Comparisons	Invalid or Misleading Comparisons
Average voltage under low load versus high load, using the same measurement setup	Average pH compared numerically against average voltage
Force readings across two material samples tested under identical conditions	Force in newtons compared directly against force in pounds without conversion
ROP values recorded at different depths within the same drilling operation	An overall average combining pH, current and pressure into one number

Before analyzing domain measurement data it is important to request additional information such as the exact unit used for each variable, the experimental condition or setup under which

the readings were taken, whether the data is raw or already processed and what range of values is considered normal for that specific measurement.

8. Final Reflection

Statistics can be technically correct in their calculation while still being scientifically or practically misleading in their interpretation. A mean or standard deviation computed without checking units can combine incompatible quantities into a single meaningless number, such as averaging pH with voltage. Mixed measurement types create the same problem even within a single domain, since combining readings taken under different experimental conditions can hide the real pattern in the data. Small sample sizes make any statistic fragile, since a handful of readings can be dominated by chance variation or a single extreme value that would be diluted in a larger dataset. Outliers left unexamined can either distort a summary or, if removed carelessly, erase a genuine and important finding. Missing context about how, when and under what condition data was collected makes it impossible to judge whether a comparison is even valid. Finally, mistaking correlation for causation can lead to confident but false conclusions about what is actually driving a pattern. A statistically correct number is only useful once it is interpreted with full awareness of its unit, its sample size, its conditions and what it does and does not prove.

REFERENCES

- [1] D. Diez, M. Cetinkaya-Rundel and C. Barr, *OpenIntro Statistics*, OpenIntro. [Online]. Available: <https://www.openintro.org/book/os/>
- [2] Khan Academy, "Statistics and Probability," Khan Academy. [Online]. Available: <https://www.khanacademy.org/math/statistics-probability>
- [3] National Institute of Standards and Technology, "Exploratory Data Analysis," NIST/SEMATECH e-Handbook of Statistical Methods. [Online]. Available: <https://www.itl.nist.gov/div898/handbook/eda/eda.htm>