

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 26, T 10 N - R 6 E, on a 20-46° curve to the right, 1337.50 feet to Sta. 1292 plus 14.53;

Thence, passing through the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 26, T 10 N-R 6 E on a tangent having a true bearing of S 89° 0' - 11° - 29° E, 2887.47 feet to Sta. 1321 plus 02.00; at which point the said center line intersects the section line between Secs. 25 and 26, T 10 N-R 6 E, 843.0 feet south of Section corner 25-24-25-26, T 10 N - R 6 E;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 25, T 10 N-R 6 E, along the same tangent having a true bearing of S 89°-11° - 29° E, 322.77 feet to Sta. 1324 plus 24.77;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 25, T 10 N-R 6 E, along a tangent having a true bearing of S 89° - 38° E, 3135.46 feet to Sta. 1355 plus 60.23;

Thence, passing through the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 25, T 10 N-R 6 E, along a tangent having a true bearing of N 89° - 59° - 01° E, 1833.33 feet to Sta. 1373 plus 93.56;

Thence, passing through the NE $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 25, T 10 N - R 6 E, along a 10 - 14° Curve to the left, 17.44 feet to Sta. 1347 plus 11.00, at which point the said center line intersects the section line between Secs. 25, T 10 N - R 6 E, and Sec 30, T 10 N - R 7 E, 758.00 feet south of Section Corner 24-25, T 10 N - R 6 E, 19-30, T 10 N - R 7 E;

Thence, passing through NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 30, T 10 N - R 7 E, on a 10-14° Curve to the left, 1160.26 feet to Sta. 1385 plus 71.26;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 30, T 10 N - R 7 E, along a tangent having a true bearing of N 75° - 27° - 46° E, 1906.72 feet to Sta. 1404 plus 77.98;

Thence, passing through the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 30, T 10 N - R 7 E, along a tangent having a true bearing of N 74° - 50° - 42° E, 717.62 feet to Sta. 1411 plus 95.00 at which point the said center line intersects the section line between Secs. 19 and 30, T 10 N - R 7 E 365 feet west of NE Corner of said NW $\frac{1}{4}$ of NE $\frac{1}{4}$ of said section 30 (measured along section line);

Thence passing through the S $\frac{1}{2}$ of the SE $\frac{1}{4}$ of Sec. 19, T 10 N - R 7 E, along the same tangent, having a true bearing of N 74° - 50° - 42° E, 1693.50 feet to Sta. 1428 plus 88.00, at which point the said center line intersects the sections line between Secs. 19 and 20, T 10 N - R 7 E 418.0 feet north of section Corner 19 - 20 - 29 - 30, T 10 N - R 7 E;

Thence, passing through the S $\frac{1}{2}$ of the SW $\frac{1}{4}$ and the W $\frac{1}{2}$ of the SE $\frac{1}{4}$ of Sec. 20, T 10 N - R 7 E, along the same tangent, having a true bearing of N 74° - 50° - 42° E, 3722.63 feet to Sta. 1466 plus 10.63;

Thence, passing through the NW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec. 20, T 10 N-R 7 E, on a 60-48° curve to the left, 788.54 feet to Sta. 1473 plus 99.17;

Thence, passing through the NE $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec. 20, T 10 N - R 7 E on a tangent having a true bearing of N 68° - 32° - 47° E, 1618.83 feet to Sta. 1484 plus 18.6, at which point said center line intersects section line between Secs. 20 and 21, 658 feet south of NE Corner of said NE $\frac{1}{4}$ of SE $\frac{1}{4}$ of said Section 20 (measured along Section line);

Thence, passing through the NW $\frac{1}{4}$ of the SW $\frac{1}{4}$, the SE $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the SW $\frac{1}{4}$ of the NE $\frac{1}{4}$, all of Sec. 21, T 10 N - R 7 E, on the same tangent, having a true hearing of N 68° - 32° - 47° E, 4182.00 feet to Sta. 1526 plus 00.00;

Thence, passing through the S $\frac{1}{2}$ of the NE $\frac{1}{4}$ of the NE $\frac{1}{4}$ and the NE $\frac{1}{4}$ of Sec. 21, TION-R7E, on a tangent having a true bearing of N 68°-25° E, 1530.0 feet to Sta. 1541 plus 30, at which point said center line intersects Section Line between Secs. 21 and 22, TION-R7E, 1230.0 feet south of Section Corner 15-16-21-22, TION-R7E;

Thence passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 22, TION-R7E, on the same tangent, having a true bearing of N 68°-22°-25° E, 1370.0 feet to Sta. 1555 plus 00.00;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$, and the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 22, TION-R7E, along a tangent having a true bearing of N 67°-58°-32° E, 1924.0 feet to Sta. 1574 plus 24.00, at which point said center line intersects section line between Secs. 15 and 22, T 10 N - R 7 E, 415 feet east of NW Corner of said NW $\frac{1}{4}$ of NE $\frac{1}{4}$ Section 22 (Measured along Section line);

Thence, passing through the S $\frac{1}{2}$ of the SE $\frac{1}{4}$ of Sec 15, T 10 N-R 7 E, along the same tangent, having a true bearing of N 67°-58°-32° E, 2434.00 feet to Sta. 1598 plus 58.00, at which point said center line intersects section line between Secs. 14 and 15, T 10 N-R 7 E, 914.00 feet north of Section Corner 14-15-22-33, T 10 N-R 7 E;

Thence, passing through the SW $\frac{1}{4}$ of the SW $\frac{1}{4}$ and the NW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec. 14, T 10 N-R 7 E, along the same tangent, having a true bearing of N-67° -58°-32° E, 2565.9 feet to Sta. 1624 plus 23.90;

Thence, passing through the NE $\frac{1}{4}$ of the SW $\frac{1}{4}$ and the NW $\frac{1}{4}$ if the SE $\frac{1}{4}$ of Sec. 14, T 10 N-R 7 E, on a 20-52° Curve to the left, 1612.72 feet to Sta. 1634 plus 36.62;