

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 19, T9N-R5E, on a 40-00' Curve to the right, 1475.54 feet to Sta. 654 plus 39.01;

Thence, passing through the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the W $\frac{1}{2}$ of the NE $\frac{1}{4}$ of Sec. 19, T9N-R5E, on a tangent having a true bearing S 70°-27'-21" E, 1300.52 feet to Sta. 667 plus 39.53;

Thence, passing through the S $\frac{1}{2}$ of the NE $\frac{1}{4}$ of Sec. 19, T9N-R5E, on a 40-04' Curve to the left, 761.01 feet to Sta. 675 plus 00.54;

Thence, passing through the SE $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 19, T9N-R5E, on a tangent having a true bearing of N 78°-36'-03" E, 1124.46 feet to Sta. 686 plus 25.00, at which point said center line intersects section line between Secs. 19 and 20, T9N-R5E, 25 feet South of NE corner of said SE $\frac{1}{4}$ of NE $\frac{1}{4}$ (measured along section line);

Thence, passing through the SW $\frac{1}{4}$ of the NE $\frac{1}{4}$ and the N $\frac{1}{2}$ of the NW $\frac{1}{4}$ of Sec. 20, T9N-R5E, along the same tangent, having a true bearing of N 78°-36'-03" E, 1561.99 feet to Sta. 701 plus 86.99;

Thence, passing through the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 20, T9N-R5E, on a 60 - 40' Curve to the left, 260.66 feet to Sta. 704 plus 47.65;

Thence passing through the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec 20, T9N-R5E on a tangent having a true bearing of N 61° - 13' - 43", 1980.35 feet to Sta. 724 plus 28.00, at which point said center line intersects section line between Secs 20 and 17, T9N-R5E, 465 feet west of NE Corner of NW $\frac{1}{4}$ of NE $\frac{1}{4}$ said Section 20 (Measured along said Section line);

Thence, passing through the S $\frac{1}{2}$ of the SE $\frac{1}{4}$ of Sec 17, T 9 N - R 5 E, along the same tangent, having a true bearing of N 61° - 13' - 43" E, 926.07 feet to Sta. 733 plus 54.02;

Thence, passing through the SE $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec 17, T 9 N - R 5 E on a 30-08' Curve to the right, 641.49 feet to Sta. 739 plus 95.56;

Thence, passing through the SE $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec 17, T 9 N - R 5 E, on a tangent having a true bearing N 81°-20' - 11" E, 371.44 feet to Sta. 743 plus 67.00, at which point said center line intersects section line between Secs. 17 and 16, T 9 N - R 5 E, 703 feet north of Section Corner 16-17-20-21, T 9 N - R 5 E, measured along said section line;

Thence, passing through Lot No. 2 of Section 16, T 9 N, along the same tangent, having a true bearing of N 81° - 20' - 11" E, 2519.00 feet to Sta. 768 plus 86.00, at which point said center line intersects the "Choctaw Boundary Line" 1098 feet (measured along the boundary line) North of the intersection of Section Line between Secs. 16 and 21, T 9 N - R 5 E, with said "Choctaw Boundary Line";

Thence, passing through Lots Nos. 6 and 5 of Sec. 21, T 9 N - R 5 E, east of said Choctaw Boundary Line, along the same tangent, having a true bearing N 81° - 20' - 11" E, 2764.00 feet to Sta. 796 plus 50.00, at which point said center line intersects section line between Secs. 21 and 22, T 9 N - R 5 E, 838 feet south of Section Corner 15 - 16-21 - 22, T 9 N - R 5 E;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 22, T 9 N - R 5 E, along the same tangent, having a true bearing of N 81° - 20' - 11" E, 341.59 feet to Sta. 799 plus 91.59;

Thence, passing through the N $\frac{1}{2}$ of the NW $\frac{1}{4}$ of Sec. 22, T 9 N - R 5 E, on a tangent having a true bearing of N 80° - 51' 22" E, 1474.70 feet to Sta. plus 66.29;

Thence, passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ and the NW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 22, T9N-R5E, on a 30-32' Curve to the left, 1107.71 feet to Sta. 825 plus 74.00, at which point said center line intersects section line between Secs. 22 and 15, T9N-R5E, 113 feet east of NW Corner of NW $\frac{1}{4}$ of NE $\frac{1}{4}$ of said Section 22 (measured along said Section line);

Thence, passing through the SW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec. 15, T9N-R5E, along the same 30 - 32' Curve to the left, 559.86 feet to Sta. 831 plus 33.86;

Thence, passing through the W $\frac{1}{2}$ of the SE $\frac{1}{4}$ of Sec. 15, T9N-R5E, on a tangent having a true bearing of N 21° - 56' - 16" E, 1647.85 feet to Sta. 847 plus 81.71;

Thence, passing through the NW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Sec. 15, T 9 N - R 5 E, on a 30 - 15' Curve to the right, 374.74 feet to Sta. 851 plus 56.45;

Thence, passing through the N $\frac{1}{2}$ of the SE $\frac{1}{4}$ and the E $\frac{1}{2}$ of the NE $\frac{1}{4}$ of Sec. 15, T9N-R5E, on a tangent having a true bearing of N 34° - 07' - 09" E, 2321.26 foot to Sta. 874 plus 77.71;

Thence passing through the NE $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 15, T9N-R5E on a tangent having a true bearing N 34° - 30' - 47" E, 271.29 feet to Sta. 877 plus 49.00, at which point said center line intersects section line between Secs. 15 and 14, 790 feet south of Section Corner 10-11-14-15, T9N-R5E (measured along section line);

Thence passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 14, T9N - R5E, along the same tangent, having a true bearing of N 34° - 30' - 47" E, 900.49 feet to Sta. 886 plus 49.49;

Thence passing through the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec 14, T 9 N - R 5 E, on a 20 - 50' Curve to the left, 57.51 feet to Sta. 887 plus 08.00, at which point said center line intersects section line between Secs. 14 and 11, 538 feet east of Section Corner 10-11-14-15, T9N-R5E (measured along section line);

Thence, passing through the SW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec. 11, T9N-R5E, on the same 20-50' Curve to the left, 180.21 feet to Sta. 888 plus 87.21;

Thence, passing through the SW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec. 11, T 9 N - R 5 E, on a tangent having a true bearing N 27° - 46' - 50" E, 1048.85 feet to Sta. 899 plus 36.06;

Thence, passing through the W $\frac{1}{2}$ of the SW $\frac{1}{4}$ and the NE $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec 11, T9N-R5E, on a 20 - 42' Curve to the right, 549.23 feet to Sta. 904 plus 85.29;

Thence, passing through the NE $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec. 11, T9N-R5E, on a tangent having a true bearing of N 42° - 36' - 39" E, 564.94 feet to Sta. 910 plus 50.23;

Thence, passing through the NE $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Sec. 11, T9N-R5E, on a 10-54' Curve to the right, 450.00 feet to Sta. 915 plus 00.23;