NOTES:

1. SAG MILL DISCHARGE DENSITY CALCULATION.
2. FLANGED ASME B16.5 CLASS 150.
3. FEED AND DISCHARGE END TRUNION BEARING PRESSURE INDICATORS USED IN FUNCTION BLOCK FOR MILL WEIGHT CALCULATION; PI13644, PI13645, PI13646, PI13647, PI13648, PI13649, PI13650 & PI13651.
4. SIGNALS FROM SAG MILL MOTOR 1 AND 2 VSD.
5. SIGNALS SAG MILL LOAD IQ SERVER.
6. SHARED BETWEEN THE SAG AND BALL MILL.
7. FLANGED ASME B16.5 CLASS 150.

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0872-PW-PE16-225

PE16 SS2

13-0092-PW-SS2-200

FIT 13123
FE 13123
DETAIL 1
FIC 13123
FCV 13123

200VBFE1S2 F13-10167

200VBFE1S2 F13-10168

50VB03S1 F13-10171

TO GRADE

200x150

150VBFE1S1 FC

200x150

200VBFE1S2 F13-10169

13-0093-PW-SS2-200

200VBFE1S2 F13-10170

WIC13121
2000-F13-PID-PR-10001
SIGNAL

f(x) m³/t

% SOLIDS NOTE 1

HS 13121

FIC 13121

FE 13121

FIT 13121

DETAIL 1
FCV 13121

MILL WATER PUMPS
2000-F24-PID-PR-10001
PROCESS WATER

13-0032-PW-SS1-300

300VBFD1S2 F13-10172

300VBFD1S2 F13-10173

50VB03S1 F13-10176

TO GRADE

300VBFD1S1 FC

300VBFD1S2 F13-10174

SS1 PE8

13-1257-PW-PE8-315

SS1

SS3

13-0033-PW-SS1-300

300VBFD1S2 F13-10175

SP SC-028

CYCLONE UNDERFLOW BOIL BOX
2000-F13-PID-PR-10002
CYCLONE UNDERFLOW

13-1211-MS-RL3-750

F13-BX-401
SAG MILL FEED BOX

13-2434-PW-SS3-50

50VB03S1 F13-10338

SAG MILL FEED CONVEYOR
2000-F13-PID-PR-10001
COARSE ORE

MECH

F13-CH-430
SAG MILL FEED CONVEYOR HEAD CHUTE

SP SC-028

LAH 13058

LSH 13058

F13-CH-431
SAG MILL FEED CHUTE

13-0079-MS-RL3-750

PIPING

COARSE ORE STOCKPILE 2 SUMP
2000-F13-PID-PR-10001
SPILLAGE

13-0016-FD-PE10-90

F13-CH-432
SAG MILL CONVEYOR CLEANOUT CHUTE

F13-GA-431
SAG MILL SLIDE GATE

MECH

F13-CH-427
SAG MILL TROMMEL COVER

F13-HC-501
F13-HD-501
SAG FEED ISOLATION GATE MONORAIL AND CHAIN DRIVEN TROLLEY 1

F13-HD-502
SAG FEED ISOLATION GATE CHAIN DRIVEN TROLLEY 2

F13-HC-503
F13-HD-503
SAG FEED ISOLATION GATE MONORAIL AND MANUAL TROLLEY 1

F13-HD-504
SAG FEED ISOLATION GATE MANUAL TROLLEY 2

CCTV F13-CAM-002

F13-MS-401
SAG MILL

SP SP-002 13 OFF

F13-SC-404
SAG MILL TROMMEL

F13-XM-406
SAG MILL FEED SPOUT

F13-CH-468
SAG MILL FEED END CLEANOUT CHUTE

13-1273-FD-PE8-630

VENDOR PACKAGE
2000-ME001.2-D07-50002 & 2000-F13-PID-PR-10010

F13-MS-401 START-UP SIREN 2
F13-MS-401 START-UP SIREN 1
BARRING SIREN

YA 13133B
YA 13133A
YA 13132

SI 13137A HH H L LL MASTER VSD SPEED
JI 13136A H MASTER VSD POWER
SI 13137B HH H L LL SLAVE VSD SPEED
JI 13136B H SLAVE VSD POWER
XA 13139 COMMON VSD FAULT

f(x) JIC 13136

NOTE 4

F13-AN-406
SAG MILL MILL SCANNER (LOAD IQ)

F13-XM-417
SAG MILL ACOUSTIC ANALYSER (MANTA-MIC)

F13-HU-416
SAG MILL BRAKE HYDRAULIC POWER UNIT

F13-LU-413
SAG MILL MAIN BEARINGS LUBRICATION UNIT

F13MS401A-VS
SAG MILL MOTOR 1 VSD

F13MS401B-VS
SAG MILL MOTOR 2 VSD

F13-BK-401
SAG MILL BRAKE 1

F13-LU-416
SAG MILL SEAL GREASE SYSTEM

F13-MS-401A
SAG MILL MOTOR 1

F13-MS-401B
SAG MILL MOTOR 2

F13-BK-402
SAG MILL BRAKE 2

F13-LU-411
SAG MILL MOTOR LUBRICATION UNIT

F13-LU-424
MILL RING GEAR SPRAY SYSTEM

NOTE 6

F13-XM-421
PORTABLE MILLS INCHING DRIVE

NOTE 6

F13-HU-413
MILL INCHING DRIVE HYDRAULIC POWER UNIT

NOTE 6

XIC 13135 H L

WIC 13135 HH H

f(x) PV

NOTE 3

VOLUME WEIGHT

HS 13135

WIC13121
2000-F13-PID-PR-10001
SIGNAL

ZI 13945 INCHING DRIVE BALL MILL PLACEMENT POSITION SWITCH
ZI 13944 INCHING DRIVE SAG MILL PLACEMENT POSITION SWITCH
XI 13759 INCHING DRIVE HPU MOTOR RUN FEEDBACK
XI 13743 INCHING DRIVE HPU PERMISSION

F13-CR-413
MILL LINER BOLT HAMMER 1 JIB HOIST 1

F13-CR-414
MILL LINER BOLT HAMMER 1 JIB HOIST 2

F13-HC-481
F13-HD-481
MILL LINER BOLT HAMMER 1 MONORAIL 1 AND TROLLEY 1

F13-HC-482
F13-HD-482
MILL LINER BOLT HAMMER 1 MONORAIL 2 AND TROLLEY 2

F13-LH-401
SAG MILL LINER HANDLER

F13-LRT-401
MILL LINER BOLT HAMMER 1

F13-HC-483
F13-HD-483
MILL LINER BOLT HAMMER 2 MONORAIL 1 AND TROLLEY 1

F13-HC-484
F13-HD-484
MILL LINER BOLT HAMMER 2 MONORAIL 2 AND TROLLEY 2

F13-HU-411
MILL LINER BOLT HAMMER 1 POWER PACK

VENDOR PACKAGE

F13-CH-429
SAG MILL TROMMEL DISCHARGE SCREEN FEED CHUTE
MECH

SAG MILL DISCHARGE SCREEN
2000-F13-PID-PR-10002
SAG MILL SCATS

F13-CH-428
SAG MILL TROMMEL UNDERFLOW CHUTE

MECH

BALL MILL DISCHARGE LAUNDER
2000-F13-PID-PR-10002
SAG MILL DISCHARGE

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0123-PW-PE16-90

80VBFE1L2 F13-10177

PEBBLE BUNKER
2000-F13-PID-PR-10002
PEBBLES

MECH

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0122-PW-PE16-160

160x110

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0142-PW-PE16-110

RL1 PE10

13-0034-FD-RL1-200

50VB03S1 F13-10184

SP MC-002

200VKGD1L1 F13-10183

50VB03S1 F13-10182

SP MC-002

SP HS-003

SP HS-003

200x150

O/F

F13-PS-404
MILL DISCHARGE END SUMP PUMP

MILL FLOOR

F13-XM-478
MILL FEED DECK DRAIN

13-2507-FD-PE10-160
13-0028-FD-PE10-160
13-0038-FD-PE10-160
13-2144-FD-MSG3-50
13-2145-FD-MSG3-50
13-2146-FD-MSG3-50
13-2147-FD-MSG3-50
13-1097-FD-PE10-160
13-2148-FD-MSG3-50
13-2149-FD-MSG3-50
13-2150-FD-MSG3-50
13-2151-FD-MSG3-50
13-1096-FD-PE10-160
13-1095-FD-PE10-160
13-1093-FD-PE10-160

MSG3 PE10

PE10 MSG3

110x63

13-2158-FD-PE10-110

13-0047-FD-PE10-280

MILL FEED END DRIVE-IN SUMP

SP MC-002

SP MC-002

50VB03S1 F13-10185

50VB03S1 F13-10187

150VKGD1L1 F13-10186

150x100

LSH 13131

LAH 13131

NOTE 2

F13-PS-405
MILL FEED END SUMP PUMP

13-0035-FD-PE10-225

PRIMARY CYCLONE FEED HOPPER
2000-F13-PID-PR-10002
SPILLAGE

13-2487-FD-RL1-150

RL1 PE10

13-0037-FD-PE10-160

BALL MILL DISCHARGE LAUNDER
2000-F13-PID-PR-10002
SPILLAGE

F13-HC-449
F13-HD-449
MILL DISCHARGE DRIVE IN SUMP MONORAIL AND TROLLEY

13-0143-PW-SS2-100

100VBFE1S2 F13-10180

100x65

F13-XM-585
MILL DISCHARGE AREA DRIVE-IN SUMP MONITOR NOTE 7

MILL DISCHARGE AREA DRIVE-IN SUMP

PE16 SS2

100VBFE1S2 F13-10181

13-0124-PW-SS2-100

LI 13130 HH H

LI 13130

LT 13130

2°

FLOTATION AREA SUMP PUMP 1
2000-F16-PID-PR-10001
OVERFLOW