BALL CHARGING MAGNET BIN CHUTE
2000-F19-PID-PR-10007
BALL MILL BALLS

BALL CHARGING MAGNET BIN CHUTE
2000-F19-PID-PR-10007
SAG MILL BALLS

BALL CHARGING MAGNET BIN CHUTE
2000-F19-PID-PR-10007
SAG MILL BALLS

LE 19757 — LIT 19757
LE 19756 — LIT 19756
LE 19755 — LIT 19755

NOTE 3
LI 19755 H L
LIT 19755
LE 19755
19-BN-61A
BALL CHARGING BIN No. 1

NOTE 3
LI 19756 H L
LIT 19756
LE 19756
19-BN-61B
BALL CHARGING BIN No. 2

NOTE 3
LI 19757 H L
LIT 19757
LE 19757
19-BN-61C
BALL CHARGING BIN No. 3

FV 19660
FV 19661
FV 19662

19-FE-61
BALL FEEDER NO.1
19-FE-62
BALL FEEDER NO.2
19-FE-63
BALL FEEDER NO.3

M
19-CH-82A
CONVEYOR 62 FEED CHUTE NO.1
19-CH-82B
CONVEYOR 62 FEED CHUTE NO.2
19-CH-82C
CONVEYOR 62 FEED CHUTE NO.3

SSL 19673
SAL 19673
ZS 19674E
ZS 19674F
ZA 19674E
ZS 19674C
ZS 19674D
ZA 19674C
19-CV-62
BALL CHARGE CONVEYOR No. 1
ZS 19674A
ZS 19674B
ZA 19674A
HS 19675A
HS 19675B
HA 19675A
19-CV-67
CONVEYOR CV62 HEAD CHUTE

19-CR-XX
OVERHEAD CRANE
HOLD 2

19-DG-61
FIM
SAG MILL CHARGE DIVERTER GATE
FV 19663

19-DG-51
MT CHARLOTTE SAG MILL CHARGE DIVERTER GATE
FV 19664

SSL 19676
SAL 19676
HS 19678A
HS 19678B
HA 19678A
19-CV-63
NEW MILLS BALL CHARGE CONVEYOR No. 2
19-CH-62
FIM SAG MILL BALL FEED CHUTE
ZS 19677A
ZS 19677B
ZA 19677A
ZS 19677C
ZS 19677D
ZA 19677C

MECH
FIM (19-MS-61) SAG MILL FEED CHUTE
2000-F19-PID-PR-10001
MILL BALL

NOTES:

1. FOR GENERAL NOTES, REFER TO 2000-F00-PID-PR-10001 TO 10007.
2. INSTRUMENT NUMBERS AND CONTROL LOGIC CONNECTIONS ARE REFERENCED FROM DCS.
3. PROCESS SWITCHPOINTS USED TO AUTO INITIATE THE BALL CHARGING SEQUENCE IF F19-BLC-401 IS IN LOCAL/REMOTE AUTO MODE AND AUTO START IS ENABLED.

HOLDS:

1. INSTRUMENT TYPE NOT SIGHTED IN THE FIELD AND IS CURRENTLY UNCONFIRMED.
2. EQUIPMENT SIGHTED BUT NO TAG NUMBER IS CONFIRMED.
3. CLIENT TO CONFIRM LINE SERVICE, NO APPLICABLE SERVICE DESCRIPTION FOUND IN EPC STANDARD.

ORIGINAL DRAWING: FME-19-PI-422