NOTES:

1. REFER TO 2000-F24-PID-PR-10034 FOR GLAND WATER DETAIL.
2. CYCLONE OVERFLOW DENSITY CALCULATION.
3. FLANGES AT INTERFACES TO BE TABLE E.
4. 88.2° BEND TO BE 2 OFF 44.1° CERAMIC LINED SEGMENTS.
5. GRAVITY CYCLONE FEED VALVES INCLUDED AS PART OF PRIMARY CYCLONE CLUSTER SUPPLY BY VENDOR.
6. CHAIN OPERATOR. 2.5m LONG.
7. CERAMIC LINED PREFORMED SLURRY HOSE REDUCER 900x750.
8. CHAIN OPERATOR. 1.2m LONG.
9. MANUAL ISOLATION GATE AT CHUTE/CONVEYOR INTERFACE FOR MAINTENANCE PURPOSES.
10. VIBRATION SENSOR VE13120U IS A SPARE.

HIGH PRESSURE PROCESS WATER PUMPS
2000-F14-PID-PR-10001
HP PROCESS WATER
13-1604-PW-SS2-80

HIGH PRESSURE PROCESS WATER PUMPS
2000-F14-PID-PR-10001
HP PROCESS WATER
13-1605-PW-SS2-80

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER
13-0050-PW-PE16-280

SAG MILL TROMMEL SCREEN
2000-F13-PID-PR-10003
SAG MILL SCATS
MECH

MILL WATER PUMPS
2000-F24-PID-PR-10001
PROCESS WATER
13-0021-PW-SS1-600

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER
13-0055-PW-SS2-400

MILL DISCHARGE END SUMP PUMP
2000-F13-PID-PR-10003
SPILLAGE
13-0035-FD-PE10-225

INTENSIVE CYANIDATION LEACH REACTOR
2000-F14-PID-PR-10003
INTENSIVE CYANIDATION TAILINGS
14-0236-CS-PE10-225

COPPER SULPHATE DOSING PUMPS
2000-F72-PID-PR-10008
COPPER SULPHATE
72-1149-CO-PE8-25

ILR AREA SUMP PUMP
2000-F14-PID-PR-10003
SPILLAGE
14-0057-FD-PE10-90

MILL FEED END SUMP PUMP
2000-F13-PID-PR-10003
SPILLAGE
13-0037-FD-PE10-160

SAG MILL TROMMEL UNDERFLOW CHUTE
2000-F13-PID-PR-10003
SAG MILL DISCHARGE
MECH

BALL MILL TROMMEL UNDERFLOW CHUTE
2000-F13-PID-PR-10004
BALL MILL DISCHARGE
MECH

EXISTING FIM SAG CIRCUIT
2000-F19-PID-PR-10001
FIM SAG MILL DISCHARGE
19-3000-MS-CL1-300

EXISTING FIM SAG CIRCUIT
2000-F19-PID-PR-10001
FIM SAG MILL DISCHARGE
19-3001-MS-CL1-300

F13-CAM-004
CCTV

F13-HC-438
F13-HD-438
FIM SAG DISCHARGE PIPING MONORAIL AND TROLLEY 1

F13-HC-439
F13-HD-439
FIM SAG DISCHARGE PIPING MONORAIL AND TROLLEY 2

F13-CH-434
SAG MILL DISCHARGE SCREEN UNDERPAN

F13-SC-401
SAG MILL DISCHARGE SCREEN
VENDOR PACKAGE

F13-CH-433
SAG MILL DISCHARGE SCREEN OVERSIZE CHUTE

F13-VL-419
BALL MILL DISCHARGE LAUNDER

F13-CR-454
FIM SAG TRANSFER MAINTENANCE JIB CRANE

F13-HP-401
PRIMARY CYCLONE FEED HOPPER

F13-BX-416
PRIMARY CYCLONE FEED HOPPER OVERFLOW BOX

F13-HU-407
CYCLONE FEED PUMP SUCTION VALVE HYDRAULIC POWER UNIT

F13-HU-408
HYDRAULIC THROATBUSH ADJUSTER HPU

F13-PP-401
CYCLONE FEED PUMP

F13-CR-402
CLASSIFICATION AREA OVERHEAD CRANE

F13-CY-401
PRIMARY CYCLONE CLUSTER

F14-CY-411
GRAVITY CYCLONE 1

F14-CY-412
GRAVITY CYCLONE 2

F13-BX-417
GRAVITY CYCLONES OVERFLOW COLLECTION BOX

F13-FD-401
CYCLONE UNDERFLOW BOIL BOX

F13-CH-441
PEBBLE BUNKER OVERFLOW CHUTE

F13-HC-445
F13-HD-445
CYCLONE FEED PUMP DISCHARGE LINE MONORAIL AND TROLLEY

ACTUATED CYCLONE FEED VALVES (15 OFF) FL

CYCLONE VIBRATION SENSORS 18 OFF (WIRED TO SYNERTREX PANEL)

ALL FLANGES TABLE E

VENDOR PACKAGE

GRAVITY SCREEN 1 FEED BOX
2000-F14-PID-PR-10001
CYCLONE UNDERFLOW

GRAVITY SCREEN 2 FEED BOX
2000-F14-PID-PR-10001
CYCLONE UNDERFLOW

TRASH SCREEN FEED DISTRIBUTION BOX
2000-F13-PID-PR-10007
CYCLONE OVERFLOW

SAG MILL FEED BOX
2000-F13-PID-PR-10003
CYCLONE UNDERFLOW

BALL MILL FEED BOX 1
2000-F13-PID-PR-10004
CYCLONE UNDERFLOW

BALL MILL FEED BOX 1
2000-F13-PID-PR-10004
CYCLONE UNDERFLOW

RECYCLE CONVEYOR 1
2000-F13-PID-PR-10005
PEBBLES

MILL DISCHARGE DRIVE-IN SUMP
2000-F13-PID-PR-10003
PEBBLES

TO MILL DISCHARGE END DRIVE-IN SUMP

TO MILL DISCHARGE END DRIVE-IN SUMP