




NOTES:

1. SAG MILL DISCHARGE DENSITY CALCULATION.
2. FLANGED ASME B16.5 CLASS 150.
3. FEED AND DISCHARGE END TRUNION BEARING PRESSURE INDICATORS USED IN FUNCTION BLOCK FOR MILL WEIGHT CALCULATION; PI3644, PI3645, PI3646, PI3647, PI3648, PI3649, PI3650 & PI3651.
4. SIGNALS FROM SAG MILL MOTOR 1 AND 2 VSD.
5. SIGNALS SAG MILL LOAD IQ SERVER.
6. SHARED BETWEEN THE SAG AND BALL MILL.
7. FLANGED ASME B16.5 CLASS 150.