NOTES:

1. SAG MILL DISCHARGE DENSITY CALCULATION.
2. FLANGED ASME B16.5 CLASS 150.
3. FEED AND DISCHARGE END TRUNION BEARING PRESSURE INDICATORS USED IN FUNCTION BLOCK FOR MILL WEIGHT CALCULATION; PI13644, PI13645, PI13646, PI13647, PI13648, PI13649, PI13650 & PI13651.
4. SIGNALS FROM SAG MILL MOTOR 1 AND 2 VSD.
5. SIGNALS SAG MILL LOAD IQ SERVER.
6. SHARED BETWEEN THE SAG AND BALL MILL.
7. FLANGED ASME B16.5 CLASS 150.

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0872-PW-PE16-225

PE16 SS2

13-0092-PW-SS2-200

FIT 13123
FE 13123
DETAIL 1
FIC 13123
FCV 13123

200VBFE1S2 F13-10167
200VBFE1S2 F13-10168
50VB03S1 F13-10171
200x150
150VBFE1S1 FC
200x150
200VBFE1S2 F13-10169
TO GRADE

13-0093-PW-SS2-200
200VBFE1S2 F13-10170

WIC13121
2000-F13-PID-PR-10001
SIGNAL

f(x) m³/t
% SOLIDS NOTE 1
HS 13121
FIC 13121
FE 13121
FIT 13121

MILL WATER PUMPS
2000-F24-PID-PR-10001
PROCESS WATER

13-0032-PW-SS1-300
300VBFD1S2 F13-10172
300VBFD1S2 F13-10173
50VB03S1 F13-10176
TO GRADE
300VBFD1S1 FC
DETAIL 1
FCV 13121
300VBFD1S2 F13-10174
SS1 PE8
13-1257-PW-PE8-315
SS1
SS3
13-0033-PW-SS1-300
300VBFD1S2 F13-10175

CYCLONE UNDERFLOW BOIL BOX
2000-F13-PID-PR-10002
CYCLONE UNDERFLOW

13-1211-MS-RL3-750
SP SC-028
F13-BX-401 SAG MILL FEED BOX
13-2434-PW-SS3-50
50VB03S1 F13-10338

SAG MILL FEED CONVEYOR
2000-F13-PID-PR-10001
COARSE ORE

MECH
F13-CH-430 SAG MILL FEED CONVEYOR HEAD CHUTE
F13-CH-431 SAG MILL FEED CHUTE
13-0079-MS-RL3-750
SP SC-028
LAH 13058
LSH 13058

COARSE ORE STOCKPILE 2 SUMP
2000-F13-PID-PR-10001
SPILLAGE

13-0016-FD-PE10-90
F13-CH-432 SAG MILL CONVEYOR CLEANOUT CHUTE
F13-GA-431 SAG MILL SLIDE GATE
MECH
PIPING
MECH
F13-CH-427 SAG MILL TROMMEL COVER

F13-MS-401 START-UP SIREN 2
F13-MS-401 START-UP SIREN 1
BARRING SIREN
YA 13133B
YA 13133A
YA 13132

F13-AN-406 SAG MILL MILL SCANNER (LOAD IQ)
F13-XM-417 SAG MILL ACOUSTIC ANALYSER (MANTA-MIC)

F13-HU-416 SAG MILL BRAKE HYDRAULIC POWER UNIT
F13-LU-413 SAG MILL MAIN BEARINGS LUBRICATION UNIT
F13MS401A-VS SAG MILL MOTOR 1 VSD
F13MS401B-VS SAG MILL MOTOR 2 VSD
F13-BK-401 SAG MILL BRAKE 1
F13-LU-416 SAG MILL SEAL GREASE SYSTEM
F13-MS-401A SAG MILL MOTOR 1
F13-MS-401B SAG MILL MOTOR 2
F13-BK-402 SAG MILL BRAKE 2
F13-LU-411 SAG MILL MOTOR LUBRICATION UNIT
F13-LU-424 MILL RING GEAR SPRAY SYSTEM
NOTE 6
F13-XM-421 PORTABLE MILLS INCHING DRIVE
NOTE 6
F13-HU-413 MILL INCHING DRIVE HYDRAULIC POWER UNIT
NOTE 6

SI 13137A HH H L LL MASTER VSD SPEED
JI 13136A H MASTER VSD POWER
SI 13137B HH H L LL SLAVE VSD SPEED
JI 13136B H SLAVE VSD POWER
XA 13139 COMMON VSD FAULT
NOTE 4
f(x) JIC 13136

XIC 13135 H L
Volume
WIC 13135 HH H
Weight
HS 13135
f(x) PV
NOTE 3
WIC13121
2000-F13-PID-PR-10001
SIGNAL

ZI 13945 INCHING DRIVE BALL MILL PLACEMENT POSITION SWITCH
ZI 13944 INCHING DRIVE SAG MILL PLACEMENT POSITION SWITCH
XI 13759 INCHING DRIVE HPU MOTOR RUN FEEDBACK
XI 13743 INCHING DRIVE HPU PERMISSION
2

F13-CR-414 MILL LINER BOLT HAMMER 2 JIB HOIST 2
F13-CR-413 MILL LINER BOLT HAMMER 1 JIB HOIST 1
F13-CR-411 MILL LINER MAINTENANCE HOIST 1
F13-LH-401 SAG MILL LINER HANDLER
F13-LRT-401 MILL LINER BOLT HAMMER 1
F13-HU-411 MILL LINER BOLT HAMMER 1 POWER PACK

CCTV F13-CAM-002
F13-XM-406 SAG MILL FEED SPOUT
F13-MS-401 SAG MILL
SP SP-002 13 OFF
F13-SC-404 SAG MILL TROMMEL
F13-CH-468 SAG MILL FEED END CLEANOUT CHUTE
VENDOR PACKAGE 2000-ME001.2-D07-50002 & 2000-F13-PID-PR-10010
13-1273-FD-PE8-630

F13-CH-429 SAG MILL TROMMEL DISCHARGE SCREEN FEED CHUTE
MECH
SAG MILL DISCHARGE SCREEN 2000-F13-PID-PR-10002 SAG MILL SCATS

F13-CH-428 SAG MILL TROMMEL UNDERFLOW CHUTE
MECH
BALL MILL DISCHARGE LAUNDER 2000-F13-PID-PR-10002 SAG MILL DISCHARGE

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0123-PW-PE16-90
80VBFE1L2 F13-10177

PEBBLE BUNKER
2000-F13-PID-PR-10002
PEBBLES

MECH

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0122-PW-PE16-160
160x110

HIGH PRESSURE PROCESS WATER PUMPS
2000-F24-PID-PR-10019
HP PROCESS WATER

13-0142-PW-PE16-110

PE16 SS2
100VBFE1S2 F13-10180
13-0142-PW-SS2-100
100x65
F13-XM-585 MILL DISCHARGE AREA DRIVE-IN SUMP MONITOR NOTE 7
MILL DISCHARGE AREA DRIVE-IN SUMP

PE16 SS2
100VBFE1S2 F13-10181
13-0124-PW-SS2-100

LI 13130 HH H
LI 13130
LT 13130

200VKGD1L1 F13-10183
50VB03S1 F13-10184
SP MC-002
50VB03S1 F13-10182
SP MC-002
SP HS-003
SP HS-003
200x150
O/F
F13-PS-404 MILL DISCHARGE END SUMP PUMP

RL1 PE10
13-0034-FD-RL1-200

MILL FLOOR
F13-XM-478 MILL FEED DECK DRAIN

13-2507-FD-PE10-160
13-0028-FD-PE10-160
13-0038-FD-PE10-160
MSG3
PE10
13-2158-FD-PE10-110
110x63
13-2144-FD-MSG3-50
13-2145-FD-MSG3-50
13-2146-FD-MSG3-50
13-2147-FD-MSG3-50
13-1097-FD-PE10-160
13-2148-FD-MSG3-50
13-2149-FD-MSG3-50
13-2150-FD-MSG3-50
13-2151-FD-MSG3-50
MSG3 PE10
13-1096-FD-PE10-160
13-1095-FD-PE10-160
13-1093-FD-PE10-160
13-0047-FD-PE10-280

SP MC-002
SP MC-002
50VB03S1 F13-10185
50VB03S1 F13-10187
150VKGD1L1 F13-10186
150x100
LSH 13131
LAH 13131
NOTE 2
F13-PS-405 MILL FEED END SUMP PUMP
MILL FEED END DRIVE-IN SUMP

2°

13-0035-FD-PE10-225
PRIMARY CYCLONE FEED HOPPER 2000-F13-PID-PR-10002 SPILLAGE

13-2487-FD-RL1-150
RL1 PE10
13-0037-FD-PE10-160
BALL MILL DISCHARGE LAUNDER 2000-F13-PID-PR-10002 SPILLAGE

FLOTATION AREA SUMP PUMP 1
2000-F16-PID-PR-10001
OVERFLOW