

WO #S9315-13145

Estimate

Staging Heavy Duty - 9919

Customer: Darren Moore
Company: Aagate Landscaping
VIN: 1FDXE4FS0GDC42219
Date: Feb 11, 2026
Lead Technician: Joel Parker

Vehicle: 2016 Ford E-450
Unit: P1061
Mileage: 109680

	Name/Description	Actual/Estimate	Status
1	Diagnose - Engine oil leak Level 2 starting to become level 3 leak	0.00 / 2.00	Needs Approval
Labor	Joel Parker		
2	Replace - Mudflap anti sails Missing broken on axle 2	0.00 / 2.00	Needs Approval
Labor	Joel Parker		
Parts	(WS1) WELDING SUPPLIES	1	
	(CR1/2) COLD ROLLED ROUND BAR 1/2"	8	
3	Replace - Mudflap Driver side mudflap missing	0.00 / 0.75	Needs Approval
Labor	Joel Parker		
Parts	(SHHD1824) Mudflap, 18x24	2	

	Name/Description	Actual/Estimate	Status
4	Repair - Left front headlight Housing fastener and J-clip missing. Component secured with only three of four required fasteners.	0.00 / 1.00	Needs Approval
Labor	Joel Parker		
Parts	lower left headlight bezzle body bolt retainer	1	
	lower left headlight bezzle bolt	1	
5	Replace - Left side lower mirror glass cracked Damaged/cracked	0.00 / 1.00	Needs Approval
Labor	Joel Parker		
Parts	(9C2Z-17683-CA) D/S Mirror Assembly	1	
6	Replace - Air filter housing Cracking	0.00 / 1.00	Needs Approval
Labor	Joel Parker		
Parts	(GC2Z-9600-A) Air Cleaner Housing	1	

	Name/Description	Actual/Estimate	Status
7	Replace - All rear suspension bushings Component worn. Recommend replacing springs as well due to load weight to maintain proper support	0.00 / 5.00	Needs Approval
Labor	Joel Parker		
Parts	(DN-58) Deep Nut - 5/8"	8	
	(175-010) Washer - 5/8"	8	
	(8T5828) U-Bolt	4	
	(402.18) M18 Flat Washer	2	
	(369.018) M18 Coarse Stover Nut	2	
	(068.18.140) Hex Bolt, M18-2.5 X 140mm	2	
	(330-158) Leaf Spring Shackle Kit, Ford	2	
	(43-1791HD) Leaf Spring, HD	2	

Total Actual Time: 0.00

Total Estimated Time: 12.75

Printed: Sep 1, 2026 10:37 AM