

Heavy Duty - 9919

9919 Shepard Road SE
Calgary, Alberta
T2C 4M5
(403) 523 - 0488



Invoice: INV- S2-15522

Invoice date: **Jun 9, 2026** Paid date: **Jun 11, 2026**

ADDRESSES

BILL TO

Aagate Landscaping
65355 Sarah Bypass Suite 442
Heatherborough, Yukon Territory Y1S6C3

REMIT PAYMENT TO

**Foothills Group Inc c/o Interstate
Billing Service**
C/O T04220C PO Box 4220, STN A
Toronto, Ontario M5W 3B9
(403) 523 - 0488

ASSET	PLATE	MILEAGE	ENG HRS	VIN / SERIAL
2018 Ford F-550	SYG-1329	146,404	5,523	U7R0H2AYTHLW9DMUG

Customer PO **2018 Ford F-150**

Terms **Net 30**

WORK PERFORMED

01 Service - Perform LOF and inspection

SCOPE OF WORK

AZ: Changed engine oil and oil filter. Filled engine oil, started the unit, topped up oil level as required, and completed inspection. Job complete.

LABOR

Service - Perform LOF and inspection			\$224.93
--------------------------------------	--	--	----------

PARTS

Brake & Parts Cleaner	1	\$7.99	\$7.99
EP2 Grease Tube, 390G	1	\$11.50	\$11.50
Windshield Washer Fluid 4L	1	\$7.13	\$7.13
Engine Oil Filter, Ford 7.3L Gas	1	\$17.26	\$17.26
5W20 FULL SYNTHETIC 4.73L, GASOLINE ENGINE OIL	1	\$41.76	\$41.76
5W20 FULL SYNTHETIC 4.73L, GASOLINE ENGINE OIL	1	\$41.76	\$41.76

Line total **\$352.33**

02 Diagnose - No start Continued work order from S2-15468

SCOPE OF WORK

CW: Attempted to start unit again and it now starts no problem. Started and stopped unit multiple times with no issues and no warnings on dash. Scanned unit and it still has

fault codes for lost communication with ECM/PCM. Unit has a bad connection somewhere and suspect the moisture from the rain has gotten in causing unit to start now.

JL: Consulted previous diagnostics for no-start concern. Battery and starter replaced, unit was still exhibiting a no-start condition with faults for no communication with ECM. Continued diagnostics, verified unit starts with no issues. Scanned unit for fault codes. Found inactive faults in all modules for loss of communication with engine ECM - Fault code U0100:87. Consulted fault code diagnostics. Verified ECM connections are not corroded and are seating properly. Load tested ECM power and ground connections, verified ECM is receiving good power and ground. Inspected all ECM related fuses and relays, found no issues. Performed visual inspection of unit, added list of findings during inspection. Found no issues related to no-start condition. Cleared all faults from all modules, took unit on street and highway speed road test, found no drivability concerns. Suspect no-start condition has been repaired with previous battery and starter replacement.

LABOR

Diagnose - No start \$443.85

Line total **\$443.85**

03 Quality control check over QC

SCOPE OF WORK

TK: Performed quality control inspection. Job complete.

LABOR

Quality control check over

Line total **\$0.00**

04 Sublet - Tow Tow unit

SCOPE OF WORK

Sublet repair: Towed back to shop from Robert B. Somerville's yard. Job complete.

LABOR

Sublet - Tow \$74.98

PARTS

Tow	1	\$349.99	\$349.99
-----	---	----------	----------

Line total **\$424.97**

05 Monitor - Level 1 leak at transfer case rear output seal

SCOPE OF WORK

Client to monitor.

LABOR

Monitor - Level 1 leak at transfer case rear output seal

\$0.00

Line total **\$0.00**

SUMMARY

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Labor	\$743.76
Parts	\$477.39
Shop supplies	\$78.09
Subtotal	\$1,299.24
GST (5%)	\$64.97
Total	\$1,364.21
Payments	
Jun 11, 2026 - EFT	\$1,364.21

BALANCE

\$0.00

CUSTOMER SIGNATURE

PRINTED NAME

DATE