

## Staging Heavy Duty - 9919

9919 Shepard Road SE  
Calgary, Alberta, T2C 4M5  
(403) 523 - 0488



**Estimate: EST-S1-17520**

Invoice Date: Sep 11, 2026  
Due date: Oct 11, 2026

### Bill To

Havre Diesel Repair (IBS#: 852727)  
959 Moore Trafficway Apt. 471  
Kelseyberg, Yukon Territory, G5J8T9

### Remit payment to

Punta Gorda Truck Service & Repair  
057 Graham Crossroad  
Ryanfort, Yukon Territory, Y5E 2E2  
519-531-1194

| Unit          | VIN/Serial #      | Asset                     | Mileage     | Eng Hrs    |
|---------------|-------------------|---------------------------|-------------|------------|
| 68            | 8M5W3KR3WLJBG0W4B | 2011 Western Star<br>4900 | 635,095     | 27,630     |
| Service Order | Terms             | Due date                  | Customer PO | Authorizer |
| S1-17520      | Net 30            | Oct 11, 2026              |             |            |

| Description                                                                                                                                                                                                                                                                              | Quantity | Rate     | Amount   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|----------|
| <b>Service - CVIP inspection single or tandem axle</b>                                                                                                                                                                                                                                   |          |          |          |
| Labor Annual inspection<br>CM: CVIP inspection with wheels removed<br>measure shoes, drums, tire psi and tread depth<br>fail unit on efacity                                                                                                                                             |          |          | \$400.00 |
| Parts Total                                                                                                                                                                                                                                                                              |          |          | \$0.00   |
| Labor Total                                                                                                                                                                                                                                                                              |          |          | \$400.00 |
| Line Total                                                                                                                                                                                                                                                                               |          |          | \$400.00 |
| <b>Service - Wheels off single or tandem axle</b>                                                                                                                                                                                                                                        |          |          |          |
| Labor Annual inspection<br>MW: Removed wheels for inspection.Backed off steer<br>axle brakes to remove drum. Reinstalled wheels after<br>inspection, reset brake stroke on steer axle, lowered<br>truck and torqued wheels, placed torque tag inside<br>cab. Parked truck, job complete. |          |          | \$150.00 |
| Parts Total                                                                                                                                                                                                                                                                              |          |          | \$0.00   |
| Labor Total                                                                                                                                                                                                                                                                              |          |          | \$150.00 |
| Line Total                                                                                                                                                                                                                                                                               |          |          | \$150.00 |
| <b>Service - Boost</b>                                                                                                                                                                                                                                                                   |          |          |          |
| Labor Unit needed a boost<br>CM: Hook up battery charger and boost unit                                                                                                                                                                                                                  | 1        | \$149.95 | \$149.95 |
| Parts Total                                                                                                                                                                                                                                                                              |          |          | \$0.00   |
| Labor Total                                                                                                                                                                                                                                                                              |          |          | \$149.95 |
| Line Total                                                                                                                                                                                                                                                                               |          |          | \$149.95 |

Quality control check over

| Description                                                         | Quantity | Rate              | Amount   |
|---------------------------------------------------------------------|----------|-------------------|----------|
| Labor QC                                                            |          |                   |          |
|                                                                     |          | <b>Line Total</b> | \$0.00   |
| <b>Diagnose - HVAC controller</b>                                   |          |                   |          |
| Labor Not working - (Safety)                                        | 2        | \$149.95          | \$299.90 |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$299.90 |
|                                                                     |          | <b>Line Total</b> | \$299.90 |
| <b>Diagnose - Lower bunk lights</b>                                 |          |                   |          |
| Labor 1/2 out - 1 on left side and 1 on right side - (Safety)       | 2        | \$149.95          | \$299.90 |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$299.90 |
|                                                                     |          | <b>Line Total</b> | \$299.90 |
| <b>Diagnose - Head ache rack lights</b>                             |          |                   |          |
| Labor Multiple upper tail/brake lights more than 25% out - (Safety) | 2        | \$149.95          | \$299.90 |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$299.90 |
|                                                                     |          | <b>Line Total</b> | \$299.90 |
| <b>Replace - Hub cap</b>                                            |          |                   |          |
| Labor Leaking - axle 1 left - (Safety)                              | 0.5      | \$149.95          | \$74.98  |
| Parts hub cap                                                       | 1        | \$0.00            | \$0.00   |
| Parts hub cap gasket                                                | 1        | \$0.00            | \$0.00   |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$74.98  |
|                                                                     |          | <b>Line Total</b> | \$74.98  |
| <b>Diagnose-Air conditioning</b>                                    |          |                   |          |
| Labor Visible leak on firewall (non safety)                         | 2        | \$149.95          | \$299.90 |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$299.90 |
|                                                                     |          | <b>Line Total</b> | \$299.90 |
| <b>Diagnose - Audible air leak</b>                                  |          |                   |          |
| Labor Leak near firewall drivers side - (Safety)                    | 2        | \$149.95          | \$299.90 |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$299.90 |
|                                                                     |          | <b>Line Total</b> | \$299.90 |
| <b>Replace - Steer shaft u joint</b>                                |          |                   |          |
| Labor Loose - Lower u joint - (Safety)                              | 1.5      | \$149.95          | \$224.93 |
| Parts steer shaft u joint                                           | 1        | \$0.00            | \$0.00   |
|                                                                     |          | Parts Total       | \$0.00   |
|                                                                     |          | Labor Total       | \$224.93 |
|                                                                     |          | <b>Line Total</b> | \$224.93 |

| Description                                                                                              | Quantity | Rate              | Amount          |
|----------------------------------------------------------------------------------------------------------|----------|-------------------|-----------------|
| <b>Diagnose - Wheel bearings</b>                                                                         |          |                   |                 |
| Labor Loose - axle 1 both sides - (Safety)                                                               | 2        | \$149.95          | \$299.90        |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$299.90        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$299.90</b> |
| <b>Diagnose - Power steering leak</b>                                                                    |          |                   |                 |
| Labor Level 1 leak at the bottom of the reservoir - (Non-safety)                                         | 2        | \$149.95          | \$299.90        |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$299.90        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$299.90</b> |
| <b>Diagnose - Engine Oil leaks</b>                                                                       |          |                   |                 |
| Labor Level 2 engine oil leaks near oil pan, crankcase spinner, inject pass through seals - (Non-safety) | 2        | \$149.95          | \$299.90        |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$299.90        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$299.90</b> |
| <b>Replace - Glad hand seal</b>                                                                          |          |                   |                 |
| Labor Torn - (Safety)                                                                                    | 0.2      | \$149.95          | \$29.99         |
| Parts glad hand seal                                                                                     | 1        | \$0.00            | \$0.00          |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$29.99         |
|                                                                                                          |          | <b>Line Total</b> | <b>\$29.99</b>  |
| <b>Repair - Storage compartment door</b>                                                                 |          |                   |                 |
| Labor Does not open due to hitting exhaust-drivers side - (Non-safety)                                   | 1.5      | \$149.95          | \$224.93        |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$224.93        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$224.93</b> |
| <b>Replace - Brake shoes</b>                                                                             |          |                   |                 |
| Labor Cracked - axle 2 left - (Safety)                                                                   | 1.5      | \$149.95          | \$224.93        |
| Parts brake shoe kit                                                                                     | 1        | \$0.00            | \$0.00          |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$224.93        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$224.93</b> |
| <b>Replace - Shocks</b>                                                                                  |          |                   |                 |
| Labor Corroded - axle 2 left, axle 3 left - (Safety)                                                     | 1.5      | \$149.95          | \$224.93        |
| Parts shocks                                                                                             | 2        | \$0.00            | \$0.00          |
|                                                                                                          |          | Parts Total       | \$0.00          |
|                                                                                                          |          | Labor Total       | \$224.93        |
|                                                                                                          |          | <b>Line Total</b> | <b>\$224.93</b> |

| Description                                                           | Quantity | Rate              | Amount          |
|-----------------------------------------------------------------------|----------|-------------------|-----------------|
| <b>Replace - Dust shield</b>                                          |          |                   |                 |
| Labor Corroded - axle 3 right - (Non-safety)                          | 1        | \$149.95          | \$149.95        |
| Parts dust shield                                                     | 1        | \$0.00            | \$0.00          |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$149.95        |
|                                                                       |          | <b>Line Total</b> | <b>\$149.95</b> |
| <hr/>                                                                 |          |                   |                 |
| <b>Service - 5th wheel adjustment</b>                                 |          |                   |                 |
| Labor Out of adjustment                                               | 0.75     | \$149.95          | \$112.46        |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$112.46        |
|                                                                       |          | <b>Line Total</b> | <b>\$112.46</b> |
| <hr/>                                                                 |          |                   |                 |
| <b>Replace - Air tank drain cable</b>                                 |          |                   |                 |
| Labor Broken - (Non-safety)                                           | 0.5      | \$149.95          | \$74.98         |
| Parts air tank drain cable                                            | 1        | \$0.00            | \$0.00          |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$74.98         |
|                                                                       |          | <b>Line Total</b> | <b>\$74.98</b>  |
| <hr/>                                                                 |          |                   |                 |
| <b>Diagnose - Hydraulic oil leak</b>                                  |          |                   |                 |
| Labor Level 3 leaks near filter and bottom of tank - (Safety)         | 2        | \$149.95          | \$299.90        |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$299.90        |
|                                                                       |          | <b>Line Total</b> | <b>\$299.90</b> |
| <hr/>                                                                 |          |                   |                 |
| <b>Replace - Exhaust clamps</b>                                       |          |                   |                 |
| Labor Broken - Vband clamp and mounting clamp under cab<br>- (Safety) | 1.5      | \$149.95          | \$224.93        |
| Parts v-band clamp at bellows under cab                               | 1        | \$0.00            | \$0.00          |
| Parts bellows mounting clamp                                          | 1        | \$0.00            | \$0.00          |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$224.93        |
|                                                                       |          | <b>Line Total</b> | <b>\$224.93</b> |
| <hr/>                                                                 |          |                   |                 |
| <b>Repair - Positive jump start stud</b>                              |          |                   |                 |
| Labor Corroded - (Non-safety)                                         | 0.5      | \$149.95          | \$74.98         |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$74.98         |
|                                                                       |          | <b>Line Total</b> | <b>\$74.98</b>  |
| <hr/>                                                                 |          |                   |                 |
| <b>Repair - Caging bolt</b>                                           |          |                   |                 |
| Labor Loose - axle 3 right - (Safety)                                 | 0.5      | \$149.95          | \$74.98         |
|                                                                       |          | Parts Total       | \$0.00          |
|                                                                       |          | Labor Total       | \$74.98         |
|                                                                       |          | <b>Line Total</b> | <b>\$74.98</b>  |
| <hr/>                                                                 |          |                   |                 |

|                      |            |
|----------------------|------------|
| <b>Labor</b>         | \$5,116.02 |
| <b>Parts</b>         | \$0.00     |
| <b>Shop supplies</b> | \$350.00   |
| <b>Subtotal</b>      | \$5,466.02 |
| <b>GST (5%)</b>      | \$273.37   |
| <b>Total</b>         | \$5,739.39 |
| Payments             |            |
| Balance              | \$5,739.39 |

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

**Customer signature:** \_\_\_\_\_

**Printed name:** \_\_\_\_\_ **Date:** \_\_\_\_\_