

Staging Heavy Duty - 9919

9919 Shepard Road SE
Calgary, Alberta, T2C 4M5
(403) 523 - 0488



Invoice: INV-S99999-16518

Invoice Date: Sep 12, 2026
Due date: Nov 11, 2026

Bill To

Monroe Truck Service & Repair
938 Zachary Lodge Apt. 430
East Nancy, Manitoba, M7A 1T5

Remit payment to

Staging Heavy Duty - 9919
9919 Shepard Road SE
Calgary, Alberta, T2C 4M5
(403) 523 - 0488

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
H9725	CPVNUEG53WP5MMV75	1998 Ford Lt9513	407,185	16,408

Service Order	Terms	Due date	Customer PO	Authorizer
S99999-16518	Net 60	Nov 11, 2026		

Description	Quantity	Rate	Amount
Service - Travel to ogden yard to inspect other jet			
Labor for parts			
Gear reduction box failure			
Starting kilometers: 84,529 kms			
Ending kilometers: 84,539 kms			
TK: Travel to location and get info and inspect and travel back to shop.	1.84	\$145.00	\$266.80
		Parts Total	\$0.00
		Labor Total	\$266.80
		Line Total	\$266.80
Service - Inspect truck for travel in Canmore			
Labor Preventative			
TK: Performed a pre-trip inspection and found the brakes applied and the batteries discharged. Charged the batteries, built air pressure to release the brakes, and verified they were operating correctly. Checked the engine oil level.			
Found the unit stuck in ruts where it was parked. Towed the unit free and completed final checks to prepare it for travel. Job complete.	2	\$145.00	\$290.00
		Parts Total	\$0.00
		Labor Total	\$290.00
		Line Total	\$290.00
Service - CVIP inspection single or tandem axle			
Labor Annual inspection			
Tk: attempted cvip unit is dead with no power			
			\$400.00

Description	Quantity	Rate	Amount
CM: CVIP inspection. Limited inspection "C" with wheels on measure shoes, push rod travel, tire psi and tread depth Fail unit on efacity			
		Parts Total	\$0.00
		Labor Total	\$400.00
		Line Total	\$400.00
Service - Boost unit			
Labor CM: Hook up battery charger and boost unit.	1.96	\$145.00	\$284.20
		Parts Total	\$0.00
		Labor Total	\$284.20
		Line Total	\$284.20
Service - Wheels off trailer tri-axle			
Labor Annual inspection MW: Attempted to move a CP truck to make room, truck would not start. Had to move truck into another bay. Once other truck was out of bay, raised truck onto jackstands for inspection.			\$150.00
		Parts Total	\$0.00
		Labor Total	\$150.00
		Line Total	\$150.00
Service - Perform LOF and inspection			
Labor MW: Drained engine, drain plug, lube filter was very tight, no oil on seal. Checked fluid levels, greased chassis. Job complete.	1.5	\$145.00	\$217.50
Parts BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
Parts HDEO14 - 15W40 Bulk- Mobil 1 Delvac HDEO	30	\$7.11	\$213.30
Parts GREASETUBE - EP2 Grease Tube, 390G	1	\$11.50	\$11.50
Parts WWF - Windshield Washer Fluid 4L	1	\$7.09	\$7.09
Parts LF3973 - Engine Oil Filter, Caterpillar/Mack	1	\$29.15	\$29.15
		Parts Total	\$269.03
		Labor Total	\$217.50
		Line Total	\$486.53
Service - Air filter			
Labor MW: Removed and replaced engine air filter, applied service sticker, job complete.	0.5	\$145.00	\$72.50
Parts 46664 - Primary Engine Air Filter	1	\$151.16	\$151.16
Parts 46665 - Secondary Engine Air Filter	1	\$99.94	\$99.94
		Parts Total	\$251.10
		Labor Total	\$72.50
		Line Total	\$323.60
Service - Replace fuel filters			
Labor	0.8	\$145.00	\$116.00

Description		Quantity	Rate	Amount
MW: Removed and replaced fuel filters. Checked for leaks, job complete.				
After completing fuel filters on time, 3rd fuel filter was given after inspection was complete. Last filter was extremely stuck, tried multiple ratchets, each longer than the last. Had to use pipe wrench with 4 foot snipe with strap wrench. Changed filters, replaced hardened o-ring, required to pick apart o ring as it fell apart in pieces during removal. Started engine and tested for leaks. Job complete.				
Parts	FS1000 - Fuel/Water Separator	1	\$36.02	\$36.02
Parts	FF5320 - Fuel Filter, Caterpillar	1	\$20.52	\$20.52
Parts	9M-2341 - Fuel Filter (P552341, 9M2341, FF234, 33941)	1	\$27.12	\$27.12
Parts	8H-2778 - O-Ring Seal	1	\$9.99	\$9.99
			Parts Total	\$93.65
			Labor Total	\$116.00
			Line Total	\$209.65

Diagnose - Jet no start

Labor	Not starting			
TK: Inspected unit and removed fan cover. Washed all oil and grime from around gear reduction box. Removed and flow tested PTO; PTO is putting out desired pressure. Removed and inspected splines on PTO and gear reduction box; all splines appear okay. While operating, fan will not engage and grinding can be clearly heard inside gear reduction box. Unit will need gear reduction box replaced.				
Inspect unit and operate unit found gear box functional		3.5	\$145.00	\$507.50
			Parts Total	\$0.00
			Labor Total	\$507.50
			Line Total	\$507.50

Diagnose - Wipers

Labor	Not parking - (Safety)			
This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY				
		2	\$145.00	\$290.00
			Parts Total	\$0.00
			Labor Total	\$290.00
			Line Total	\$290.00

Diagnose - HVAC system

Labor	No air flow to floor - (Safety)			
This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY				
		2	\$145.00	\$290.00
			Parts Total	\$0.00
			Labor Total	\$290.00

Description		Quantity	Rate	Amount
			Line Total	\$290.00
Diagnose - Engine oil leaks				
Labor	Level 2 leaks - (Non-safety)			
	This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY This is the tECH sTORY	2	\$145.00	\$290.00
			Parts Total	\$0.00
			Labor Total	\$290.00
			Line Total	\$290.00
Diagnose - Hydraulic oil leak				
Labor	Level 3 leak at shut off taps - (Safety)	2	\$149.95	\$299.90
			Parts Total	\$0.00
			Labor Total	\$299.90
			Line Total	\$299.90
Diagnose - Hydraulic oil leak				
Labor	Level 2 leak near filter - (Non-safety)	2	\$145.00	\$290.00
			Parts Total	\$0.00
			Labor Total	\$290.00
			Line Total	\$290.00
Diagnose - Wheel locked up				
Labor	Axle 1 left will not spin - (Safety)	2	\$145.00	\$290.00
			Parts Total	\$0.00
			Labor Total	\$290.00
			Line Total	\$290.00
Diagnose - Brake adjustment				
Labor	Uneven stroke - axle 1 - (Safety)	1	\$145.00	\$145.00
			Parts Total	\$0.00
			Labor Total	\$145.00
			Line Total	\$145.00
Diagnose - Brake adjustment				
Labor	Uneven stroke- axle 2 - (Safety)	1	\$145.00	\$145.00
			Parts Total	\$0.00
			Labor Total	\$145.00
			Line Total	\$145.00
Diagnose - Brake adjustment				
Labor	Uneven stroke- axle 3 - (Safety)	1	\$145.00	\$145.00
			Parts Total	\$0.00
			Labor Total	\$145.00
			Line Total	\$145.00
Diagnose - Front pole lights				
Labor	Left side broken - right side not working - (Safety)	1	\$145.00	\$145.00
			Parts Total	\$0.00

[illegible]

Description	Quantity	Rate	Amount
		Parts Total	\$0.00
		Labor Total	\$0.00
		Line Total	\$0.00
		Labor	\$4,924.40
		Parts	\$613.78
		Shop supplies	\$75.00
		Subtotal	\$5,613.18
		GST (5%)	\$280.70
		Total	\$5,893.88
		Payments	
		Balance	\$5,893.88

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer signature: _____

Printed name: _____ Date: _____