The South Fork Trail

Segment 4: Peachtree Bar (East)

Report Date: June 13, 2022.

Trail Stats -- Mileage: 3.3 miles; Elevation Gain/Loss: 625 feet. 2,735' (top), 2,110' (bottom).

Status: https://www.google.com/maps/d/viewer?mid=1cK-eXqe6|X6YY26 JrNhdLB370vl92aL&ll=37.60174944115586%2C-119.79676961792443&z=12

Overall Goal -- To repair and maintain the segment for non-motorized users (hikers, runners equestrians and backpackers).





Project History -

The section of trail between Devil's Gulch and the South Fork of the Merced was scouted in 2014 and 2015; no work has occurred on this trail segment.


Past Activities --

Except where noted, all categories are described as "number of."

| YEAR | OUTINGS | VOL- HOURS | TREES CLEARED | TREAD REPAIR (ft) | ROCKWORK | BRUSH REMOVED | CAMPSITE IMPROVE |
|------|---------|---------------|------------------|----------------------|-------------|------------------|---------------------|
| 0014 | | | | (, | | | |
| 2014 | 1 | 8 | | | survey work | | |
| 2015 | 1 | 32 | | | survey work | | |
| | | | | | | | |
| | | | | | | | |

Future Objectives –

- 1. Buck fallen trees from trail (estimate of 8)
- 2. Remove brush and saplings encroaching onto trail by: (1) extract buck-brush, poison oak and deer-brush by roots (8 hrs labor); and, (2) clipping back brush (4 hrs labor)
- 3. Repair trail tread (2.8 miles)
- 4. Install trail information sign at Peachtree Bar.



SOUTH FORK TRAIL- SEGMENT 4: Peachtree Bar (east)

