Haas VF-4 — Operator & Maintenance Manual (sample excerpt)

Sample placeholder created for the demo tenant. It is not an OEM document.

Daily: check way lube and coolant levels; clear chips from enclosure.

Quarterly: inspect spindle drawbar force; grease axis ball screws per schedule.