Servo controller signal level shifterr



Power Supply



The external smps must be at least 15V.
The -10V rail must be at least -5V for the op-amp to be able to output 0V.

Dsub connectors



Microcontroller



Xbox Wheel Side



Active Low SPI address = 010